

1999 Dam Safety Inspection Reports

**PUB 1.2
Attachment I**

Port Union Development

NEWFOUNDLAND POWER

April 26, 2000


Memo From: J. P. Halliday
To: M. C. Hunter
Subject: 1999 Dam Safety Inspection Reports
Port Union Development
File: 401.01.03.29.01


Attached are the Dam Safety Inspection reports for structures located in the Port Union Development. Several structures in this development have been rehabilitated in recent years and should operate safely with minor repairs and maintenance.

Halfway Pond Dam, however, remains in poor condition, with continued erosion along the upstream slope and crest. This reservoir should continue to operate at low levels until repairs are carried out to this structure.

The outlet structure at Well's Pond is also in poor condition, with the gate left fully open to maintain low water levels. This practice should continue until a decision is made on the status of this structure.

Attach:



PROVINCE OF NEWFOUNDLAND	
	PERMIT HOLDER
	This Permit Allows
NEWFOUNDLAND POWER INC.	
To practice Professional Engineering in Newfoundland and Labrador. <u>Joe BB</u> Permit No. as issued by APEGN <u>Joe BB</u> which is valid for the year <u>2000</u>	

DAM SAFETY INSPECTION

Whirl Pond Dam & Outlet

Dam Type: Timber Cribwork

Date & Time of Examination: 1999-11-30 @ 12:00 pm

Operational Status at Time of Examination:

Reservoir Water surface elevation	<u>2' below FSL</u>
Releases	<u>Gate open ~ 12"</u>
Weather Conditions	<u>Cloudy 0°C</u>
Water in storage	<u></u>
Recent Seismic Events	<u>None</u>

Examining Party
G. Humby
P. Halliday
D. Laing

INSPECTION CHECKLIST FOR TIMBER-CRIB DAM

WHIRL POND TIMBER-CRIB DAM

Structure

Timber structural members	<u>Good</u>
Timber planking	<u>Good, few rotten planks along walkway need to be replaced.</u>
Crib Content	<u>Good, some ballast missing from crib work at outlet.</u>

Upstream Face

Alignment	<u>Good, timbers in upstream face in fair condition.</u>
Seepage on Downstream Face	<u>Minor seepage on left side probably through timber facing. Flow \approx 0.5gal/min</u>
Downstream toe settlement	<u>None observed</u>

Crest

Surface cracking	<u>None observed</u>
Settlement	<u>None observed</u>

Abutments

Seepage	<u>None observed</u>
---------	----------------------

Remarks: Fill placed on downstream slope for access to outlet makes inspection difficult.

WHIRL POND OUTLET

OUTLET WORKS

Intake

Trashrack	<u>Fish Screen – Good, new screens installed in 1999.</u>
-----------	---

Concrete	<u>N/A</u>
----------	------------

Outlet Conduit

Metal work	<u>N/A</u>
------------	------------

Penstock	<u>N/A</u>
----------	------------

Control Facilities

Gatehouse	<u>N/A</u>
-----------	------------

Crane	<u>N/A</u>
-------	------------

Gate and controls (description)	<u>Mechanical lift</u>
---------------------------------	------------------------

General condition	<u>Good</u>
-------------------	-------------

Operation at time of examination	<u>Open</u>
----------------------------------	-------------

Control System Mechanical items	<u>Good</u>
---------------------------------	-------------

Ventilation	<u>N/A</u>
-------------	------------

Lighting	<u>N/A</u>
----------	------------

Stop logs	
-----------	--

General condition	<u>N/A</u>
-------------------	------------

Seals	<u>N/A</u>
-------	------------

Chute

Debris	<u>None observed</u>
--------	----------------------

Walls	
-------	--

Movement (offsets)	<u>None observed</u>
--------------------	----------------------

Settlement	<u>None observed</u>
------------	----------------------

Joints	<u>Good</u>
Cracks or areas of distress	<u>None observed</u>
Condition of backfill	<u>N/A</u>

Floor


Movement	<u>Not visible</u>
Settlement	_____
Joints	_____
Drains	_____
Cracks	_____
Drains	_____
Amount of flow	_____
Location of seeping drains	_____

Stilling Basin(observed operation)

Debris in basin	<u>None observed</u>
Walls	<u>Rock walls good</u>
Movement (offsets)	_____
Settlement	_____
Joints	_____
Cracks or areas of distress	_____
Floor (if visible)	<u>Not visible</u>
Cracks or areas of distress	_____
Movement	_____
Joints	_____
Erosion	_____
Outlet Channel	
Slope protection	<u>Good</u>
Stability of side slopes	<u>Good</u>
Vegetation or other	
Obstructions	<u>Good</u>

Remarks: Generally in good condition except for few minor leaks. Gate appeared to be in good condition.

Development: Port Union
Structure: Whirl Pond Dam and Outlet



Timber on upstream face



Outlet from downstream

Development: Port Union
Structure: Whirl Pond Dam and Outlet



Outlet – Left abutment from downstream




Ballast missing from crib work

Development: Port Union
Structure: Whirl Pond Dam and Outlet



Fishscreen



Outlet gate from upstream

Development: Port Union
Structure: Whirl Pond Dam and Outlet



Looking toward left abutment

DAM SAFETY INSPECTION

Whirl Pond Spillway

Dam Type: Concrete

Date & Time of Examination: 1999-11-30 @ 12:00 pm

Operational Status at Time of Examination:

Reservoir Water surface elevation ≈ 2' below spill

Releases N/A

Weather Conditions Cloudy 0°C

Water in storage

Recent Seismic Events None

Examining Party
G. Humby
P. Halliday
D. Laing

INSPECTION CHECKLIST FOR CONCRETE DAM

DAM

Upstream Face

Cracks	<u>None observed, structure rebuilt in 1999</u>
Joint Offsets	<u>None observed</u>

Downstream Face

Cracks	<u>None observed</u>
Joint Offsets	<u>None observed</u>
Seepage on downstream face	<u>Some leakage through the foundation of the structure. Flow \approx 4-5 gal/min.</u>

Downstream Toe

Cracks	<u>None observed</u>
Undercutting(from erosion)	<u>None observed</u>

Crest

Roadway	<u>N/A</u>
Walks	<u>N/A</u>
Parapet Wall	<u>Good condition</u>
Lighting, etc.	<u>N/A</u>

ABUTMENTS

Foundation at Downstream Toe of Dam

Seepage around dam	
Location	<u>Some leakage through foundation</u>
Amount	<u>4-5 gal/min</u>
Measurement Methods	<u>Visible</u>

Remarks: Structure rebuilt in 1999 with new concrete cut off wall, upstream and downstream rip-rap, and concrete fish ladder. Overall, new structure in good condition.

Development: Port Union
Structure: Whirl Pond Dam and Spillway



Old freeboard dam



View from left abutment

Development: Port Union
Structure: Whirl Pond Spillway



New fish ladder(constructed in 1999)



View along crest