

# **1997 Dam Safety Inspection Lockston Development**

**PUB 3.2  
Attachment C**

# NEWFOUNDLAND POWER

1997 11 03

Memorandum From: J.P. Halliday

To: J.L. Simmons

Subject: 1997 Dam Safety Inspections  
Lockston Development

File: ENS-0790.30

---


Please find attached the 1997 Dam Safety Inspection Reports for structures located within the Lockston Development. Structures in this development are in generally good condition and should operate safely with general maintenance and minor capital improvements.

Some of the important items noted in the report which will require attention include deteriorated concrete, especially along sections of the power canal, and significant leakage from the penstock.

Since the last inspection during 1995, Trinity Pond Dam and Lockston Intake have been reconstructed and a diversion dam and canal have been built at Copeley's Pond. These structures are all in good condition.

SH/dje

Enclosure

A handwritten signature in black ink, appearing to read "J.P. Halliday", is written over the "Enclosure" text.

# DAM SAFETY INSPECTION

Copeley's Pond Dam

Dam Type: Earthfill Dam

Date & Time of Examination: 97-06-13, 9:00 AM

Operational Status at Time of Examination:

Reservoir Water surface elevation \_\_\_\_\_

Releases N/A

Weather Conditions Overcast 12°C

Water in storage \_\_\_\_\_

Recent Seismic Events \_\_\_\_\_

Examining Party

S. Hancock

I. Kerr

DAM	
<b>Upstream Face</b>	
Slide movements	<u>None Observed</u>
Slope protection	<u>Adequate</u>
Erosion - beaching	<u>None observed</u>
Cracks	<u>None observed</u>
Sinkholes	<u>None observed</u>
Settlement	<u>None observed</u>
Displacement	<u>None Observed</u>
Debris	<u>None observed</u>
Unusual conditions	<u>None Observed</u>

Slide movements	<u>None Observed</u>
Signs of movements	<u>None Observed</u>
Cracks	<u>None Observed</u>
Seepage or wet areas	<u>Pond along downstream toe</u>
Unusual conditions	

Seepage	<u>None Observed</u>
Cracks, joints, and bedding planes	<u>None Observed</u>

Slides

None Observed


Signs of movement

None Observed


Remarks: Structure is adequate for its function (i.e. divert water into canal). Dam consists of old railway bed with timber culverts removed and backfilled to prevent free flow of water. Structure probably built on bog (resulting in pervious foundation). Flow through foundation varies depending on water elevation in Copeley's Pond.

**LOCKSTON DEVELOPMENT  
COPELEY'S POND DAM**

**97-06-13**




**CREST OF STRUCTURE WHERE LARGE BOX CULVERT WAS REMOVED.**




**UPSTREAM SLOPE WHERE LARGE BOX CULVERT WAS REMOVED**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND DAM**

**97-06-13**



**DOWNSTREAM SLOPE WHERE LARGE BOX CULVERT WAS REMOVED.**



**UPSTREAM SLOPE WHERE SMALL TIMBER BOX CULVERT WAS REMOVED.**

## DAM SAFETY INSPECTION

Copeley's Pond Canal

Dam Type: Channel

Date & Time of Examination: 97-06-13 (09:30 AM)

### Operational Status at Time of Examination:

Reservoir Water surface elevation N/A

Releases

Weather Conditions Rain

Water in storage

Recent Seismic Events

Examining Party

I. Kerr

S. Hancock



## CANAL

### Approach Channel

Debris None Observed

Channel side slope stability Good

### Invert

Debris Some evidence of beavers. Gauge should be installed at entrance to canal to ensure invert elevation remains at design elevation and canal is not blocked by mud and debris.

### Channel

Slope Protection None

Stability of side slopes Bog has fallen into canal in several areas near upstream end.

Vegetation or other obstructions Some logs and debris in brook in several locations.

Remarks: Good flow in canal. River diverts and is very swampy just upstream of highway. Operations staff should check canal regularly, especially at upstream end, to ensure water is flowing into canal. As indicated in this section on Copeley's Pond Dam, the railway bed foundation is pervious and if the canal entrance is partially blocked it could raise the elevation of Copeley's Pond possibly resulting in increased flow through the railway bed foundation and out of the system.

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**INLET TO CANAL LOOKING UPSTREAM**



**ENTRANCE TO CANAL LOOKING DOWNSTREAM. THIS AREA SHOULD BE  
INSPECTED AND CLEARED AS NECESSARY.**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**997-06-13**



**AREA WHERE BOG HAS FALLEN INTO CANAL**




**LOOKING DOWNSTREAM. NOTE BOG HAS FALLEN INTO STREAM**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**LOOKING DOWNSTREAM**




**LOOKING DOWNSTREAM AT START OF WOODED AREA.**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**LOOKING UPSTREAM AT START OF WOODED AREA**




**LOOKING DOWNSTREAM**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**




**LOOKING UPSTREAM. NOTE STEEPER SLOPE OF STREAM.**



**LOOKING DOWNSTREAM. NOTE BROKEN TREE BRANCHES IN STREAM.**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**NOTE DEBRIS IN STREAM**




**TYPICAL CANAL SECTION**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**TYPICAL CANAL SECTION**




**STREAM SECTION JUST UPSTREAM OF HIGHWAY.**




**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**




**CANAL EMBANKMENT JUST UPSTREAM OF HIGHWAY.**



**NEW CULVERT IN HIGHWAY**

**LOCKSTON DEVELOPMENT  
COPELEY'S POND CANAL**

**1997-06-13**



**STREAM SECTION JUST DOWNSTREAM OF HIGHWAY**

## DAM SAFETY INSPECTION

### Trinity Pond Dam and Outlet

Dam Type: Concrete

Date & Time of Examination: 97-06-13 (10:20 AM)

#### Operational Status at Time of Examination:

Reservoir Water surface elevation 11.0'

Releases Gate open

Weather Conditions Overcast

Water in storage

Recent Seismic Events

#### Examining Party

I. Kerr

S. Hancock

## INSPECTION CHECKLIST FOR CONCRETE DAM

### Upstream Face

Cracks None Observed

Joint Offsets N/A

### Downstream Face

Cracks None Observed

Joint Offsets N/A

Seepage on Downstream Face None Observed

### Downstream Toe

Cracks Gate open - not visible

Undercutting from erosion Gate open - not visible

### Crest

Roadway N/A

Walks Good

Parapet Wall Handrail low

Lighting, etc. N/A

## ABUTMENTS

### Foundation at Downstream Toe of Dam

#### Seepage around dam

Location None Observed


Amount None Observed

Measurement methods                     


Remarks: Dam recently reconstructed. In excellent condition.

**LOCKSTON DEVELOPMENT  
TRINITY POND DAM**

**1997-06-13**




**GENERAL VIEW FROM UPSTREAM**



**VIEW FROM RIGHT ABUTMENT**

**LOCKSTON DEVELOPMENT  
TRINITY POND DAM**

**1997-06-13**



**GATE LIFT AND STEM ON UPSTREAM FACE**



**DOWNSTREAM FACE OF DAM**

## DAM SAFETY INSPECTION

### Rattling Pond Spillway

Dam Type: Concrete

Date & Time of Examination: 97-06-13 (10:45 AM)

#### Operational Status at Time of Examination:

Reservoir Water surface elevation \_\_\_\_\_

Releases \_\_\_\_\_

Weather Conditions Showers

Water in storage \_\_\_\_\_

Recent Seismic Events \_\_\_\_\_

#### Examining Party

I. Kerr

S. Hancock



## INSPECTION CHECKLIST FOR CONCRETE DAM

### Upstream Face

Cracks

Good - minor hairline cracks

Joint Offsets

Expansion joints sealed with cement grout

### Downstream Face

Cracks

Good - minor hairline cracks

Joint Offsets

Expansion joints sealed with cement grout.

### Seepage on Downstream Face

None Observed

### Downstream Toe

Cracks

\_\_\_\_\_

Undercutting from erosion

Prevalent along much of toe

### Crest

Roadway

N/A

Walks

N/A

Parapet Wall

N/A

Lighting, etc.

N/A

## ABUTMENTS

### Foundation at Downstream Toe of Dam

#### Seepage around dam

Location	<u>Through rock on right abutment in highly fractured rock.</u>
Amount	<u>Not measured</u>
Measurement methods	<u>N/A</u>

Remarks: Erosion at toe and seepage through abutment should be monitored until repairs are completed.

## SPILLWAY

### Approach Channel

Debris	<u>None Observed</u>
Slides above channel	<u>None Observed</u>
Channel side slope stability	<u>Good, some fractured rock at right abutment.</u>
Log boom	<u>N/A</u>
Slope Protection	<u>N/A</u>

### Control structures (Observed Operation)

#### Crest

Cracks or areas of distress	<u>N/A</u>
Signs of movement	<u></u>


#### Walls

Movement (offsets)	<u>N/A</u>
Cracks or areas of distress	<u></u>
Settlement	<u></u>
Joints	<u></u>
Drains	<u></u>
Backfill	<u></u>


Apron	
Movement	_____
Settlement	_____
Joints	_____
Cracks	_____
Walkway	
Condition of piers	_____
Condition of decking and beams	_____
Condition of rails	_____
Chute	
Debris	<u>N/A</u>
Walls	
Movement (offsets)	<u>N/A</u>
Settlement	_____
Joints	_____
Cracks or areas of distress	_____
Floor	
Movement	<u>N/A</u>
Settlement	_____
Joints	_____
Cracks	_____
Drains	_____
Amount of flow	_____
Location of seepage drain	_____
Stilling Basin (Observed Operation)	
Debris in basin	<u>Some driftwood</u>
Walls	
Movement (offsets)	<u>N/A</u>
Settlement	_____
Joints	_____
Cracks or areas of distress	_____
Floor (if visible)	<u>Small rock along toe could be displaced by significant flood.</u>
Cracks or areas of distress	_____
Movement	_____
Joints	_____
Erosion	_____
Outlet Channel	
Slope Protection	<u>N/A</u>
Stability of side slopes	<u>Good, except at right abutment</u>
Vegetation or other obstructions	<u>OK</u>

**LOCKSTON DEVELOPMENT  
RATTLING POND SPILLWAY**

**1997-06-13**




**GENERAL VIEW OF STRUCTURE. NOTE GROUTED JOINTS**




**DOWNSTREAM SLOPE OF SPILLWAY**

**LOCKSTON DEVELOPMENT  
RATTLING POND SPILLWAY**

**1997-06-13**



**UNDERCUTTING ALONG TOE OF SPILLWAY**



**RIGHT ABUTMENT WHERE WATER IS LEAKING THROUGH ROCK**

## DAM SAFETY INSPECTION

Rattling Pond Dam, Outlet, and Sluice gate

Dam Type: Concrete

Date & Time of Examination: 97-06-13 (10:50 AM)

Operational Status at Time of Examination:

Reservoir Water surface elevation 100mm below top of dam

Releases Outlet gate open

Weather Conditions Showers

Water in storage \_\_\_\_\_

Recent Seismic Events \_\_\_\_\_

Examining Party

I. Kerr

S. Hancock

## INSPECTION CHECKLIST FOR CONCRETE DAM

### Upstream Face

Cracks

Face recently repaired. Good condition  
except some honey combing

Joint Offsets

Good

### Downstream Face

Cracks

Worst areas were recently patched.  
Minor cracking and leaching

Joint Offsets

Good

### Seepage on Downstream Face

None Observed

### Downstream Toe

Cracks

None Observed

Undercutting from erosion

None Observed

### Crest

Roadway

N/A

Walks

N/A

Parapet Wall

Good

Lighting, etc.

N/A

## ABUTMENTS

### Foundation at Downstream Toe of Dam

#### Seepage around dam

Location

None Observed

Amount

\_\_\_\_\_

Measurement methods


\_\_\_\_\_

Remarks: Freeboard varies by 70mm. Should be checked. Gate in outlet and sluice appear to be in relatively good condition.




**LOCKSTON DEVELOPMENT  
RATTLING POND DAM**

**1997-06-13**




**GENERAL VIEW OF DAM. SLUICE GATE IN FOREGROUND**




**UPSTREAM FACE. NOTE NEW CONCRETE**

**LOCKSTON DEVELOPMENT  
RATTLING POND DAM**

**1997-06-13**



**DOWNSTREAM FACE. NOTE GROUT PATCHES. SLUICeway ON LEFT.**



**OUTLET GATE STRUCTURE**

## DAM SAFETY INSPECTION

Lockston Canal, Intake and Penstock

Dam Type: Concrete

Date & Time of Examination: 97-06-13 (11:15 AM)

Operational Status at Time of Examination:

Reservoir Water surface elevation near FSL

Releases

Weather Conditions Rain

Water in storage

Recent Seismic Events

Examining Party

I. Kerr

S. Hancock

# INSPECTION CHECKLIST FOR CONCRETE DAM

## Upstream Face

Cracks

Good near intake, but poor along several sections of canal.

Joint Offsets

Good

## Downstream Face

Cracks

Just replaced near intake, but poor condition in several sections along canal.

Joint Offsets

Good

## Seepage on Downstream Face

Three significant leaks in canal were noted (likely others deeper down) with estimated flow of 100 litres/minute. Two small leaks in repaired section were noted (near sluice and on left side of intake) approximate flow is 2-4 litres/minute

## Downstream Toe

Cracks

Rockfill in place. Not visible.

Undercutting from erosion

N/A

## Crest

Roadway

N/A

Walks

N/A

Parapet Wall

Repaired near intake. Poor condition in some areas along canal.

Lighting, etc.

N/A

## ABUTMENTS

### Foundation at Downstream Toe of Dam

#### Seepage around Dam

Location None Observed

Amount \_\_\_\_\_

Measurement methods \_\_\_\_\_

Remarks: Concrete along much of canal in poor condition with several significant leaks. Should be dewatered and inspected to determine the extent of repairs required. (Note - it is not good practice to frequently dewater the canal due to the poor condition of the old concrete along the canal. When dewatered, the concrete wall must act as a retaining wall to support the rockfill on the upstream side. The deteriorated concrete may not be adequate to resist this force and it is possible that a section of the wall could fail while dewatered and fall into the empty canal).

## OUTLET WORKS

### Intake

Trashrack Not inspected

Concrete Recently replaced. Good condition except minor honey combing

### Outlet Conduit

Metal work \_\_\_\_\_

Penstock See next section

### Control Facilities

Gatehouse Needs paint

Crane	<u>Good</u>
Gate and controls (description)	<u></u>
General condition	<u>Good</u>
Operation at time of examination	<u>Open</u>
Control System Mechanical items	<u>Good</u>
Ventilation	<u>Good</u>
Lighting	<u>Good</u>
Stop logs	
General condition	<u>N/A</u>
Seals	<u>N/A</u>

#### Chute

Debris	<u>N/A</u>
Walls	
Movement (offsets)	<u></u>
Settlement	<u></u>
Joints	<u></u>
Cracks or areas of distress	<u></u>
Condition of backfill	<u></u>
Floor	
Movement	<u>N/A</u>
Settlement	<u></u>
Joints	<u></u>
Cracks	<u></u>
Drains	<u></u>
Amount of Flow	<u></u>
Location of seeping drain	<u></u>
Stilling Basin (Observed Operation)	
Debris in basin	<u></u>

## Walls

Movement (offsets)

\_\_\_\_\_

Settlement

\_\_\_\_\_

Joints

\_\_\_\_\_

Cracks or areas of distress

\_\_\_\_\_

Condition of backfill

\_\_\_\_\_

## Floor (if visible)

Cracks or areas of distress

\_\_\_\_\_

Movement

\_\_\_\_\_

Joints

\_\_\_\_\_

Erosion

\_\_\_\_\_

## Outlet Channel

Slope Protection

N/A

Stability of side slopes

\_\_\_\_\_

Vegetation or other obstructions

\_\_\_\_\_

Remarks: Concrete rebuilt last year and is in good condition.

## PENSTOCK

### Right of way

Vegetation

Brush cut but left along side Penstock

Drainage ditches

Fair

Culverts

N/A

### Condition of Penstock Bed

Good

Alignment

Good

Settlement

None Observed

### Penstock Type

Condition of wood, steel, fiberglass

Fair/Poor

Cracks

Prevalent in lower section

Stresses

Several deteriorated staves

Other

\_\_\_\_\_

Penstock Supports

Cradles

Fair except for one cradle just upstream  
of the anchor block is tipped over and  
broken

Saddles

Anchor Blocks

Condition of concrete

Deteriorated in several sections

Settlement

None Observed

Stress cracks

Movement

None Observed

Expansion Joints

Leaks


None Observed

Remarks Penstock is leaking substantially throughout.




**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**1997-06-13**



**TYPICAL SECTION OF CONCRETE CANAL WALL.**




**HIGH SECTION OF CONCRETE CANAL WALL WITH SIGNIFICANT  
DETERIORATION BELOW WATER LEVEL**

**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**997-06-13**




**TOP OF CONCRETE WALL BROKEN OFF.**




**DETERIORATED SECTION OF CONCRETE**

**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**1997-06-13**




**LEAK IN CONCRETE WALL**




**WATER LEAKING THROUGH HOLE IN CANAL WALL. SHOULD BE PATCHED.**

**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**1997-06-13**




**WATER FROM LEAK JUST BELOW SURFACE OF ROCKFILL**




**VIEW OF CANAL WALL NEAR INTAKE. NOTE NEW CONCRETE AND ROCKFILL.**

**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**1997-06-13**




**VIEW OF CANAL FROM INTAKE, LOOKING UPSTREAM. NOTE NEW CONCRETE  
FACE.**



**NEW CONCRETE INTAKE AND ROCKFILL.**

**LOCKSTON DEVELOPMENT  
POWER CANAL AND INTAKE**

**1997-06-13**



**CANAL WALL ON LEFT SIDE OF INTAKE. NOTE SEEPAGE ON RIGHT.**

**LOCKSTON DEVELOPMENT  
LOCKSTON PENSTOCK**

**1997-06-13**



**VIEW OF PENSTOCK FROM INTAKE**



**SECTION NEAR MIDDLE OF PENSTOCK. NOTE LEAKAGE.**

**LOCKSTON DEVELOPMENT  
LOCKSTON PENSTOCK**

**1997-06-13**



**PENSTOCK SECTION. NOTE WATER IN ROAD DUE TO LEAKAGE.**




**PENSTOCK SECTION NEAR POWERHOUSE. NOTE LARGE LEAKS.**



**LOCKSTON DEVELOPMENT  
LOCKSTON PENSTOCK**

**1997-06-13**



**PENSTOCK SECTION NEAR POWERHOUSE. NOTE WATER FLOWING ON  
BEDDING**




**PENSTOCK SECTION NEAR POWERHOUSE. NOTE BROKEN CRADLE TO LEFT.**

**LOCKSTON DEVELOPMENT  
LOCKSTON PENSTOCK**

**1997-06-13**



**SECTION NEAR BIFURCATION. NOTE SECTION OF BROKEN CRADLE AND CUT BRUSH**



**ANCHOR BLOCK AT BIFURCATION. NOTE CONCRETE DETERIORATION.**

**LOCKSTON DEVELOPMENT  
LOCKSTON PENSTOCK**

**1997-06-13**



**DETERIORATED CONCRETE AT BASE OF ANCHOR BLOCK**