

1999 Dam Safety Inspection Reports

PUB 3.2
Attachment D

Lockston Development

NEWFOUNDLAND POWER


April 26, 2000


Memo From: J. P. Halliday
To: M. C. Hunter
Subject: 1999 Dam Safety Inspection Reports
Lockston Development
File: 401.01.03.30.01

Attached are the Dam Safety Inspection reports for structures located in the Lockston Development. In general, structures in this development are in good condition and should operate safely with minor repairs and maintenance.

The woodstave penstock, however, is in poor condition, and consideration should be given to replacement in the near future.

Attach:



PROVINCE OF NEWFOUNDLAND	
	PERMIT HOLDER
	This Permit Allows
NEWFOUNDLAND POWER INC.	
To practice Professional Engineering in Newfoundland and Labrador. <i>2000</i>	
Permit No. as issued by APEGN <i>2000</i> which is valid for the year <i>2000</i>	

DAM SAFETY INSPECTION

Trinity Pond Dam, Spillway & Outlet

Dam Type: Concrete Buttress

Date & Time of Examination: 99-11-30

Operational Status at Time of Examination:

Reservoir Water surface elevation Approximately 8' below crest of outlet

Releases None

Weather Conditions Cloudy, 0°C

Water in storage

Recent Seismic Events None

Examining Party

P. Halliday

G. Humby

D. Laing

INSPECTION CHECKLIST FOR CONCRETE DAM

DAM

Upstream Face

Cracks None Observed

Joint Offsets None observed

Downstream Face

Cracks None observed

Joint Offsets None observed

Seepage on downstream face None observed

Downstream Toe

Cracks Gate opened approximately 1' at time of inspection.

Undercutting(from erosion) None observed

Crest

Roadway N/A

Walks Good

Parapet Wall N/A

Lighting, etc. N/A

Foundation at Downstream Toe of Dam

Seepage around dam

Location None observed

Amount

Measurement

Remarks: Structure is in good condition. Handrailing along crest appears low and should be raised 6"

Development: Lockston
Structure: Trinity Pond Outlet



General view from upstream



General view from downstream

DAM SAFETY INSPECTION

Rattling Pond Dam, Spillway & Outlet

Dam Type: Concrete

Date & Time of Examination: 99-11-30

Operational Status at Time of Examination:

Reservoir Water surface elevation F.S.L

Releases None

Weather Conditions Cloudy, 0°C

Water in storage

Recent Seismic Events None

Examining Party

P. Halliday

G. Humby

D. Laing

INSPECTION CHECKLIST FOR CONCRETE DAM

DAM

Upstream Face

Cracks Some minor spalls.

Joint Offsets None observed

Downstream Face

Cracks Few minor cracks

Joint Offsets None observed

Seepage on downstream face Minor seepage at toe near canal entrance.

Downstream Toe

Cracks Leaking in few areas

Undercutting(from erosion) None observed

Crest

Roadway N/A

Walks N/A

Parapet Wall N/A

Lighting, etc. N/A

Foundation at Downstream Toe of Dam

Seepage around dam

Location At toe near canal entrance.

Amount Minor

Measurement

Remarks: Gate mechanism has been replaced. Some minor seepage through sluice gate. Need to complete walkway and handrailing. Handrailing or safety fence should also be installed on dam section.

SPILLWAY

Control Structures

Crest N/A

Orifices N/A

Gates and Controls

Type of Gate N/A

General condition N/A

Operation of gates
at time of examination N/A

Approach Channel

Debris None observed

Slides over channel None observed

Channel side slope stability Good

Slope protection Good

Walkway

Condition of Piers N/A

Condition of decking and beams N/A

Condition of rails N/A

Stilling Basin

Debris None observed

Walls movement None observed

Walls settlement, etc None observed

Outlet Channel

Slope Protection	<u>O.K</u>
Stability of Slopes	<u>O.K</u>
Vegetation and other obstructions	<u>None observed</u>
Other	<u></u>

Flashboards

Condition	<u>N/A</u>
Operation	<u>N/A</u>

Remarks: Concrete in good condition. Minor undercutting D/S on left abutment. Also very minor seepage in this area, and through expansion joints

Development: Lockston
Structure: Rattling Pond Dam




Spillway from left abutment



Upstream showing canal entrance

Development: Lockston
Structure: Rattling Pond Dam



Upstream at canal gate



Sluice gate to right of canal entrance

DAM SAFETY INSPECTION

Lockston Canal, Intake & Penstock

Dam Type: Concrete

Date & Time of Examination: 99-11-30

Operational Status at Time of Examination:

Reservoir Water surface elevation F.S.L

Releases None

Weather Conditions Cloudy, 0°C

Water in storage

Recent Seismic Events None

Examining Party

P. Halliday

G. Humby

D. Laing

INSPECTION CHECKLIST FOR CONCRETE DAM

DAM

Upstream Face

Cracks	<u>Several cracks and areas of spalled concrete along canal. Intake concrete in good condition.</u>
Joint Offsets	<u>None observed</u>

Downstream Face

Cracks	<u>Few minor cracks</u>
Joint Offsets	<u>None observed</u>
Seepage on downstream face	<u>Several areas with minor leakage . Significant leak through valve near intake.</u>

Downstream Toe

Cracks	<u>Minor cracks</u>
Undercutting (from erosion)	<u>None observed</u>

Crest

Roadway	<u>N/A</u>
Walks	<u>O.K</u>
Parapet Wall	<u>N/A</u>
Lighting, etc.	<u>N/A</u>

Remarks: Concrete in fair condition. Several audible leaks all along canal but should be stable due to rockfill. Canal has little vegetation. Several areas along canal, and intake have been repaired/patched in recent years.

OUTLET WORKS

Intake

Trash rack Clear

Concrete See concrete section.

Outlet Conduit

Metal work N/A

Penstock See Penstock Section Attached

Control Facilities

Gatehouse Fair-Poor condition. Needs work on roof and exterior.

Crane N/A

Gate and controls (description) New Armtec gate & lift

General condition Good

Operation at time of examination Open

Control System Mechanical items Good condition

Ventilation O.K

Lighting O.K

Stop logs

General condition N/A

Seals

Remarks: - Rakes for cleaning trash rack not working. Not sure if they are ever used, as they appear obsolete. Maybe they should be removed.
- Electrical service may need upgrading for water level controls.

PENSTOCK

Right of way

Vegetation	<u>Some minor vegetation along penstock bed, especially in upstream section</u>
Drainage ditches	<u>Drainage poor</u>
Culverts	<u>N/A</u>

Condition of Penstock Bed

	<u>Bed Stable – however, drainage poor & several support cradles undetermined.</u>
Alignment	<u>O.K, some areas of settlement, however they don't appear recent.</u>
Settlement	<u>Few areas</u>

Penstock Type

Condition	<u>Wood in poor condition, especially in lower section where staves are crushed.</u>
Cracks	<u>Several cracks in lower section.</u>
Stresses	<u>Several staves crushed, probably due to stresses in pipe or overtightening bands.</u>
Other	<u></u>

Penstock Supports

Cradles	<u>Fair Condition</u>
Saddles	<u>Fair Condition</u>

Anchor blocks

Condition of concrete	<u>Fair-Good with some minor leaching.</u>
Settlement	<u>None observed</u>
Stress cracks	<u>None observed</u>
Movement	<u>None observed</u>

Expansion Joints

Leaks	<u>N/A</u>
Stress cracks	<u>N/A</u>

Penstock Cover


Condition of backfill	<u>N/A</u>
Slope Stability	<u>N/A</u>

Remarks: Penstock in poor condition with several staves crushed and/or rotted. Cradles and penstock supports are in fair condition, with several undermined. Considerable work has gone into repairs to leakage.

Development: Lockston
Structure: Lockston Power Canal



Canal embankment looking upstream



Concrete deterioration along canal walls

Development: Lockston
Structure: Lockston Power Canal



Concrete deterioration along canal walls



Concrete deterioration along canal wall

Development: Lockston
Structure: Lockston Power Canal



Leakage through canal wall near intake

Development: Lockston
Structure: Lockston Intake



Downstream slope to right of intake



View from downstream

Development: Lockston
Structure: Lockston Penstock



Looking downstream near intake



Typical crushed staves

Development: Lockston
Structure: Lockston Penstock



Typical crushed staves




Looking downstream showing leakage along bedding and access road

Development: Lockston
Structure: Lockston Penstock



Looking downstream from access road



Looking downstream towards powerhouse