

1 **Re Distribution Reliability Initiative, Volume III, Distribution - Appendix 3, Attachment B,**
2 **pages 1- 2 (\$949,000)**

3
4 **Q. Corrective measures have been taken concerning poles along “the Beach” section of**
5 **this line, the section that has been responsible for the majority of outage duration**
6 **over the last five years. Also, SAIFI for this line is better than system average.**
7 **Given these facts, could the upgrading of feeder BRB-04 be deferred pending**
8 **analysis of further experience? If not, why not?**
9

10 A. The poles that failed were replaced at the time of the incident, however, no further
11 corrective measures have been taken concerning poles along “the Beach” section of this
12 line.
13

14 The SAIFI for this feeder is better than the average as indicated in Appendix A of the
15 report “A Review of Reliability, Bay Roberts-04 Feeder”, however, it is only one
16 measure of the feeder’s reliability. The SAIDI for this feeder, at 5.51 customer hours per
17 year (see Appendix A), is also an important measure of reliability and it is much worse
18 than the SAIDI average for all feeders at 2.85 customer hours per year.
19

20 The proposed reliability upgrade of BRB-04 represents an opportunity to substantially
21 improve the reliability of a poorly performing line with a relatively small investment in
22 reconstruction in two locations that have been responsible for the majority of problems
23 over the last five years.