

**Newfoundland Power Inc.
2005 Capital Budget Application
Filing Contents**

**Volume I
Application**

Application

- Schedule A *2005 Capital Budget Summary*
- Schedule B *2005 Capital Projects Explanations*
- Schedule C *Estimate of Future Required Expenditures on 2005 Projects*
- Schedule D *Rate Base*
- Schedule E *Average Invested Capital*
- Schedule F *Calculation of Rate of Return on Rate Base*

2005 Capital Budget Plan

2004 Capital Expenditure Status Report

Report on Deferred Charges and Rate Base

Report on the Amortization of the Unfunded Pension Liability

**Volume II
Expenditure Details, Reports and Studies**

Energy Supply

- Appendix 1 *Hydro Plants - Facility Rehabilitation*
- Appendix 2 *Wesleyville Gas Turbine Overhaul*
 - Attachment A *Rolls-Royce Field Service Report dated December 22, 2003*
- Appendix 3 *Rattling Brook Hydro Plant Refurbishment*
 - Attachment A *Engineering Plan – Rattling Brook Refurbishment*
 - Attachment B *Project Justification - Rattling Brook Refurbishment Project*

Substations

- Appendix 1 *Rebuild Substations*
- Appendix 2 *Replacement and Standby Substation Equipment*

Transmission

- Appendix 1 *Rebuild Transmission Lines*

Distribution

Appendix 1 ***Distribution Reliability Initiative***

Attachment A ***A Review of Reliability Gander Bay-02 Feeder***

Appendix 2 ***Feeder Additions and Upgrades to Accommodate Growth***

Attachment A ***St. John's East End Planning Study: Virginia Waters, Ridge Road, Broad Cove and Pulpit Rock Substations***

General Property

Appendix 1 ***Tools and Equipment***

Appendix 2 ***Real Property***

Transportation

Appendix 1 ***Purchase Vehicles and Aerial Devices***

Attachment A ***Details 2005 Capital Budget Vehicle Budget***

Information Systems

Appendix 1 ***Application Enhancements***

Appendix 2 ***Application Environment***

Appendix 3 ***Customer Systems Replacement***

Appendix 4 ***Network Infrastructure***

Appendix 5 ***Personal Computer Infrastructure***

Appendix 6 ***Shared Server Infrastructure***

Project Title: **Hydro Plants - Facility Rehabilitation**

Location: **Various**

Classification: **Energy Supply**

Project Cost: **\$1,887,000**

This project consists of a number of items as noted.

(a) Cape Broyle – Replace Inlet, Drain and Bypass Valves

Cost: \$249,000

Description: Replace existing turbine inlet valve, drain valve and bypass valves.

Operating Experience: The 78 inch turbine inlet valve and associated drain and bypass valves were installed in 1952. Erosion of the valve disc and seats have rendered this equipment ineffective in providing positive water shut off required to perform maintenance on the equipment. On occasion the water leakage through the valve has caused the turbine unit to continue to turn during machine shutdown.

The following table gives the expenditures for the past five years for the Cape Broyle Plant.

| Expenditures | | | | | |
|---------------------|-------------|-------------|-------------|-------------|--------------|
| Year | 2000 | 2001 | 2002 | 2003 | 2004F |
| (\$000s) | \$38 | \$1,086 | \$5 | \$91 | - |

The following table gives the projected expenditures for this plant for the next five years.

| Projected Expenditures | | | | | |
|-------------------------------|-------------|-------------|-------------|-------------|-------------|
| Year | 2005 | 2006 | 2007 | 2008 | 2009 |
| (\$000s) | \$289 | - | - | \$1,098 | - |

Justification: The inlet valve and associated equipment is a critical link in the continued safe and effective operation and maintenance of the Cape Broyle Hydro Generation Plant. Normal production at this facility is 34.2 GWh per year.

A cost benefit analysis to determine the long term economic viability of the plant based on forecasted capital expenditures and operating costs indicates an incremental cost of 0.67 cents per kilowatt hour for Cape Broyle plant energy when levelized over 25 years on a NPV basis.

(b) Seal Cove – Fenelons Pond Dam Refurbishment

Cost: \$390,000

Description: Refurbish Fenelons Pond dam, including earth fill embankment, spillway and flow control structure.

Operating Experience: Regularly scheduled engineering dam safety inspections have identified that the dam, spillway and flow control structure have all reached a state of advanced deterioration. Of particular concern is the erosion of embankment materials evident throughout the crest, upstream face and at the spillway abutments.

The following table gives the expenditures for the past five years for the Seal Cove Plant.

| Expenditures | | | | | |
|---------------------|-------------|-------------|-------------|-------------|--------------|
| Year | 2000 | 2001 | 2002 | 2003 | 2004F |
| (\$000s) | - | - | \$4,013 | \$532 | \$11 |

The following table gives the projected expenditures for this plant for the next five years.

| Projected Expenditures | | | | | |
|-------------------------------|-------------|-------------|-------------|-------------|-------------|
| Year | 2005 | 2006 | 2007 | 2008 | 2009 |
| (\$000s) | \$390 | \$131 | \$25 | \$470 | - |

Justification: The Fenelons Pond dam and associated structures are critical to the safe and effective operation of the Seal Cove Hydro Generation Plant. The refurbishment of these structures will minimize risk of failure and associated risk to public safety and environmental damage. Normal production at this plant is 8.8 GWh per year.

A cost benefit analysis to determine the long term economic viability of the plant based on forecasted capital expenditures and operating costs indicates an incremental cost of 2.74 cents per kilowatt hour for Seal Cove energy when levelized over 25 years on a NPV basis.

(c) Heart's Content – Forebay Canal Refurbishment, Long Pond Dam Refurbishment and Rocky Pond Dam Refurbishment

Cost: \$337,000

Description: Refurbish existing forebay canal, gate house foundation, Long Pond dam, Rocky Pond dam and spillway located within the Hearts Content Hydro Generation Plant watershed.

Operating Experience: Hydrology studies and recently completed inspections at the Heart's Content watershed areas assessed the spill/discharge capacities of the reservoir and general conditions of the existing structures. The studies and inspections identified that:

- the crest of the forebay canal embankment and adjacent structures should be raised to ensure flood conditions are adequately routed through the Rocky Pond spillway.
- the gabion abutments at the Long Pond dam have deteriorated. In particular, the gabion walls located at the spillway and outlet structure are leaning away from the embankment, thus compromising the integrity of the dam embankment.
- there was insufficient freeboard allowance at the Long Pond dam, posing a risk of dam crest overtopping during flood events.
- there was insufficient freeboard allowance at the Rocky Pond dam, posing a risk of dam crest overtopping during flood events.

The following table gives the expenditures for the past five years for the Heart's Content Plant.

| Expenditures | | | | | |
|---------------------|-------------|-------------|-------------|-------------|--------------|
| Year | 2000 | 2001 | 2002 | 2003 | 2004F |
| (\$000s) | \$17 | \$78 | \$55 | \$17 | - |

The following table gives the projected expenditures for this plant for the next five years.

| Projected Expenditures | | | | | |
|-------------------------------|-------------|-------------|-------------|-------------|-------------|
| Year | 2005 | 2006 | 2007 | 2008 | 2009 |
| (\$000s) | \$337 | - | \$150 | - | \$1,631 |

Justification: The canal, dams and associated structures are critical components for the continued safe and effective operation of the Heart's Content Hydro Generation Plant. The refurbishment of these structures will minimize the risk of flooding and associated risk to public safety and environmental damage. Normal production at this plant is 8.2 GWh per year.

A cost benefit analysis to determine the long term economic viability of the plant based on forecasted capital expenditures and operating costs indicates an incremental cost of 3.43 cents per kilowatt hour for Heart's Content Plant energy when levelized over 25 years on a NPV basis.

(d) Mobile – Replace Inlet, Drain and Bypass Valves

Cost: \$240,000

Description: Replace existing turbine inlet valve, drain valve and bypass valves.

Operating Experience: The 60-inch turbine inlet valve and associated drain and bypass valves were installed in the early 1950's. Erosion of the valve disc and seals has rendered this equipment ineffective in providing positive water shut off required to perform maintenance on the equipment. On occasion, the water leakage through the valve, has caused the turbine unit to continue to turn during machine shutdown. Several attempts during the past 10 years to fix the inlet valve by repairing internal valve seals have not been successful.

The following table gives the expenditures for the past five years for the Mobile Plant.

| Expenditures | | | | | |
|---------------------|-------------|-------------|-------------|-------------|--------------|
| Year | 2000 | 2001 | 2002 | 2003 | 2004F |
| (\$000s) | \$56 | \$46 | \$9 | \$1 | \$5 |

The following table gives the projected expenditures for this plant for the next five years.

| Projected Expenditures | | | | | |
|-------------------------------|-------------|-------------|-------------|-------------|-------------|
| Year | 2005 | 2006 | 2007 | 2008 | 2009 |
| (\$000s) | \$240 | - | - | - | - |

Justification: The inlet valve and associated equipment is a critical link in the continued safe and effective operation and maintenance of the Mobile Hydro Generation Plant. Normal production at this facility is 41.8 GWh per year.

A cost benefit analysis to determine the long term economic viability of the plant based on forecasted capital expenditures and operating costs indicates an incremental cost of 0.58 cents per kilowatt hour for Mobile Plant energy when levelized over 25 years on a NPV basis.

(e) Port Union – Refurbish Whirl Pond Dam

Cost: \$76,000

Description: Refurbish existing Whirl Pond dam at the Port Union Hydro Plant.

Operating Experience: Regularly scheduled inspections by an independent engineering consultant and Newfoundland Power engineering and operations staff have identified that the timber crib dam at Whirl Pond has become deteriorated. In particular, excessive rotting of timber and movement/settlement of rock fill is evident throughout.

Justification: The Whirl Pond dam is a critical component for the continued safe and effective operation of the Port Union Hydro Generating plant. The refurbishment of the dam will minimize risk of failure and associated risk to public safety and environmental damage. Normal production at this plant is 2.3 GWh per year.

(f) Various Plants – Upgrade Protection and Controls

Cost: \$302,000

Description: Replace protection and control systems in Newfoundland Power's hydro plants to provide for the reliable and safe operation of the plants and to support a predictive maintenance program. This will be achieved by addressing issues pertaining to equipment requiring maintenance but no longer supported by the manufacturer thus making replacement parts expensive or unavailable. As well, this project will improve the control and protection of the equipment by using more versatile electronic devices. Additional monitoring, control and protective devices will be installed to meet present day standards. These upgrades will also facilitate increased automation and remote control capabilities. In 2005 upgrades are planned for the following Hydro Plants: Lookout Brook, Lockston, Lawn and Tors Cove.

Operating Experience: The power plants owned by Newfoundland Power range in age from 6 to 104 years. Much of the original protection and control equipment is still in service, in particular the hydraulic gateshaft governors, switchgear and protective relays. The switchgear in some plants is over fifty years old and the majority of plants have protection schemes utilizing electromechanical relays that do not provide the present IEEE minimum protection requirements.

Justification: The continued reliable, safe and environmentally responsible operation of Newfoundland Power's generating stations requires the replacement of equipment which is beyond its serviceable life as well as the application of new technology to better monitor and control the units to minimize the possibility of costly, major failures.

(g) Refurbish/Replace Hydro Generating Plant Infrastructure & Equipment

Cost: \$150,000

Description: Refurbish/replace deteriorated or damaged structures and equipment identified through the normal inspection process.

Operating Experience: Newfoundland Power maintains a variety of dams and control structures forming part of the watershed areas for its various hydro generating facilities.

These dams and control structures are subjected to repetitive natural forces which exert pressures that could lead to failure. Ice action is an annual event causing movement of rock fill on the upstream slopes of the embankment dams. Excessive ice loading conditions leads to failures of timber stop log structures used to control the flow of water past a control structure or overflow spillway.

Wave action during windstorms results in the erosion of earth fill dam materials that undermines the integrity of the structure.

During the spring runoff, with reservoir water levels high, spillway structures are susceptible to damage from flood events during that period of the year.

Since the integrity of these facilities is critical to the efficient operation of the generating facilities, environmental protection and public safety, the facilities are inspected on a regular basis. Deficiencies identified during inspections normally require immediate attention.

Justification: The dams and control structures are critical components in the safe and efficient operation of its hydro generating plants. The expeditious refurbishment of damaged structures will minimize the risk of failure and associated risk to public safety and environmental damage.

(h) Projects < \$50,000

Cost: \$143,000

Description: Listed are projects estimated at less than \$50,000.

1. Cape Broyle – Dam refurbishment
2. Lookout Brook – Bridge refurbishment
3. Rose Blanche – Building and drainage refurbishment
4. Sandy Brook – Spillway and outlet structure refurbishment

Project Title: Wesleyville Gas Turbine Overhaul

Location: Wesleyville

Classification: Energy Supply

Project Cost: \$1,124,000

See Attachment A, *Rolls-Royce Field Service Report* dated December 22, 2003, outlining the recommendations for this project.



Rolls-Royce

Energy Supply
Appendix 2
Attachment A
NP 2005 CBA

Field Service Report

Operator: Newfoundland Power

Site: Wesleyville

Reason for Visit: Engine and Installation Inspection

Operator Contact:

John Budgell
Kent Nicholson

Contact phone number:

Visit Dates From:

Dec 07th, 2003

to:

Dec 12th, 2003

Equipment: Avon Mk1533-76L

Gas Generator serial no:

37127

Hours since new:

2745

Power Turbine/package serial no:

N/A

Hours since *new/overhaul:

N/A

Field Service Rep:

Gary Glancy

Date of report:

Dec 22nd, 2003

Report Reference:

SWOF: 03-2111

SV-IMD-A762

1.0 INTRODUCTION

- 1.1 This unit was moved from Salt Pond Newfoundland to Wesleyville. During the move the power turbine was overhauled and a complete new intake assembly was installed. A new Allen Bradley fuel control was also installed.
- 1.2 Newfoundland Power asked for a Rolls-Royce Representative to inspect the gas generator and installation prior to starting the unit.

2.0 CONCLUSIONS

- 2.1 The gas generator was inspected prior to the move and the recommendation at that time was to have the unit sent to an approved overhaul facility for repair prior to running the unit. This visit was not different in that the customer was informed that the gas generator is in poor condition and should be overhauled as soon as possible to prevent the possibility of a catastrophic failure.

3.0 RECOMMENDATIONS TO CUSTOMER

- 3.1 This engine should be removed and sent to an approved overhaul facility as soon as possible.
- 3.2 The fuel drain from the fuel cooled oil cooler should be tubed in to the common drain tank.
- 3.3 The fuel drain from the low fuel pressure switch should be tubed in to the common drain tank.
- 3.4 A thermocouple should be installed in the cooling air pipe work and a trip setting of 360DegC should be set into the fuel control.
- 3.5 The gearbox breather was open to inside the enclosure, this should be fed into the exhaust ducting or to outside of the building.
- 3.6 The bleed valve ductwork was adjusted during installation; a further check should be carried out when the engine is warm to make sure that the ductwork does not come in contact with the engine off takes.
- 3.7 Customer should seriously consider installing a variable inlet guide vane feedback. At this time it is impossible to check variable inlet guide vane position. Although there is no guide vane position indication; the bleed valve opening set-points should be checked during initial running.

- 3.8 Flex couplings should be added to the cooling and sealing air pipe work to prevent any stress at the engine interface.
- 3.9 Entry should be made in engine log book to record work performed and any modifications embodied in the engine listed below.

4.0 WORK PERFORMED, OBSERVATIONS AND TEST RESULTS

- 4.1 After arriving at site the engine installation was inspected. The front mounts were found installed correctly, the rear mounts were also found installed correctly. The rear exhaust section was already installed and had been inspected by site personnel; the complete alignment checks were therefore not completed.
- 4.2 A further inspection of the engine externals was carried out which led to the recommendation as reported above.
- 4.3 The top and bottom intake assemblies were inspected prior to motoring the engine. This was then signed off along with NFP personnel.
- 4.4 A boroscope inspection was carried out and the following pictures will show the poor condition of the gas generator. The first few pictures show the intake casing and guide vanes. Both the casing and vanes are extremely salt corroded, eroded and pitted:






- 4.5 The next two pictures show the last stage of compressor blade with FOD impact damage:



- 4.6 The fuel burners had recently been removed and cleaned and were found in good condition. The combustors were also in reasonable condition with exception to heavy carbon build-up.
- 4.7 The HP NGV's and HP Turbine were found in poor condition as the following pictures will show. These blades are also corroded, eroded and pitted, FOD damage and splatter also apparent.



- 4.8 All inspections and/or processes described in this report have been carried out in accordance with the following list of reference documents and their amendments.
Ind Avon Installation Manual.
Ind Avon Maintenance Manual

5.0 ROLLS-ROYCE ACTIONS

- 5.1 None.

Gary Glancy
Customer Service Business

Project Title: **Rattling Brook Hydro Plant Refurbishment**

Location: **Rattling Brook – Norris Arm South**

Classification: **Energy Supply**

Project Cost: **\$350,000**

See Attachment A, *Engineering Plan – Rattling Brook Refurbishment*, which describes the engineering work proposed for 2005 and Attachment B, *Project Justification -Rattling Brook Refurbishment Project*, which outlines the rationale and justification for this project.

**Engineering Plan
Rattling Brook Refurbishment**

July 16, 2004

Prepared By:

Jack Casey P. Eng.
Gary Humby P. Eng.

Table of Contents

| | Page |
|---|-------------|
| 1.0 General..... | 1 |
| 2.0 Deliverables | 1 |
| 2.1 Civil Engineering..... | 2 |
| 2.1.1 Environmental..... | 2 |
| 2.1.2 Penstock Engineering Design | 2 |
| 2.1.3 Penstock Installation Specification | 2 |
| 2.1.4 Penstock Supply Tender Preparation | 2 |
| 2.1.5 Penstock Installation Tender Preparation | 2 |
| 2.1.6 Surge Tank Engineering Design Specification | 2 |
| 2.2 Electrical Engineering..... | 2 |
| 2.2.1 Prepare final Design Document..... | 2 |
| 2.2.2 Protection Review | 3 |
| 2.2.3 Electrical Installation Design Specifications | 3 |
| 2.2.4 Electrical Installation Tender Preparation | 3 |
| 2.2.5 Governor Design Specifications | 3 |
| 2.2.6 Governor Tender Preparation | 3 |
| 2.2.7 Protection and Control System Design Specifications | 3 |
| 2.2.8 Inspection of Switchgear..... | 3 |
| 2.3 Mechanical Engineering | 3 |
| 2.3.1 Internal Inspection of Mechanical Components | 3 |
| 2.3.2 Main Valve Engineering Design Specifications | 4 |
| 2.3.3 Main Valve Tender Preparation..... | 4 |
| 2.3.4 Turbine Runner Engineering Design Specifications..... | 4 |
| 2.3.5 Turbine Runner Tender Preparation | 4 |
| 2.3.6 Mechanical Installation Design Specifications | 4 |
| 2.3.7 Mechanical Installation Tender Preparation | 4 |
| 2.4 Resource Assignment..... | 4 |
| 3.0 Cost Estimate | 5 |

1.0 General

The Rattling Brook hydro development was placed into service in 1958. Since 1958, some refurbishment work has been completed within the plant. In 1986 and 1987, the turbine runners were replaced on each unit. In 1994, the Rattling Brook generating station was placed under remote control from the system control centre in St. John's. In 2002, the stator on unit # 2 generator was rewound after it failed in service. The rewind of generating unit #1 is included in the 2004 Capital Budget. Also in 2002, a new power transformer was installed replacing the two original units. With the exception of these major projects, the plant remains in original condition.

During the 2006 and 2007 construction seasons, Newfoundland Power intends to undertake a refurbishment of the civil, electrical and mechanical systems at Rattling Brook. The level of preliminary engineering completed to date varies across the different engineering disciplines. Preliminary engineering studies have been completed on the in-plant electrical and mechanical systems. More detailed engineering studies have been completed on the replacement of the woodstave penstock and the refurbishment of the surge tank and the turbine runners.

Construction will be completed in two phases during the 2006 and 2007 construction seasons. The penstock will be replaced in two stages, with the lower half being replaced in 2006, and the upper half in 2007. The mechanical work associated with the runner, wicket gates and valves will also be undertaken in 2006. The surge tank refurbishment and the plant electrical, governors, protection and control work will be completed in 2007.

In 2005 detailed engineering design, specification and tender preparation work will be completed for the replacement of the woodstave penstock and for the mechanical work planned for 2006. Also preliminary engineering work is planned for 2005 for the refurbishment of the surge tank and the electrical work planned for 2007. This preliminary engineering work is necessary to provide detailed estimates for the 2006 and 2007 capital budgets.

2.0 Deliverables

To ensure the project is completed on budget and on schedule, with a minimal impact on the production available from the Rattling Brook development, the major pieces of engineering work should be completed in advance of the 2006 construction season. It is proposed that most of the engineering design work be completed during 2005. The following list of engineering deliverables, organized by engineering discipline, will be completed in 2005.

2.1 Civil Engineering

2.1.1 Environmental

Complete the necessary environmental work required for the replacement of the woodstave penstock. Conduct environmental investigation and soil testing to determine the extent of contamination from the creosote treated penstock, and to determine an environmentally acceptable method for disposal of soil and penstock materials.

2.1.2 Penstock Engineering Design

Complete detailed engineering design to optimize penstock diameter, and to explore alternatives for penstock material (steel or fibreglass). Complete design of penstock sections, penstock supports, anchor blocks, steel bulkhead, and transition to existing steel penstock.

Conduct testing on the lower section of steel penstock to determine the location and causes of excess head losses upstream and downstream of the bifurcation.

Research design information and past load rejection history, and conduct load rejection testing to confirm the capacity of the components that are to remain.

2.1.3 Penstock Installation Specification

Complete field survey and geotechnical investigation, and prepare engineering specifications.

2.1.4 Penstock Supply Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.1.5 Penstock Installation Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.1.6 Surge Tank Engineering Design Specification

Complete field surveys and prepare engineering specifications. Engage consultant with expertise in the design of surge tanks.

2.2 Electrical Engineering

2.2.1 Prepare Final Design Document

Review documented maintenance history for the plant and review current maintenance issues with local operators. Inspect electrical equipment, including control system, synchronizer, voltage regulator, and governor electrical interfaces. Identify issues with wear, corrosion, and other forms of degradation. Prepare a final design document based upon the conceptual design for review by technical experts. Review budget estimates in light of final design and revise as necessary.

2.2.2 Protection Review

Review existing protection system, including relay settings and single line diagrams. Apply current protection standards and identify areas where existing protection fails to meet current standard. Prepare a detailed protection plan for inclusion in protection and control specifications.

2.2.3 Electrical Installation Design Specifications

Complete engineering specifications for replacement equipment, and other electrical work to be completed by an electrical contractor. Specification document will include all electrical work to be completed during the 2006 construction season. Specifications will include electrical work associated with all civil and mechanical work planned for 2006.

2.2.4 Electrical Installation Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.2.5 Governor Design Specifications

The mechanical inspection will verify if the power components of the existing Woodward hydraulic governor remain serviceable. If, as expected, this proves to be the case, develop engineering specifications for replacing the governor control head with an electronic controller. However, if the power components of the existing Woodward hydraulic governor prove not to be serviceable, then prepare engineering specifications for a replacement all-electric governor.

2.2.6 Governor Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.2.7 Protection and Control System Design Specifications

The protection review will provide the protection plan required for these generators. Apply the generator protection standards to the protection plan developing the necessary design drawings and specifications. Incorporate the generator protection design with the specific control system requirements of the generator, to prepare specifications for the construction of a PLC-based unit control panel.

2.2.8 Inspection of Switchgear

Complete an internal inspection of the switchgear and associated potential and current transformers. Inspect the bus work, exciter cables, power cables and power cable terminations. Make recommendations on the remaining service life of the switchgear.

2.3 Mechanical Engineering

2.3.1 Internal Inspection of Mechanical Components

Remove the plant from service and dewater the penstock. Inspect the internal components associated with the main valve and the wicket gates. Identify which components need to be replaced or refurbished.

Disassemble the Woodward hydraulic governors and inspect the power components for wear and oil leaks. If possible, include a manufacturer's representative with the inspection team. Determine the condition of all spare parts and source additional spare parts as necessary. Make an assessment of the remaining life of these components.

2.3.2 Main Valve Engineering Design Specifications

The internal inspection will confirm if a valve refurbishment is technically possible, or if the main valves will need to be replaced. Prepare engineering specifications on alternative chosen. Review budget estimates in light of final design and revise as necessary.

2.3.3 Main Valve Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.3.4 Turbine Runner Engineering Design Specifications

The mechanical internal inspection will identify the work necessary on the turbine runner. Prepare engineering specifications for the work identified. Review budget estimates in light of final design and revise as necessary.

2.3.5 Turbine Runner Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.3.6 Mechanical Installation Design Specifications

Complete engineering specifications for replacement equipment, and other mechanical work to be completed by a mechanical contractor. Include the realignment of unit #2 and the replacement of the generator cooling air intake dampers with these specifications. Specification document will include all mechanical work to be completed during the 2006 construction season.

2.3.7 Mechanical Installation Tender Preparation

Complete the necessary tender documents including the tender form, agreement, schedule of prices, schedule of equipment and all other necessary schedules.

2.4 Resource Assignment

It is anticipated that internal Newfoundland Power resources will be used to complete most engineering work, including equipment inspections. Engineering consultants will be engaged for specialized expertise such as the inspection of the surge tank and the required environmental assessments.


3.0 Cost Estimate

The table below identifies the effort and associated cost for preparing the various engineering deliverables:

| Deliverable | Internal Cost | Consultant Cost | Total |
|-------------------------------|----------------------|------------------------|---------------------|
| Civil Engineering | | | |
| Testing and Inspections | \$14,000.00 | \$10,000.00 | \$24,000.00 |
| Engineering Design | \$40,000.00 | \$20,000.00 | \$60,000.00 |
| Tenders and Procurement | \$29,000.00 | | \$29,000.00 |
| Electrical Engineering | | | |
| Testing and Inspections | \$16,000.00 | | \$16,000.00 |
| Engineering Design | \$98,500.00 | | \$98,500.00 |
| Tenders and Procurement | \$28,000.00 | | \$28,000.00 |
| Mechanical Engineering | | | |
| Testing and Inspections | \$22,500.00 | | \$22,500.00 |
| Engineering Design | \$50,500.00 | | \$50,500.00 |
| Tenders and Procurement | \$21,500.00 | | \$21,500.00 |
| TOTAL | | | \$350,000.00 |

Project Justification
Rattling Brook Refurbishment Project

July 9, 2004



Prepared By:
John W. Pardy, P.Eng.
Jack W. Casey, P. Eng.

Table of Contents

| | Page |
|--|-------------|
| 1.0 Introduction..... | 1 |
| 2.0 Civil Works..... | 1 |
| 3.0 Electrical Works..... | 2 |
| 4.0 Mechanical Works | 3 |
| 5.0 Feasibility Analysis..... | 4 |
| 6.0 Project Execution..... | 4 |
| 7.0 Conclusion | 5 |
| | |
| Appendix A: Civil Engineering Reports | |
| Appendix B: Electrical Equipment Site Assessment | |
| Appendix C: Mechanical Site Assessment | |
| Appendix D: Feasibility Analysis | |

1.0 Introduction

The Rattling Brook hydro development is located approximately 50 kilometres west of Gander in the Notre Dame Bay area. The development was placed into service on December 16, 1958 utilizing two 8500 horsepower vertical shaft Francis type turbines connected to separate generators, each with an individual rating of 7500 kVA. The original construction cost of this project was approximately \$6 million.

Since that time, refurbishment work has been completed on some systems within the plant. In 1986 and 1987 the turbine runners were replaced on each unit. In 1994, the Rattling Brook generating station was placed under remote control from the system control centre in St. John's. The stator on unit # 2 generator was rewound after it failed in service in 2002. The stator on unit #1 generator is being rewound in the summer of 2004 as part of the 2004 Capital Budget. Also in 2002 the installation of a new power transformer in the substation was completed replacing the two original units. With the exception of these major projects, the plant remains in original condition.

During the 2006 and 2007 construction seasons, Newfoundland Power proposes to undertake a refurbishment of the civil, electrical and mechanical systems at Rattling Brook. Engineering assessments of the systems are included in Appendices A, B and C. Appendix D includes a detailed feasibility analysis of the costs and benefits associated with this project.

The extent of preliminary engineering completed to date varies across the different engineering disciplines. Detailed engineering studies have been completed on the replacement of the woodstave penstock and the refurbishment of the surge tank and the turbine runners. Preliminary engineering studies have been completed on the in-plant electrical and mechanical systems. Construction will be completed in two phases during the 2006 and 2007 construction seasons. In 2005 detailed engineering design, specification and tender preparation work will be completed for the replacement of the woodstave penstock. Also more detailed engineering work is planned for 2005 dealing with the refurbishment of the surge tank and the electrical and mechanical work. This more detailed engineering work will provide final estimates for the 2006 and 2007 capital budgets.

This multiphase approach to the engineering design will ensure the lowest cost solutions, proposing replacement of systems only when refurbishment is not practical. Budget costs presented in the second and third year of the project will be the result of detailed engineering assessments completed during planned outages in the previous year.

2.0 Civil Works

The engineering assessment has identified the following pieces of civil work to be completed during the plant refurbishment:

- Replace wood stave penstock
- Refurbish surge tank
- Rehabilitation of Amy's Lake control structure

In the fall of 2003, the SGE Acres consulting firm were engaged to complete inspections of the penstock and surge tank at Rattling Brook. Their report, included in Appendix A, recommends the replacement of the woodstave penstock and refurbishment of the surge tank. The penstock is described as being in poor condition with leakage along the springline. The surge tank has serious cracking of welds, wear of metal components due to friction, wood rot and corrosion damage. Undertaking the refurbishment of the surge tank in the near term can avoid the complete replacement of the structure at some future date.

In 1982, Newfoundland Power undertook a study into the potential for increasing the Rattling Brook plant capacity through a redesign of the flow area of the penstock. At that time it was determined that the cost of replacing the penstock was not justified by the benefits associated with an estimated 6.7 GWH in additional energy. In the twenty-two years since the original study, the condition of the penstock has deteriorated to the point where its replacement is required for public safety reasons and to ensure the reliable operation of the generating plant. The incremental cost of increasing the penstock diameter from its original diameter of 2.1 and 2.3 metres to the optimal diameter of 2.9 metres is justified by the increased energy supplied.

3.0 Electrical Works

An engineering assessment in Appendix B has identified the following pieces of electrical work to be completed during the plant refurbishment:

- Upgrade electrical and mechanical protection system for Rattling Brook plant
- Replace voltage regulator, synchronizer and alarm annunciation
- Replace power cables and exciter cables
- Replace existing relay control system with PLC based control system
- Refurbish or replace existing governor systems
- Replace or upgrade the existing switchgear, pending further internal inspections
- Replace AC and DC electrical distribution systems

The assessment identified concerns with the electrical protection of the new generator windings, the lack of vibration monitoring, power cable condition and future support of the existing Woodward hydraulic governors.

In 2002, the windings were replaced on the unit #2 generator after there was an in-service failure. The replacement of the windings on the unit #1 generator is planned for the summer of 2004. The set of electromechanical protective relays on the generator do not meet the current IEEE recommendations, falling short in the area of ground fault protection, over-frequency protection and stator unbalance.

The synchronizer is vacuum tube technology dating back to the 1958 installation. Replacement vacuum tubes are no longer manufactured. Similarly, the alarm annunciator is constructed using antiquated technology and fails regularly.

The switchgear and power cables are original to the 1958 installation. Deterioration of the oil filled power cables and the current/potential transformer windings due to age are a concern. An engineering review of the condition of the power cables, breakers, bus work and current/potential transformers will be undertaken with the entire system de-energized in 2005.

4.0 Mechanical Works

The engineering assessment has identified the following pieces of mechanical work to be completed during the plant refurbishment:

- Refurbish runners
- Refurbish the main valves
- Replace the five way control valves
- Replace wicket gates
- Replace the governors' hydraulic control head
- Upgrade the cooling water system and replace strainers
- Alignment of unit #2
- Replace the air intake louvers

The internal inspection of the turbine runners was completed in 1998 with the balance of plant inspection completed in May 2004. The inspection has identified both replacement and refurbishment work to be undertaken during the plant outages in 2006 and 2007.

Damage to the runners has been identified in the mechanical assessment included in Appendix C. This damage can be repaired at relatively low cost if undertaken in the next few years. The main valves are leaking, but it is felt that if the work is undertaken at this time the valves can be refurbished and not replaced. Repairs completed on the wicket gates in the 1980s have failed and the wicket gates need to be replaced.

When unit #2 generator was rewound in 2002 and issued with the unit alignment was identified that requires attention during the next plant outage of significant duration. The work on the runners during this project presents an excellent opportunity to realign unit #2.

The governors are responsible for regulating the speed of the generator, which translates into the frequency component of power quality to the customer. This is particularly important when the generators are operating isolated from the grid and do not benefit from the dampening effect of the larger power system. The existing governors are original to the plant and require more frequent maintenance as the various linkages and springs wear with age. The original equipment manufacturer can no longer provide replacement parts for the various linkages and springs that are used to regulate generator speed. However the original equipment manufacturers, and other suppliers, do manufacture an electronic upgrade for the original hydraulic control head. As the oil reservoir and power piston appear to be in good condition, these governors are candidates for this form of upgrade, as opposed to the replacement of the complete hydraulic package with newer technology.

A redesign of the cooling water system is required to address existing operational maintenance issues. Separate cooling water systems and duplex strainer systems will allow maintenance to be completed on one unit while the second unit remains in service. The generator cooling intake dampers are in need of repair and contain an amount of non-friable asbestos that will be disposed of. An associated walkway presents a safety hazard to employees that must be addressed with the replacement of the dampers.

5.0 Feasibility Analysis

Appendix D provides a detailed feasibility analysis for the continued operation of the Rattling Brook hydroelectric development assuming that the planned capital refurbishment is undertaken. The results of the feasibility analysis show that the continued operation of the facilities is economical over the long term. Investing in the life extension of the Rattling Brook hydroelectric development ensures the continued availability of 69.4 GWH of low cost energy to the provincial electrical system.

The estimated levelized cost of energy from the facility over the next 25 years based upon the proposed capital expenditures is 1.7 cents per kWh. This energy is lower in cost than replacement energy from sources such as new hydroelectric developments and additional Holyrood thermal generation.

6.0 Project Execution

The refurbishment of the Rattling Brook hydroelectric development will be a large project executed over two construction seasons. The primary reason for completing the work in two phases is to reduce the spill associated with the construction downtime. The preferred construction window for Rattling Brook is approximately twelve to sixteen weeks each summer to minimize spill. If the plant is unavailable for a period outside of this window then the potential for spilling water is increased. Therefore, it is prudent to undertake this refurbishment over two construction seasons.

To complete the entire project in a single construction season would require a continuous twenty-five week period of downtime for the plant. It is estimated that 15 GWH of energy would be lost by extending the construction period nine weeks into either the spring or early winter.

To ensure that the work is ready to proceed when the construction window opens it is essential that all engineering design, specification documents and tenders are prepared in advance of the construction season. Advanced preparation of the detailed engineering specifications will also enhance the accuracy of cost estimates. Therefore, it is proposed to undertake the necessary engineering design work in the year prior to commencement of construction.

The following is the proposed high-level schedule for the work:

2005

- Complete engineering design of penstock and surge tank
- Complete electrical engineering final design
- Complete mechanical engineering final design
- Prepare and execute tenders necessary for 2006 construction

2006

- Install first section of penstock
- Refurbish main valves on units #1 and #2
- Refurbish runners on units #1 and #2
- Replace wicket gates on units #1 and #2
- Complete engineering design for Amy's control structure
- Complete engineering design for unit control panels
- Complete engineering design for governor upgrading
- Prepare and execute tenders necessary for 2007 construction

2007

- Install second section of penstock
- Refurbish surge tank
- Replace unit control panel
- Replace forebay water level control
- Refurbish Amy's control structure

7.0 Conclusion

To date preliminary engineering assessments have been completed on the civil, electrical and mechanical systems of the Rattling Brook hydroelectric development. The civil engineering studies have been completed with the assistance of outside experts and have identified the penstock replacement and surge tank refurbishment as being required to be completed within the next two years. This requires that the detailed engineering design and procurement process be completed in 2005.

Preliminary engineering assessments have also identified electrical and mechanical systems that should be addressed in the near future. It is proposed that the engineering work associated with these systems be completed in 2005 to ensure that the necessary work proceeds in either 2006 or 2007. This will allow Newfoundland Power to take advantage of the extended outages associated with the penstock replacement to complete all necessary electrical and mechanical work, and will avoid extended outages being required in future years.

The engineering assessments have identified work associated with the refurbishment and life extension of the Rattling Brook hydroelectric development. The feasibility analysis included in Appendix D verifies the financial viability of completing this project. The 69.4 GWh of energy produced at Rattling Brook each year plays a significant role in providing affordable energy to the customers of Newfoundland Power. Safety issues with the penstock and surge tank must be addressed in the near future. The planned schedule for project execution ensures the minimum amount of lost energy due to spill. Based upon these considerations, and others outlined in this report and attached assessments, the project is recommended to proceed in 2005.

Appendix A
Civil Engineering Reports

Prepared for

Newfoundland Power

55 Kenmount Road, St. John's, NL A1B 3P6

Energy Supply

Appendix 3


Attachment B, Appendix A

NP 2005 CBA

Consulting Services for

Surge Tank and Penstock Inspection – Rattling Brook Hydroelectric Development

Final Report



Prepared by

SGE Acres Limited

November 2003

P15310.00



SGE Acres

Table of Contents

| | | |
|----------|---|------------|
| 1 | Introduction | 1-1 |
| 1.1 | General..... | 1-1 |
| 1.2 | Description of the Facility | 1-1 |
| 2 | Results of the Inspection..... | 2-1 |
| 2.1 | Woodstave Portion of Penstock..... | 2-1 |
| 2.2 | Steel Portion of the Penstock | 2-2 |
| 2.2.1 | External..... | 2-2 |
| 2.2.2 | Internal | 2-3 |
| 2.3 | Surge Tank..... | 2-5 |
| 2.3.1 | Exterior Structure..... | 2-5 |
| 2.3.2 | Surge Tank Interior..... | 2-6 |
| 2.3.3 | Internal Riser..... | 2-6 |
| 2.3.4 | External Riser..... | 2-7 |
| 3 | Conclusions and Recommendations..... | 3-1 |
| 3.1 | Woodstave Penstock..... | 3-1 |
| 3.1.1 | General..... | 3-1 |
| 3.2 | Steel Portion of the Penstock | 3-1 |
| 3.2.1 | General..... | 3-1 |
| 3.2.2 | Aboveground Penstock | 3-1 |
| 3.2.3 | Underground Penstock..... | 3-2 |
| 3.3 | Surge Tank Structure, Surge Tank and Internal Riser | 3-2 |
| 3.4 | External Riser..... | 3-3 |

Appendix A – Photographs

Appendix B – Sketches

Appendix C – Thickness Measurements

Appendix D – Safety Reports

1 Introduction

1.1 General

Following the submission of a proposal on September 18, 2003, SGE Acres was contracted by Newfoundland Power (NP) to carry out an inspection of the penstock and surge tank at the company's Rattling Brook hydroelectric station in central Newfoundland. This report is the result of that inspection.

Prior to the site visit, as a requirement of the contract, SGE Acres submitted a project specific Health and Safety Plan to NP for review. SGE Acres also subcontracted inspection support relating to rigging and structure access to Remote Access Technology (Newfoundland) Limited of St. John's. This company also carried out ultrasonic thickness measurements as required by the contract.

The site inspections, which were carried out from October 14-17, 2003, comprised:

- a visual inspection of the exterior of the woodstave portion of the penstock
- a visual inspection of the interior of the surge tank and surge tank internal and external risers
- a visual inspection of the surge tank support structure
- a visual inspection of the interior and exterior of the steel portion of the penstock
- ultrasonic measurements of the wall thickness of the surge tank and steel penstock.

Mr. G. Saunders, P.Eng., of SGE Acres St. John's office carried out the inspections with the support of the subcontractor. Mr. G. Murray, P.Eng., was NP's representative during the inspections.

1.2 Description of the Facility

The Rattling Brook Hydroelectric Development, which is located near Norris Arm in central Newfoundland, has a capacity of 15 MW from two identical units fed from a bifurcation. The facility was commissioned in 1958. The water conveyance system consists of a combination woodstave and steel penstock and steel surge tank. The tank has four main components:

- Four support legs with a base diameter of 9.6 m (31'- 6") and height of 63.1m (207' ft)
- Steel tank which is 32.9 m (107'-9") high with a 6.1 m (20'- 0") ID steel shell and 6.6 m (21'- 8" ft) OD frost casing
- Internal riser with a diameter of 1.8 m(6'- 0") and height of 32 m (105ft)
- External riser with a diameter of 2.1 m (7'- 0"), 2.5 m (8'-4") diameter frost casing and height of 62 m (203'-9").

The tank and lower riser are protected with an external creosoted timber jacket.

The woodstave/steel penstock is approximately 1980 m (6500 ft) long. The first 1677 m (5550 ft) is woodstave with the first 634 m (2080 ft) having an internal diameter of 2.3 m (7.5 ft) and the remainder having a diameter of 2.1m (7 ft). The steel portion is 290 m (950 ft) long and about 192 m of this is upstream of the surge tank and is supported on steel saddles on concrete bases. The remaining 97.5 m (320 ft) downstream of the surge tank is buried.

2 Results of the Inspection

2.1 Woodstave Portion of Penstock

A visual inspection of the woodstave penstock from the intake thimble to the aboveground steel portion of the penstock was undertaken on October 14, 2003. This inspection was carried out while the penstock was pressurized so that an assessment of the water leakage and condition could be made under normal operating conditions. To visually inspect as much as possible Mr. Saunders and Mr. Murray walked opposite sides of the penstock.

The wood staves were found to be in poor condition. (See photo number 16) Many areas along the spring line were leaking. Most of the leaks were in end joints; however, there were leaks in longitudinal joints and displaced knots. As would be expected, the leakage intensified as the pressure in the penstock increased. (See photos number 17, 18 and 19)

The steel bands and rod ends were in good condition with little corrosion evident. The stud bolts holding the saddles together showed signs of corrosion.

Along the penstock, there was evidence of previous repairs which included steel plates and wooden wedges.

Two different styles of wooden saddles were used to support the penstock. In general both support types were in satisfactory condition. In some areas, the cradle blocks were cracked around the tie rods. These cracks in the wood were not serious enough to weaken the saddle load carrying capacity. A few of the saddles were in areas of high water flow, caused by leakage, where washout of the supporting gravel base was a concern. (See photo number 20)

Following the inspection, repairs were made to previously identified areas. Approximately 100 steel plates 1.6 mm thick ranging in size from 300 mm x 300 mm to 300 mm x 1200 mm were placed between the exterior of the penstock and the steel bands. Rubber gasket material was placed underneath the plates to make a seal. After the penstock was depressurized, 30 bundles of cedar roofing shingles were used to seal some of the remaining leaking areas. (See photos number 14 and 15)

2.2 Steel Portion of the Penstock

2.2.1 External

An external visual and ultrasonic thickness inspection of the steel penstock was performed. The initial inspection was made when the penstock was pressurized so that any areas of leakage could be identified.

The penstock changes from woodstave to a welded steel section as it nears the surge tank. There are two concrete anchor blocks and two slip type expansion joints in the aboveground section of the penstock. The penstock was shop fabricated in sections of approximately 30 to 40 feet and field welded together. The aboveground sections are supported on steel saddles and concrete base pads. The supports have a fabric bearing pad placed between the curved saddle plate and the penstock; there are no wear plates welded to the penstock at the saddle locations. The notes on the drawing indicate the bearing fabric is a bonded material containing asbestos. This original material was supplied in two pieces which were cemented to the saddle and penstock metal surfaces. During the initial inspection it was noted that in some areas the bearing fabric was pulled out from between the penstock and the saddle. These areas were revisited after the penstock was dewatered. It would appear that the longitudinal motion due to expansion and contraction has caused slippage of the fabric. (See photo number 11)

The above ground portion of the steel penstock runs from the first concrete anchor block, where the woodstave is connected, to the surge tank anchor block. The portion of the penstock downstream of the surge tank is underground and can be accessed through hatches in each leg of the bifurcation located inside the powerhouse, through the hatch at the bottom on the surge tank external riser or through the main penstock access hatch located downstream of the second anchor block.

The penstock is coated with a silver coloured painting system which is in good condition. There is one area near the first expansion joint where the paint is missing causing the steel plate to oxidize. (See photo number 21)

The welded joints are sound; however, there is evidence of out of roundness and peaking at many of the joints. None of these defects are detrimental to the performance of the penstock.

The penstock supports were in good condition with no signs of damage or corrosion. The concrete base pads and the anchor bolts were inspected and found to be in good condition.

The concrete anchor blocks were in good condition considering their age. One area requiring repair was found on the upstream end of the first anchor block. There was concrete damage and a small amount of water leakage at the 6 o'clock position.

The expansion joints were inspected and found to be tightened incorrectly. The packing ring was not pulled in evenly around the circumference indicating the tensioning bolts were not tightened evenly. The expansion joint located between the two anchor blocks was not leaking; however, the second expansion joint, located between the second anchor block and the surge tank, had a large leak at the top which appeared to have been leaking for some time. (See photo number 12)

The inspection hatch, which is located in the top of the penstock just downstream of the second anchor block, was found to be in good condition with no evidence of leakage.

After the penstock was dewatered, a second external inspection was completed. This included a further inspection of the saddles, ultrasonic thickness measurements of the penstock shell plate and the interior of the access hatch. The recorded thickness readings can be found in Appendix C.

2.2.2 Internal

After the penstock was dewatered, the inspection hatches in the powerhouse, surge tank and aboveground steel penstock were opened and the penstock allowed to ventilate naturally. The penstock was then checked for oxygen level before entering.

The inspection was performed in two phases. The first phase of the inspection was carried out by a two person team which included Mr. Saunders and an assistant from RAT. This phase involved the inspection of the interior of the penstock from the access hatch to the surge tank tee where the slope was shallow and rope access unnecessary.

The 23 m (75 ft) section of the penstock upstream of the access hatch has a steep slope and could not be accessed for inspection.

A thick cake-like deposit was found on the bottom of the penstock, at the base of the elbow located at anchor block number 2. This deposit was easily chipped away from the penstock exposing a layer of oxidized metal. (See photo number 10)

Moderate corrosion pitting of the interior surface was evident over the entire length. The surface was generally rough with no signs of erosion damage on any surfaces. There did not appear to be any increased corrosion activity at the welded joints.

The expansion joint appeared to be in good condition with no significant corrosion of the leading edge of the slip joint. There was no build up of sediment in the joint and it appeared free to move. (See photo number 7)

The surge tank tee had the most corrosion. The low pressure area just above the upstream entrance to the tee was covered in large scale deposits and carbuncles. (See photos number 8 and 9) Also areas around the bottom of the tee had thick cake deposits similar to those found at the base of the upstream elbow. Samples of this caked material were taken for future analysis.

Removal of the deposits and carbuncles revealed large deep pitting of the metal surface. The surface was very rough, making it impossible to accurately measure the depth of the corrosion.

The lower section of the penstock from the surge tank tee to the powerhouse required rope access and was completed by RAT during the second phase of the inspection. The interior of the underground portion of the penstock was found to be in a similar condition to the aboveground portion.

2.3 Surge Tank

The surge tank inspection was performed in several phases all of which required rope access and were completed by RAT personnel under the supervision of Mr. Saunders.

2.3.1 Exterior Structure

The surge tank is supported on four pipe legs with a system of diagonal rod braces and horizontal box sections used to transfer the wind loads to the foundations. There are two platform levels, one at the external riser expansion joint and the other at the base of the surge tank. The platform at the base of the tank also serves as the compression ring at the top of the support legs. Both platforms were found to be in good condition. (See photo number 6)

The caged ladder is attached to the leg on the southeast corner. The ladder has an anti-fall device, which has been condemned. Rope access was used to provide a safe means of ascending and descending the ladder.

An inspection of the surge tank tower was completed in 1998 by Varcon Inc. The results of this inspection were made available to the inspection team, and it was found that the issues which were found in 1998 were still evident during this inspection. In addition NP advised that a leak in the surge tank access opening located in the side of the hemispherical dish had caused a large buildup of ice during the 2002 -2003 winter. Mild temperatures caused a large piece of ice to fall and strike one of the tie rods connecting the external riser to the support leg and a horizontal support member. The tie rod was found hanging from its pin connection at the leg because the connection plate to the external riser had sheared at the weld. To remove the potential hazard, the tie rod was cut using a hand grinder and lowered to the ground. (See photo number 5)

The horizontal member located on the north face, second horizontal from the top has been bent and has two cracks in the welds which connect the clevis plates to the end plate of the box section. The two cracks, which are short in length, are located on the top of the joints and are consistent with an impact load acting on the top of the horizontal member. This joint is normally under compression and the welds under shear due to the horizontal compression

from the diagonal bracing and vertical dead load. It is not anticipated that the cracks will grow under normal live and dead loads. (See photo number 21)

As stated in the Varcon report the diagonal braces are sagging and have kinks and bends. At the point where they cross, there is noticeable metal loss due to the constant rubbing. (See photos number 3 and 4)

The frost casing is made of wood. There is noticeable deterioration of the wooden surface due to weathering. (See photo number 6)

The 2-inch pipe nipple connection to the external riser, located inside the small building at the base of the surge tank, was removed and replaced with a 2 inch 3000# capacity coupling and steel plug.

The cover of the external riser access hatch was heavily corroded.

2.3.2 Surge Tank Interior

Rope access was used to inspect the interior surface of the surge tank. The tank, roof structure and vent are in good condition for the upper 17 m with the painting system intact. The lower section is in fair condition with surface corrosion and pitting.

Thickness measurements were taken on the shell plate using an ultrasonic thickness meter. The measurements are listed in Appendix C.

2.3.3 Internal Riser

Rope access was used to inspect both surfaces of the riser. The upper tie rods and upper 17 m of the riser and external stiffener rings are all in good condition with the painting system intact. The lower section is in fair to poor condition with surface corrosion and pitting. (See photo number 2)

The connection to the hemispherical dished head is in fair condition with surface corrosion and pitting.

Thickness measurements were taken on the shell plate using an ultrasonic thickness meter. The measurements are listed in Appendix C.

2.3.4 External Riser

Rope access was used to inspect the interior surface of the external riser. The surface is rough and corroded over the entire length. The surface roughness was such that no thickness or reliable pitting measurements could be taken on the interior. Some ultrasonic thickness measurements were taken from the exterior near the access opening at the base of the riser and are listed in Appendix C.

3 Conclusions and Recommendations

3.1 Woodstave Penstock

3.1.1 General

Based on a visual inspection, the penstock is in poor condition. Leakage of the penstock at the springline is substantial. The surface quality of the wood is poor and the saddles, although substantially intact, are showing their age. Woodstave penstocks generally have a life of 50 years and this penstock is currently 45 years old. We recommend the penstock be replaced in the near future as we expect the leakage problem to worsen causing operational difficulties and increasing maintenance costs.

3.2 Steel Portion of the Penstock

3.2.1 General

The penstock is in fair condition, but there is evidence of deep isolated pitting of the internal surface. There are many areas of thick surface deposits such as carbuncles and thick cake.

There is no immediate danger to the structural integrity of the penstock shell but continued surface corrosion will reduce its service life. Failure due to pitting corrosion will not be catastrophic but will come in the form of pinhole leaks. The penstock life could be extended indefinitely provided the corrosion deposits are removed and the metal surface blast cleaned and coated with a high build epoxy coating system.

3.2.2 Aboveground Penstock

1. The saddle bearing fabric should be readjusted where it has moved out of position. Appropriate care in handling should be taken as the material contains asbestos and is considered hazardous.
2. Where paint is missing, it should be repaired.
3. The expansion joints should be checked periodically for leakage. During the inspection, the second expansion joint was disassembled, due to a large leak at the top, and repacked with new flax rope. Care was taken to tighten the packing evenly around the circumference.

4. Concrete repairs are needed on the upstream side of the first anchor block. There is leakage and deteriorated concrete at the 6 o'clock position.

3.2.3 Underground Penstock

See general recommendations Section 3.2.1.

3.3 Surge Tank Structure, Surge Tank and Internal Riser

1. The horizontal support which was damaged during the winter of 2002/03 should be replaced. One of the clevis ends is cracked at the welds. See location marked on Drawing No. P15310.00SK-01.
2. Due to the type of loading to which this member is subjected, we do not anticipate the cracks will grow and cause a failure of the connection. We recommend the structural member be replaced as early as practical.
3. The diagonal bracing is sagging and needs to be tightened. In some of the braced bays the bracing appears to be bent or permanently deformed. A replacement assessment should be made after tightening is attempted.
4. Due to the sagging of the diagonal rod bracing, there is metal loss where the rods cross. The material loss should be stopped by attaching a wear plate between the two rods. We recommend using 10mm thick HDPE plastic pads which can be attached to the rods with galvanized U-bolts.
5. There is a loose piece of expanded metal mesh on the revolving dolly located on the roof. A temporary repair was made during the inspection, but a permanent repair should be made as soon as practical.
6. The removed external riser tie rod should be replaced.
7. The wooden frost casing is dried out and should be replaced within the next 5 years.
8. The surge tank and internal riser are deteriorating and need to be blast cleaned and coated with a high build epoxy paint system. Some of the plate may require patching but an assessment is not possible without blast cleaning the surface. If necessary, the lower can sections could be replaced when the external riser is replaced.
9. General painting touch-up should be carried out where rusted areas appear. The coatings, both internal and external, should be inspected every five years. Maintenance of the coatings will prevent further corrosion of the steel and


avoid costly replacement of the surge tank, surge tank risers and its structural frame.


10. Concrete repairs identified in the 1998 Varcon report for the crack at the top of the surge tank anchor block and the tops of the concrete foundations under the surge tank legs should be completed in 2004. The cost to repair these areas is small. Delaying these repairs by many years will allow continued deterioration of the anchor block and its steel reinforcing and deterioration of the support grout under the surge tank legs. (See photos 3 and 4 in the 1998 Varcon report)

3.4 External Riser


The external riser is heavily corroded and is in the worst condition of all the fabricated steel components. In our opinion, it has deteriorated to the point that it cannot be repaired and should be replaced within the next 5 years.

Appendix A – Photographs






1. Rolling platform loose expanded metal mesh.




2. View of internal riser and surge tank from roof hatch.




3. Wear of rod bracing.




4. Wear of diagonal rod bracing.




5. External riser stabilizer rod connection to leg #4 at EL.140'.
Weld failure on connection to riser.




6. Compression ring and walkway at EL.207'.




7. Penstock expansion joint #2.




8. Carbuncles on surge tank tee looking up stream.



9. Surface corrosion of surge tank tee at access hatch.




10. Caked build up on floor of surge tank tee.




11. Penstock saddle slider.




12. Expansion joint #2 leaking at top.




13. Surge tank anchor block with shrinkage crack.




14. Wood stave penstock steel plate patch.




15. Wood stave penstock typical patch plate location marking.




16. Wood stave penstock surface condition.




17. Wood stave penstock leakage.



18. Wood stave penstock leakage.



19. Wood stave penstock leakage.



20. Wood stave penstock saddle deterioration.






21. Expansion joint #1 paint failure.





22. Horizontal brace north face at leg #3. Cracks in welds.

Appendix B – Sketches







NORTH ELEVATION




SITE LAYOUT




| | | | |
|-------------------|-------------|--|-----------------|
| SGE Acres | | NEWFOUNDLAND POWER | |
| SGE ACRES LIMITED | | RATTLING BROOK | |
| Project Manager | M. Woodford | 308' DIFFERENTIAL SURGE TANK ELEVATION AND LAYOUT | |
| Engineer | G. Saunders | | |
| Project Manager | G. Saunders | Project No. | P15310.00 |
| Date | DEC.01.2003 | Project No. | P15310.00-SK-01 |
| | | | |



— PENSTOCK ELEVATION —
NTS

| | | |
|--|---|--------------------------------|
|  SGE Acres <small>SGE ACRES LIMITED</small> | NEWFOUNDLAND POWER RATTLING BROOK | |
| | 7'-0" DIAMETER PENSTOCK AND SURGE TANK ELEVATION | |
| DESIGNER PREPARED BY CHECKED BY PROJECT MANAGER DATE | M. Woodford G. Saunders G. Saunders DEC.01.2003 | |
| AREA PROJECT No. P15310.00 | AREA PROJECT No. P15310.00 | DRAWING No. P15310.00-SK-02 |

Appendix C – Thickness Measurements



**Newfoundland Power
Rattling Brook Penstock Inspection**

Penstock Ultrasonic Thickness Readings (Starting From Surge Tank Going Upstream)

| Can Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness | Percentage Loss | Location |
|------------|---------------------|--|--------------------|-----------------|---|
| #1 | 0.446 | | 0.4375 | 0.00 | First Can Upstream of Surge Tank Anchor Block |
| #2 | 0.460 | 0.134 | 0.4375 | 0.00 | |
| #3 | 0.417 | 0.233 | 0.4375 | 4.69 | |
| #4 | 0.409 | 0.31 | 0.4375 | 6.51 | |
| #5 | 0.447 | 0.29 | 0.4375 | 0.00 | |
| #6 | 0.480 | 0.123 | 0.4375 | 0.00 | |
| #7 | 0.462 | 0.383 | 0.4375 | 0.00 | |
| #8 | 0.489 | | 0.4375 | 0.00 | |
| #9 | 0.466 | 0.342 | 0.4375 | 0.00 | |
| #10 | 0.466 | | 0.4375 | 0.00 | |
| #11 | 0.435 | 0.163 | 0.4375 | 0.00 | |
| #12 | 0.447 | | 0.4375 | 0.57 | |
| #13 | 0.445 | | 0.4375 | 0.00 | |
| #14 | 0.461 | | 0.4375 | 0.00 | |
| #15 | 0.435 | | 0.4375 | 0.00 | |
| #16 | 0.443 | | 0.4375 | 0.57 | |
| #17 | 0.450 | | 0.4375 | 0.00 | |
| #18 | 0.448 | | 0.4375 | 0.00 | |
| #19 | 0.437 | | 0.4375 | 0.00 | |
| #20 | 0.464 | 0.108 | 0.4375 | 0.11 | |
| #21 | 0.443 | | 0.4375 | 0.00 | |
| #22 | 0.456 | | 0.4375 | 0.00 | |
| #23 | 0.373 | 0.28 | 0.375 | 0.00 | |
| #24 | 0.360 | | 0.375 | 0.53 | |
| #25 | 0.361 | | 0.375 | 4.00 | |
| #26 | 0.338 | 0.173 | 0.375 | 3.73 | |
| #27 | 0.360 | 0.115 | 0.375 | 9.87 | |
| #28 | 0.354 | | 0.375 | 4.00 | |
| | | | | 5.60 | |

| Newfoundland Power Rattling Brook Penstock Inspection | | | | | |
|--|---------------------|--|--------------------|-----------------|----------|
| Penstock Ultrasonic Thickness Readings (Starting From Surge Tank Going Upstream) | | | | | |
| Can Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness | Percentage Loss | Location |
| #29 | 0.353 | | 0.375 | 5.87 | |
| #30 | 0.371 | 0.187 | 0.375 | 1.07 | |
| #31 | 0.338 | | 0.375 | 9.87 | |
| #32 | 0.361 | | 0.375 | 3.73 | |
| #33 | 0.359 | | 0.375 | 4.27 | |
| #34 | 0.376 | | 0.375 | 0.00 | |
| #35 | 0.364 | | 0.375 | 2.93 | |
| #36 | 0.377 | | 0.375 | 0.00 | |
| #37 | 0.364 | | 0.375 | 2.93 | |
| #38 | 0.355 | | 0.375 | 5.33 | |
| #39 | 0.357 | | 0.375 | 4.80 | |
| #40 | 0.359 | 0.21 | 0.375 | 4.27 | |
| #41 | 0.364 | 0.248 | 0.375 | 2.93 | |
| #42 | 0.356 | 0.171 | 0.375 | 5.07 | |
| #43 | 0.372 | | 0.375 | 0.80 | |
| #44 | 0.354 | | 0.375 | 5.60 | |
| #45 | 0.359 | | 0.375 | 4.27 | |
| #46 | 0.359 | | 0.375 | 4.27 | |
| #47 | 0.362 | | 0.375 | 3.47 | |
| #48 | 0.369 | | 0.375 | 1.60 | |
| #49 | 0.361 | 0.053 | 0.375 | 3.73 | |
| #50 | 0.371 | | 0.375 | 1.07 | |
| #51 | 0.356 | | 0.375 | 5.07 | |
| #52 | 0.355 | | 0.375 | 5.33 | |
| #53 | 0.369 | | 0.375 | 1.60 | |
| #54 | 0.305 | | 0.375 | 18.67 | |
| #55 | 0.367 | | 0.375 | 2.13 | |
| #56 | 0.371 | 0.109 | 0.375 | 1.07 | |

| Newfoundland Power Rattling Brook Penstock Inspection | | | | | |
|--|---------------------|--|--------------------|-----------------|--|
| Penstock Ultrasonic Thickness Readings (Starting From Surge Tank Going Upstream) | | | | | |
| Can Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness | Percentage Loss | Location |
| #57 | 0.388 | | 0.375 | 0.00 | |
| #58 | 0.378 | | 0.375 | 0.00 | |
| #59 | 0.369 | | 0.375 | 1.60 | |
| #60 | 0.361 | | 0.375 | 3.73 | |
| #61 | 0.370 | | 0.375 | 1.33 | |
| #62 | 0.371 | | 0.375 | 1.07 | |
| #63 | 0.367 | | 0.375 | 2.13 | |
| #64 | 0.376 | 0.248 | 0.375 | 0.00 | |
| #65 | 0.370 | | 0.375 | 1.33 | |
| #66 | 0.364 | | 0.375 | 2.93 | |
| #67 | 0.363 | | 0.375 | 3.20 | |
| #68 | 0.362 | | 0.375 | 3.47 | |
| #69 | 0.381 | | 0.375 | 0.00 | |
| #70 | 0.368 | 0.152 | 0.375 | 1.87 | |
| #71 | 0.359 | | 0.375 | 4.27 | |
| #72 | 0.370 | | 0.375 | 1.33 | |
| #73 | 0.360 | | 0.375 | 4.00 | |
| #74 | 0.361 | | 0.375 | 3.73 | |
| #75 | 0.371 | | 0.375 | 1.07 | |
| #76 | 0.370 | | 0.375 | 1.33 | |
| #77 | 0.395 | | 0.4375 | 9.71 | Thimble Attached to Woodstave Penstock |

Note - negative numbers represent thickness which exceed the thickness stated on the original drawings.


**Newfoundland Power
Rattling Brook Penstock Inspection**

Surge Tank Shell Ultrasonic Thickness Readings

| Can Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness inches | Percentage Loss | Location |
|------------|---------------------|--|------------------------------|-----------------|--------------------|
| 1 | 0.323 | 0.297 0.328 | 0.313 | 0.00 | Top of Surge Tank |
| 2 | 0.317 | | 0.313 | 0.00 | |
| 3 | 0.326 | | 0.313 | 0.00 | |
| 4 | 0.310 | | 0.313 | 0.96 | |
| 5 | 0.331 | | 0.313 | 0.00 | |
| 6 | 0.297 | | 0.313 | 5.11 | |
| 7 | 0.303 | | 0.313 | 3.19 | |
| 8 | 0.332 | | 0.344 | 3.49 | |
| 9 | 0.391 | | 0.375 | 0.00 | |
| 10 | 0.419 | | 0.406 | 0.00 | |
| 11 | 0.471 | | 0.438 | 0.00 | |
| 12 | 0.467 | | 0.468 | 0.21 | |
| 13 | 0.682 | | 0.688 | 0.87 | Hemispherical Head |

**Newfoundland Power
Rattling Brook Penstock Inspection**

External Riser Ultrasonic Thickness Readings




| Location Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness | Percentage Loss |
|-----------------|---------------------|--|--------------------|-----------------|
| 1 | 0.476 | | 0.531 | 10.36 |
| 2 | 0.473 | | 0.531 | 10.92 |
| 3 | 0.488 | 0.34 | 0.531 | 8.10 |
| 4 | 0.531 | 0.343 | 0.531 | 0.00 |
| 5 | 0.615 | 0.264 | Unknown | |

**Newfoundland Power
Rattling Brook Penstock Inspection**

Internal Riser Ultrasonic Thickness Readings

| Can Number | Thickness inches | Pit Indication Lowest Thickness inches | Original Thickness | Percentage Loss | Location |
|------------|---------------------|--|--------------------|-----------------|--------------|
| 1 | 0.347 | 0.313 | 0.313 | 0.00 | Top of Riser |
| 2 | 0.323 | | 0.313 | 0.00 | |
| 3 | 0.332 | | 0.313 | 0.00 | |
| 4 | 0.319 | | 0.313 | 0.00 | |
| 5 | 0.321 | | 0.313 | 0.00 | |
| 6 | 0.302 | | 0.344 | 12.21 | |
| 7 | 0.316 | | 0.344 | 8.14 | |
| 8 | 0.311 | | 0.375 | 17.07 | |
| 9 | 0.291 | | 0.375 | 22.40 | |
| 10 | 0.344 | | 0.375 | 8.27 | |
| 11 | 0.373 | | 0.375 | 0.53 | |
| 12 | 0.397 | | 0.375 | 0.00 | |
| 13 | 0.405 | | 0.375 | 0.00 | |

Appendix D – Safety Reports






50 Pippy Place, St. John's, Newfoundland, Canada A1B 4H7

Ph: 709 738 6353 Fax: 709 738 6355

e-mail: info@ropeaccess.ca

October 22, 2003



Greg,

Here is all the information gathered during the inspection. It was a pleasure working with you, not to mention, the chuckle I got when I saw you in your \$0.50 rain gear made the trip worthwhile. I look forward to working with you again in the future.

Cheers,

JB DelRizzo

General Manager

Remote Access Technology (Newfoundland) Inc.

Prejob Site Meeting Contractor Safety Checklist



Contractor's Name: SGE-Acces and Remote Access Technology
Location: Rattling Brook
Date: Oct 14/03

| | |
|---------------------------------------|--|
| Personal Protective Equipment | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| First Aid Equipment | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Fire Protection | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> N/A |
| Emergency Communication and Response | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Fall Protection | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Minimum Approach Distances Maintained | <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A |
| Tail Board / Tool Box Meetings | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Warning /Danger Signs | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |
| Public Safety | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> N/A |

Comments:

Remote access conducted their own Tool box meeting. Completed
prejob / hazard checklist.
Lock-out Provided by NF Power to enter tank and perstock.

Action taken to address any issues:

Signature of Owner's Representative:

Signature of Contractor's Supervisor:

White: Originator, Yellow: Contractor

Form No. 399 Revised 03/28/01

Remote Access Technology (Newfoundland) Inc.

Confined Space Entry Checklist ☒

Yes/No

| | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Personnel entering confined space have been trained in the hazards of confined space entry. |
| <input checked="" type="checkbox"/> | Approved Permit to Work has been obtained. |
| <input checked="" type="checkbox"/> | Designated trained standby person assigned to standby the confined space entrance at all times. |
| <input checked="" type="checkbox"/> | Oxygen/Gas detector is present and calibrated. |
| N/A | <input checked="" type="checkbox"/> Minimum of two explosion-proof portable lights in use. |
| N/A | <input checked="" type="checkbox"/> Explosion-proof personal radios in use. |
| N/A | <input checked="" type="checkbox"/> Appropriate warning signs/barricades in use. |
| <input checked="" type="checkbox"/> | Portable tripod with a combined fall arrestor-retrieving winch or similar system in use. |
| <input checked="" type="checkbox"/> | One Company approved full body harness in use per person. |
| <input checked="" type="checkbox"/> | Internal pressure checked and vented before removing fastening devices on confined space. |
| <input checked="" type="checkbox"/> | Designated standby person will monitor air quality upon entry and each re-entry. |
| <input checked="" type="checkbox"/> | Oxygen levels is between 19.5% to 22% DO NOT ENTER IF ABOVE OR BELOW AFOREMENTIONED RANGE! |
| <input checked="" type="checkbox"/> | Air Quality is tested for H2S / Explosive gases – None Present. |
| <input checked="" type="checkbox"/> | Confined space will be sounded for fluid before entered. Flotation device will be worn if a drowning hazard exists. |
| <input checked="" type="checkbox"/> | Standby person will maintain constant radio contact with persons in confined space and control room. |
| <input checked="" type="checkbox"/> | Standby person knows how to raise the alarm if person inside or confined space require emergency assistance and knows not to enter confined space until assistance arrives. |
| <input checked="" type="checkbox"/> | Adequate rescue equipment is readily available and standby person is familiar with its use. |
| <input checked="" type="checkbox"/> | Standby person will keep a tally of number / names of persons inside confined persons. |
| <input checked="" type="checkbox"/> | Standby person will notify Person in Charge for a relief watchman to be assigned as relief and wait until being properly relieved before leaving the post. |
| <input checked="" type="checkbox"/> | Adequate handover and safety briefing will be conducted with any person who relieves the standby person or crew members working in the confined space. |
| <input checked="" type="checkbox"/> | Explosion proof ventilation will be used for a continuous supply of fresh air unless sufficient airflow is obtained through a free flow process. |
| N/A | <input checked="" type="checkbox"/> No source of ignition will be introduced into a confined space where flammable vapors or gasses may be present. |
| <input checked="" type="checkbox"/> | All pipelines discharging into that space will be closed with blind flanges, plugs or valves and energy isolation signs and tags posted. |
| N/A | <input checked="" type="checkbox"/> If torch cutting or welding is carried out on pipelines passing through confined spaces, they will be isolated, purged if necessary, energy isolations signs and tags posted prior to the hot work starting. |
| N/A | <input checked="" type="checkbox"/> Oxygen/ Acetylene hoses will be removed from confined space where during the extended breaks and air retested for gas before reentry. |
| <input checked="" type="checkbox"/> | The time of opening or closing a confined space entry or exit of personnel will be recorded at the manned control point (Control Room, Radio Room, etc.) |
| | |
| | |

Person in charge: J.B. DELRIZZO (name) [Signature] (sign)

Date: OCT 16 / 03 Time: 4:48 PM

Standby Person: STEVE DEATHE (name) [Signature] (sign)



ANNEX A - Code of Practice

Doc: 13354.1

Date: 2003-04-08

Reviewed by:

MDS

Approved by:

ADB

TAILGATE SAFETY MEETING REPORT

Date of Meeting:

Oct 15/03

Time of Meeting:

8:30

(am/pm)

Location of Meeting:

Rattling brook P.S. / MFLD**Employees Present:**

1 Steve Deathe
 2 J.R. Delrizzo
 3 Pat Heath Pat Heath
 4 Hayward Miller
 5 G. Murray
 6 G. Saunders
 7 _____
 8 _____

9

10

11

12

13

14

15

16

Items Discussed

1 Review unsafe situations mentioned at previous meeting

2 Review any safety suggestions from the crew

3 Review of hazards expected in upcoming work

4 Proper P.P.E., radio communication, First Aid kit in the truck5 layards on all tools, all rigging assessed by Level 3 climber6 install fall arrest system for climbing ladders7 Follow all TATA GUIDELINES FOR ACCESS METHODS

8

Comments

This safety meeting conducted by:

COPIES TO: OFFICE (ORIGINAL)

Safety Coordinator



Safety Policy and Procedures Manual

ANNEX A – Code of Practice

Doc: 13354.1

Date: 2003-04-08

Reviewed by:

MDS

Approved by:

ADB

JOB HAZARD ANALYSIS

Date: Oct 15/03 Time: 8:30 Location: Rattling Brook P.S./MFLD

Supervisor: _____

Job Description: Inspection of surge tank & penstock (visual & U.T.)

Work Crew (List names & have employees initial on same line)

Completed By: Steve DeAtheName Steve DeAtheName: Pat HeathName: G. MurrayName J.B. DelrizzoName: Hayward MillerName: G. Sanders

| Permits Required | | | yes | no | n/a | Other Checks | | | yes | no | n/a |
|------------------|--|--|-------------------------------------|-------------------------------------|--------------------------|-----------------------------------|--|--|-------------------------------------|-------------------------------------|-------------------------------------|
| General Work | | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Safety Operator Required | | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Hot Work | | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Hazardous Material Present | | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Entry | | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Evac./Assembly Area Confirmed | | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| RPP <u>Scba</u> | | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Job Objective Discussed with Crew | | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Other () | | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Is Crew Aware of MSDS Location | | | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

| yes | no | n/a | |
|-------------------------------------|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Proper permits obtained/signed? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | RPP equipment required? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Confined space entry permit req'd? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Staging required / OK Tag? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Personal fall protection req'd? |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Staging(s) inspected & confirmed adequate by |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Evacuation/assembly area known? |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Eyewash/safety shower location known? |
| <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | Hot work requirements? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Protective equipment required? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Location of fire equipment known? |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Equipment blinded or not? |
| <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | Proper lighting for work? |
| <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Conflicting jobs in area? |
| | | | Safety behaviors discussed |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Proper PPE Used |
| | | | (eye/hearing/gloves/nomex/etc.) |
| <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Housekeeping (tripping hazards/hoses/leads) |

Comments / Notes / Actions

Scba's on standby for internal workoutside natural/internal headlamps
Flashlights

Hazard recognized/corrective action

Rope Hazard Identification & control

Hazard

Rank

Corrective Actions

Pinch pointsAproper rigging / assessed by Level 3Sharp edgesAproper rope protection

Considerations / Comments:


Corrective actions carried out? Yes No If no, state reason below:

Rank: A = could easily result in a fatality

B = could result in serious injury

C = could result in minor injury

Form 12-6-19



February 18, 2004
P15602.00

Newfoundland Power
P.O. Box 8910
55 Kenmount Road
St. John's, NL A1B 3P6

Attention: Mr. G. Humby, P. Eng.

Dear Sir:

**Rattling Brook Development
Selection of optimum penstock diameter**

Newfoundland Power (NP) proposes to replace the existing woodstave penstock at the Rattling Brook Development with a new steel penstock. NP requested SGE Acres to carry out a study to determine the optimum diameter for the replacement penstock, and to comment on the feasibility of replacing the buried steel section. For the woodstave portion, the analysis requested by NP is incremental; energy benefits are taken to be incremental to existing, and costs are incremental to replacement costs. As a separate item, NP requested a cost to replace the external riser of the surge tank.

This letter report documents the findings of the study.

1 System Description

The Rattling Brook station is located near Norris Arm, on the northeast coast of the Island of Newfoundland. It was built in 1958, with a nominal installed capacity of 12.75 MW provided by two units. The nameplate capacity is 15.1 MW; the nameplate unit capacities are 7.5 MW and 7.6 MW. The gross head is 99 m.

The woodstave penstock is 1693 m long, 1054 m of 7 ft diameter, and 639 m of 7 1/2 ft diameter. (Penstock diameters are given here in imperial units for consistency with design drawings and previous reports.) A 7 ft steel section 50 m long joins provides the connection from the intake to the woodstave section. The penstock winds along a river valley, with numerous changes to the alignment.

The last 309 m of penstock is a steel section, of which the last 115 m from the surge tank to the units is buried. The penstock bifurcates about 16 m upstream of the units into two sections leading to the two units, each section 4 ft 9 in. inside diameter. A butterfly valve is located just upstream of each of the units.

The steel section as well as the surge tank were inspected by SGE Acres in the fall of 2003, and a separate report documents the findings and recommendations arising from those inspections.

2 Methodology

2.1 Energy Benefits

Based on previous reports and practical considerations of the maximum size of penstock that could be installed at the Rattling Brook location, diameters in the range of 7 1/2 ft to 11 ft were considered. An energy simulation model of the Rattling Brook system previously developed for NP for a Water Management Study was updated and used to estimate the available energy¹.

The head losses in the existing and proposed system required for the modeling were estimated using data from index testing in the 1980's by NP,² from efficiency testing carried out by SGE Acres for NP in 2000, and from standard references. Only the woodstave section was assumed to be replaced. Curves of energy benefit as a function of penstock diameter were developed from the results. The sensitivity to higher or lower friction factors was checked.

The effect on available capacity of head loss reduction was taken into account in the modeling. The capacity increases from 11.3 MW in the existing case to 12.4 MW with a penstock with a diameter of 8 ft. With a 10 ft diameter penstock, the capacity is 14.2 MW. With two units of about 7.5 MW each, the maximum capacity would be about 15 MW. (These calculations assume there are no other limiting factors on installed capacity.)

In addition, the Water Management Study carried out for NP had indicated that the mean annual runoff might be higher than the estimated value of 900 mm/yr. Given this possibility, the sensitivity of the results to a mean annual runoff 10 percent higher than previously estimated was checked.

The energy benefit of replacing the intake and the 50 m steel section of the existing penstock connecting the intake to the woodstave penstock was not calculated, since it is clear that the cost of replacing the intake and/or that short section of steel would far exceed the benefits. At present there is no requirement to replace these components, and therefore the value of the incremental benefits would have to exceed the total cost of replacement, not just the incremental cost above replacing the existing intake and short length of steel penstock.

2.2 Costs

A preliminary design considering plate thickness for hoop stress and material handling requirements was prepared for each of the optional diameters. Following discussions with NP, a plate thickness of 9.5 mm (3/8 in) was assumed for all diameters. The required weight of steel was then calculated. Costs were developed from experienced fabricators and from estimates prepared by NP. Cost per unit weight of steel was the most comparable measure between the projects referenced by fabricators.

¹ Acres International, *Water Management Study*, Report prepared for Newfoundland Power, Dec. 2000.

² Newfoundland Power, *Rattling Brook Report to Increase Plant Capacity by Increasing Flow area*, Feb. 1984

The future cost of steel plate is uncertain, but the consensus among suppliers is that it will certainly rise. The costs were thus re-estimated assuming increases in steel supply costs of 20% and 50%. These lead to total penstock cost increases of 10% and 25%. The 10 percent increase was used as the base case, and a 25 percent increase as a sensitivity check. An installation cost per unit weight of steel derived from NP estimates compared well with the information provided by the fabricators. The analysis used a base supply cost of \$2600/tonne and an install cost of \$3000/tonne. Our estimated costs are summarized in Table 1.

The budget price for replacing the external riser and expansion joint and installing new insulation and cladding is \$430,000 (no HST). This estimate is provided for information, as requested, and is not used elsewhere in this report.

2.3 Economic Analysis

The annual value of the energy benefits was calculated assuming two marginal values of energy, \$0.0553/kWh and \$0.0771/kWh. A discount rate of 8.52 percent and periods of 25 and 50 years were considered to determine the present worth value of the benefits. Sensitivity checks were done with discount rates of 7.5 and 9.5 percent and periods of 50 years.

The net present worth value for each penstock replacement diameter, as well as the incremental (stepwise) net benefit, were then tabulated, and the results plotted. The optimal diameter was taken as the diameter at which the net present worth is highest, and the incremental benefit of the increase in diameter exceeds the incremental cost.

3 Results

The curve of energy benefits as a function of penstock diameter is shown in Figure 1. This shows that the benefits continue to increase as the diameter increases, but the curve flattens out at the larger diameters. The shape is similar for the sensitivity to mean annual runoff. The curves start at 8.0 ft since the 7.5 ft diameter is the diameter assumed to replace the existing penstock.

The incremental energy benefits over the existing simulated energy of 63.5 GWh range from 1.9 to 5.7 GWh. As Figure 2 shows, the lowest energy is 65.4 GWh, for the 8 ft diameter case, for the highest friction factor, and the maximum is 69.7 GWh for the 11 ft diameter case with the lowest friction factor. The results for 11 ft are included in the plot but were not used further in the analysis since it became clear that the incremental benefits would only outweigh the incremental costs for the most attractive economic conditions. The cost assumptions are also not likely to apply at such a large diameter.

For the case with an increase of mean annual runoff of 10 percent, the average annual energy for the existing case is also higher, at 66.5 GWh. This value increases to 72.9 GWh with a 10 ft diameter penstock, a difference of 6.4 GWh annually. These results assume a Manning's n friction factor of 0.013.

The curve of costs as a function of penstock diameter is shown in Figure 2. The cost estimates are most accurate for diameters in the middle of the study range (8.5-9.0 ft). The penstock weights are calculated based on preliminary design of the penstock; the curves are linear because a plate thickness of 9.5 mm is used for all diameters. Plate thinner than 9.5 mm may be acceptable for smaller diameters; thicker shell plate may be required for larger diameters to permit suitably long spans between ring girder supports.

Figure 3 shows the net benefits (energy benefits minus cost) for the periods and values of energy provided by NP. These curves are all for the specified discount rate of 8.52 percent. As long as the slope of the curve remains positive, the investment is attractive, that is, the incremental energy benefits of an increase in diameter of 1/2 ft are less than the incremental costs. The diameter at which the net present value reaches its maximum is the optimal diameter.

For the cases presented in Figure 3, the optimal diameter is 9.5 ft, except for the case with the lower value of energy and shorter payback period. The net present value of the benefits ranges from about \$1.5 million to over \$3 million, depending on the economic factors. Figure 4 is a similar figure including results for higher and lower discount rates.

The results for the base case and all the sensitivities are summarized in Table 1. Figures 5 shows the range of net benefits for all the cases in Table 1, and Figure 6 shows the incremental net benefits. The optimum diameter is the one at which the incremental net benefit is positive.

For the combinations considered, these figures show that the minimum optimal diameter is 9 ft, and the maximum is 10 ft. The absolute range of net benefits is wide, from less than \$1 million to nearly \$4 million. The lowest net benefit is for an 8 ft diameter penstock, assuming a higher friction factor, the lower value of energy and shorter period (all other parameters at base case values). The highest net benefit is for a 10 ft diameter penstock, assuming increased runoff, higher energy values, lower discount rate, and longer period.

Although the absolute range is wide, the difference in net present value in the 9 ft to 10 ft range for any individual case is small, generally less than 5 percent of the cost. It therefore would not take much change in cost or economic assumptions to shift the optimal diameter within this range.

3.1 Energy benefit of replacement of steel section

During the course of this study it was determined that up to half the head loss in the system is occurring in the buried section downstream of the surge tank. It is not clear whether these occur in the buried penstock, at the bifurcation, in the short 4 1/2 ft diameter sections below the bifurcations, or in the butterfly valves. There is some indication that the excess loss may be occurring between the bifurcation and the unit, but this requires confirmation.

Organic/mineral deposits were found in parts of the steel section, and these are likely to be contributing to the losses.

Even if the total head losses in the system can be reduced by around 3 percent by replacing the steel section, bifurcation and valves, the net present value of the energy benefits would be in the range of \$1 to \$2 million. This amount is far below the capital cost that would be required to replace this section.

4 Conclusions and Recommendations

4.1 Conclusions

The conclusions of this study are as follows.

- The net benefits of replacing the existing penstock with one of a larger diameter for all cases are positive, ranging from less than \$1 million to nearly \$4 million. The net benefits continue to increase for all cases for pipe diameters up to at least 9 ft.
- The net present value of the benefits is within the accuracy of the estimates in the range of 9 ft to 10 ft. For the combinations considered, a 9 1/2 ft diameter penstock is a reasonable choice. A more detailed design and cost analysis is required to confirm this.
- Factors that favour a 10 ft diameter penstock are a higher value of energy, a higher frictional resistance (for example, if deposits form) and a lower discount rate.
- If the above factors tend in the opposite direction, a smaller diameter penstock will be favoured. Also, if a plate thickness of 9.5 mm is not acceptable for a larger pipe without a large number of ring girders, then a smaller penstock will be favoured.

4.2 Recommendations

The recommendations arising from this study are as follows.

- A detailed cost estimate should be prepared for the 9 1/2 ft diameter penstock to confirm the values used in this study.
- Head loss tests should be conducted on the lower section of the penstock, similar to those conducted in the 1980's. These tests should measure losses upstream and downstream of the bifurcation and of the butterfly valves separately, to isolate the losses. If the location and causes of the excess losses can be determined, then NP can take remedial action. Also, if losses are greater than previously measured, then accumulations in or deterioration of the steel penstock are likely causes and NP can consider remediation (e.g., pressure washing, coating).
- NP should research design information, past load rejection histories and/or conduct load rejection tests to confirm the capacity of the components that are to remain. The preliminary penstock design for this study was based on load rejection surge pressure information provided in drawing 6-601-22-5. It is unclear if the surge pressure line on this drawing

February 18, 2004

refers to one or two-unit load rejection and hence if the existing steel penstock and surge tank are suitable for a two-unit load rejection. Determining existing surge capacity was beyond the scope of this study but will have a significant impact on the replacement penstock. The energy benefits of the larger diameter penstocks are calculated assuming that 15 MW capacity is available. If total plant output must be limited so that the existing steel penstock and surge tank will not be over pressurized, then larger diameter penstocks will not be economically feasible.

Yours very truly,



S.H. Richter, P.Eng.
Project Manager

SHR:sjc

Attachments

Table 1
Cost Estimates

| Penstock Diameter (ft) | 7.5 | 8.0 | 8.5 | 9.0 | 9.5 | 10.0 |
|-------------------------------------|---------------------|---------------------|---------------------|---------------------|---------------------|---------------------|
| Weight of Steel Shell (lbs) | | | | | | |
| Starting Shell Thickness (in) | 2,016,647 | 2,150,381 | 2,284,115 | 2,417,848 | 2,551,582 | 2,685,316 |
| Ending Shell Thickness (in) | 3/8 | 3/8 | 3/8 | 3/8 | 3/8 | 3/8 |
| Weight [tonnes] | 914.7 | 975.4 | 1036.1 | 1096.7 | 1157.4 | 1218.0 |
| Supply Cost, Jan. 2004 [\$2600/t] | \$ 2,378,000 | \$ 2,536,000 | \$ 2,694,000 | \$ 2,851,000 | \$ 3,009,000 | \$ 3,167,000 |
| Install Cost [\$3000/t] | \$ 2,744,000 | \$ 2,926,000 | \$ 3,108,000 | \$ 3,290,000 | \$ 3,472,000 | \$ 3,654,000 |
| Total Cost, Jan 2004 | \$ 5,122,000 | \$ 5,462,000 | \$ 5,802,000 | \$ 6,141,000 | \$ 6,481,000 | \$ 6,821,000 |
| Incremental Cost | \$ - | \$ 340,000 | \$ 680,000 | \$ 1,019,000 | \$ 1,359,000 | \$ 1,699,000 |
| Supply Cost +10% [\$2860/t] | \$ 2,616,000 | \$ 2,790,000 | \$ 2,963,000 | \$ 3,137,000 | \$ 3,310,000 | \$ 3,484,000 |
| Install Cost [\$3000/t] | \$ 2,744,000 | \$ 2,926,000 | \$ 3,108,000 | \$ 3,290,000 | \$ 3,472,000 | \$ 3,654,000 |
| Total Cost (+ 10% on supply) | \$ 5,360,000 | \$ 5,716,000 | \$ 6,071,000 | \$ 6,427,000 | \$ 6,782,000 | \$ 7,138,000 |
| Incremental Cost per 1/2 ft | \$ - | \$ 356,000 | \$ 355,000 | \$ 356,000 | \$ 355,000 | \$ 356,000 |
| Supply Cost + 25% [\$3250/t] | \$ 2,973,000 | \$ 3,170,000 | \$ 3,367,000 | \$ 3,564,000 | \$ 3,761,000 | \$ 3,959,000 |
| Install Cost [\$3000/t] | \$ 2,744,000 | \$ 2,926,000 | \$ 3,108,000 | \$ 3,290,000 | \$ 3,472,000 | \$ 3,654,000 |
| Total Cost (+25% on supply) | \$ 5,717,000 | \$ 6,096,000 | \$ 6,475,000 | \$ 6,854,000 | \$ 7,233,000 | \$ 7,613,000 |
| Incremental Cost | \$ - | \$ 379,000 | \$ 758,000 | \$ 1,137,000 | \$ 1,516,000 | \$ 1,896,000 |

Note: These estimates assume that 3/8 in plate is used for all penstock diameters.

Figure 1 is a line graph showing the relationship between Average Annual Energy (GWh) and New steel penstock diameter (ft) for three different penstock materials: 100% steel, 75% steel/25% FRP, and 50% steel/50% FRP. The x-axis represents the New steel penstock diameter (ft) from 7.5 to 12.0. The y-axis represents the Average Annual Energy (GWh) from 65.0 to 70.0. The graph shows that as the penstock diameter increases, the average annual energy also increases for all three materials. The 100% steel material consistently yields the highest energy output, followed by the 75% steel/25% FRP material, and then the 50% steel/50% FRP material.

| New steel penstock diameter (ft) | 100% steel (GWh) | 75% steel/25% FRP (GWh) | 50% steel/50% FRP (GWh) |
|----------------------------------|------------------|-------------------------|-------------------------|
| 8.0 | 66.0 | 66.0 | 66.0 |
| 8.5 | 67.0 | 67.0 | 67.0 |
| 9.0 | 68.0 | 68.0 | 68.0 |
| 9.5 | 68.5 | 68.5 | 68.5 |
| 10.0 | 69.0 | 69.0 | 69.0 |
| 11.0 | 69.5 | 69.5 | 69.5 |

F:\SGEAcres\Projects\2004\15602.00 Rattling Brook Penstock\Hydrotech\richter\Base case and sens\Base Case, Figs 1-4.xls\Fig 1

Figure 2: Cost as a function of diameter




Figure 3: Net Benefits, Varying \$/kWh and period
(energy incremented to existing)





Figure 4: Net Benefits, Varying Discount Rate and \$/kWh
(energy incremented to existing)



Case and Sensitivities

| | Diam. new steel penstock (ft) | Net Benefits 25 Years | | Incremental - Stepwise 25 Years | | Net Benefits 50 Years | | Incremental - Stepwise 50 Years | |
|---------------------------------------|--|--------------------------|-------------|------------------------------------|-------------|--------------------------|-------------|------------------------------------|-------------|
| | | Energy value (\$/kWh) | 0.0553 | Energy value (\$/kWh) | 0.0553 | Energy value (\$/kWh) | 0.0553 | Energy value (\$/kWh) | 0.0553 |
| Base Case | | | | | | | | | |
| Cost | 8 | \$1,113,000 | \$1,692,000 | \$1,113,000 | \$1,692,000 | \$1,303,000 | \$1,957,000 | \$1,303,000 | \$1,957,000 |
| Discount Rate | 8.5 | \$1,380,000 | \$2,204,000 | \$267,000 | \$512,000 | \$1,650,000 | \$2,581,000 | \$347,000 | \$624,000 |
| Friction factor | 9 | \$1,476,000 | \$2,478,000 | \$96,000 | \$274,000 | \$1,805,000 | \$2,937,000 | \$155,000 | \$356,000 |
| Runoff | 9.5 | \$1,460,000 | \$2,595,000 | (\$16,000) | \$118,000 | \$1,833,000 | \$3,116,000 | \$28,000 | \$179,000 |
| | 10 | \$1,330,000 | \$2,555,000 | (\$130,000) | (\$41,000) | \$1,732,000 | \$3,116,000 | (\$101,000) | (\$98) |
| Sensitivity to increased cost | | | | | | | | | |
| Cost | 8 | \$1,090,000 | \$1,669,000 | \$1,090,000 | \$1,669,000 | \$1,280,000 | \$1,934,000 | \$1,280,000 | \$1,934,000 |
| Discount Rate | 8.5 | \$1,333,000 | \$2,157,000 | \$243,000 | \$488,000 | \$1,603,000 | \$2,534,000 | \$323,000 | \$600,000 |
| Friction factor | 9 | \$1,406,000 | \$2,408,000 | \$73,000 | \$251,000 | \$1,735,000 | \$2,867,000 | \$132,000 | \$333,000 |
| Runoff | 9.5 | \$1,366,000 | \$2,501,000 | (\$40,000) | \$94,000 | \$1,739,000 | \$3,022,000 | \$4,000 | \$155,000 |
| | 10 | \$1,212,000 | \$2,437,000 | (\$154,000) | (\$65,000) | \$1,614,000 | \$2,998,000 | (\$125,000) | (\$24,000) |
| Sensitivity to friction factor | | | | | | | | | |
| Cost | 8 | \$1,452,000 | \$2,165,000 | \$1,452,000 | \$2,165,000 | \$1,686,000 | \$2,491,000 | \$1,686,000 | \$2,491,000 |
| Discount Rate | 8.5 | \$1,662,000 | \$2,598,000 | \$210,000 | \$433,000 | \$1,969,000 | \$3,026,000 | \$283,000 | \$535,000 |
| Friction factor | 9 | \$1,702,000 | \$2,793,000 | \$40,000 | \$195,000 | \$2,060,000 | \$3,293,000 | \$91,000 | \$267,000 |
| Runoff | 9.5 | \$1,629,000 | \$2,832,000 | (\$72,000) | \$39,000 | \$2,024,000 | \$3,363,000 | (\$36,000) | \$90,000 |
| | 10 | \$1,443,000 | \$2,712,000 | (\$186,000) | (\$120,000) | \$1,860,000 | \$3,294,000 | (\$165,000) | (\$89,000) |
| Sensitivity to friction factor | | | | | | | | | |
| Cost | 8 | \$718,000 | \$1,141,000 | \$718,000 | \$1,141,000 | \$857,000 | \$1,335,000 | \$857,000 | \$1,335,000 |
| Discount Rate | 8.5 | \$1,097,000 | \$1,810,000 | \$380,000 | \$669,000 | \$1,331,000 | \$2,136,000 | \$475,000 | \$802,000 |
| Friction factor | 9 | \$1,250,000 | \$2,163,000 | \$153,000 | \$353,000 | \$1,550,000 | \$2,581,000 | \$218,000 | \$445,000 |
| Runoff | 9.5 | \$1,290,000 | \$2,359,000 | \$41,000 | \$196,000 | \$1,641,000 | \$2,849,000 | \$92,000 | \$268,000 |
| | 10 | \$1,217,000 | \$2,397,000 | (\$73,000) | \$38,000 | \$1,604,000 | \$2,938,000 | (\$37,000) | \$89,000 |
| Sensitivity to average runoff | | | | | | | | | |
| Cost | 8 | \$1,283,000 | \$1,928,000 | \$1,283,000 | \$1,928,000 | \$1,495,000 | \$2,224,000 | \$1,495,000 | \$2,224,000 |
| Discount Rate | 8.5 | \$1,719,000 | \$2,676,000 | \$436,000 | \$748,000 | \$2,033,000 | \$3,115,000 | \$538,000 | \$891,000 |
| Friction factor | 9 | \$1,928,000 | \$3,108,000 | \$209,000 | \$432,000 | \$2,315,000 | \$3,649,000 | \$282,000 | \$534,000 |
| Runoff | 9.5 | \$1,912,000 | \$3,226,000 | (\$16,000) | \$118,000 | \$2,343,000 | \$3,828,000 | \$28,000 | \$179,000 |
| | 10 | \$1,838,000 | \$3,264,000 | (\$73,000) | \$38,000 | \$2,306,000 | \$3,916,000 | (\$37,000) | \$89,000 |
| Sensitivity to discount rate | | | | | | | | | |
| Cost | 8 | | | | | \$1,510,000 | \$2,245,000 | \$1,510,000 | \$2,245,000 |
| Discount Rate | 8.5 | | | | | \$1,944,000 | \$2,990,000 | \$434,000 | \$745,000 |
| Friction factor | 9 | | | | | \$2,162,000 | \$3,435,000 | \$218,000 | \$444,000 |
| Runoff | 9.5 | | | | | \$2,237,000 | \$3,680,000 | \$76,000 | \$245,000 |
| | 10 | | | | | \$2,168,000 | \$3,724,000 | (\$69,000) | \$44,000 |
| Sensitivity to discount rate | | | | | | | | | |
| Cost | 8 | | | | | \$1,141,000 | \$1,732,000 | \$1,141,000 | \$1,732,000 |
| Discount Rate | 8.5 | | | | | \$1,420,000 | \$2,260,000 | \$278,000 | \$528,000 |
| Friction factor | 9 | | | | | \$1,524,000 | \$2,546,000 | \$105,000 | \$286,000 |
| Runoff | 9.5 | | | | | \$1,515,000 | \$2,673,000 | (\$9,000) | \$127,000 |
| | 10 | | | | | \$1,399,000 | \$2,638,000 | (\$126,000) | (\$35,000) |

Figure 5: Net Benefits





Figure 6: Incremental net benefits



RATTLING BROOK

REPORT

TO

INCREASE PLANT CAPACITY

BY

INCREASING FLOW AREA

A. Greeley

1982 10 08

Revised 1984 02 29

TABLE OF CONTENTS

| | <u>PAGE</u> |
|-----------------------------|-------------|
| I INTRODUCTION | 1 |
| II PRESENT PLANT CAPACITY | 2 |
| III EXPECTED PLANT CAPACITY | 3 |
| IV ECONOMIC ANALYSIS | 6 |
| V CONCLUSION | 9 |
| APPENDIX | |

I
INTRODUCTION

Rattling Brook Development is located on the east coast of Central Newfoundland. The plant, commissioned in 1958, consists of two 8,500 h.p. turbines with generators rated at 6,375 kW each.

The actual plant capacity is given by Newfoundland Light & Power Co. Limited as 7,200 kW with one machine and 10,800 kW with both machines generating.

The purpose of this study is to ascertain reasons for the load restrictions with both machines operating and to analyze the feasibility of increasing production by increasing the flow area.

II
PRESENT PLANT CAPACITY

Two 8,500 h.p. turbines were installed at Rattling Brook in 1958. At present, the output in the plant is 7,200 kW with one machine in operation and 10,800 kW with both machines operating. Theoretically, the plant should have a capacity of approximately 14,000 kW.

Original design at Rattling consisted of two generating stations, each with a single machine. It was later decided, however, to erect one plant with two machines. Since the area was operated as an isolated system, the station was designed to carry all the area load on one machine with the second machine essentially a spare.

After 1966, when Rattling was tied to the provincial grid, it became feasible to operate both machines at full load if water was available. However, with both machines at full gate, excessive head losses in the pipe prevented full load on both machines.

At present, the production given for Rattling Brook during an average year is 70,000,000 kWh. With full load at 10,800 kW, this represents a load factor of 74%.

This production is achieved with a 6,850 ft. pipeline and penstock, consisting of 5,850 ft. woodstave and 1,000 ft. steel, operating with a discharge of approximately 620 cfs.

III
EXPECTED PLANT CAPACITY

It was initially thought that higher production could be accomplished by a combination of the following:

- (1) Higher output for same discharge by doubling flow area through looping a second penstock with that existing or replacing the existing pipe with a 9.25 ft. diameter pipe.
- (2) Greater efficiencies.
- (3) Picking-up some of the frequent spills.

To help evaluate item no. 1 above, site measurements were conducted for various plant conditions. With machines operating independently and together, readings were taken at various loads for the following: penstock pressure at the plant; water drop in the surge tank; forebay level; tailwater level; and flow in the tailrace. The results of the measurements are shown in the Appendix.

Two alternatives were considered, to loop another penstock from the intake to the surge tank or build a new 9.25 ft. diameter penstock, in both cases leaving the section from the surge tank to the plant unaltered.

Either alternative would increase the net head on the plant, thereby increasing the output proportionately. To calculate the average annual output due to the increased head, a load duration curve was produced for the year 1973 (see appendix "B"). 1973 was chosen because that year the production at Rattling Brook was within one percent of the average production.

The load duration graph was then divided into five sections and the increase in net head for the larger flow area calculated for each load increment. Knowing the increase in net head and discharge associated with each load increment, the increase in production was calculated using the following equation:

$$\text{kWH} = \frac{(Q) (\text{Hn increase}) (e) (\% \text{ load duration}) (8760)}{11.814}$$

kWH = output due to increase in head for each load increment

Q = discharge for each load increment

e = efficiency - assumed 75%

Hn = increase in net head

% load duration = % load increment of annual load duration

8760 = hours in one year

11.814 = constant incorporating water density and conversion of horsepower to kilowatts

The results of the calculation are shown in appendix "E". The increase in production for an average year will be in the area of 6,231,500 kWH.

An analysis of the spill records for Rattling was conducted to determine how much production could be attained from the spill. The daily spills since

1966 were reviewed and by comparing plant load on a specific day with the available production with a new pipeline, it was determined that approximately 500,000 kWh could be picked up each year by capturing the spill.

The efficiency of the plant could be increased by replacing the runner in each machine. It is anticipated the runner replacement could increase the efficiency by 4-5 percent. Another report will be completed to analyze the runner characteristics and ascertain the increase in production associated with runner replacement.

Note that increase in production due to runner replacement cannot be used to justify replacement of the penstock. Therefore, the remainder of this report will be concerned with the economics of increasing the flow area only.

IV
ECONOMIC ANALYSIS

Appendix "E" shows the additional production available from Rattling Brook Plant for an average year by looping another 7 ft. pipe with the existing pipe or erecting a new 9.25 ft. diameter pipe. In either case, the additional production for an average year is 6,231,573 kWh, plus 500,000 kWh by reducing spill. The total additional production is approximately 6,700,000 kWh.

The value of the 6,700,000 kWh of additional production was estimated from information obtained from Newfoundland and Labrador Hydro Corporation for the period 1983-2040. Accordingly, the benefit available from 6,700,000 kWh over the remaining life of the plant (56 years) is approximately \$3,640,000 (\$1984).

For a 7 ft. diameter pipeline, the cost is estimated to be \$4,196,750. The cost of operating this pipeline is estimated to be \$1,000 per year beginning in 1985.

For a 9.25 ft. diameter pipeline, the cost is estimated to be \$4,835,000. The cost of operating this pipeline should not be higher than that of the existing pipe and no operating cost will be included in the analysis.

If the project is eligible for a federal government incentive program to aid small hydro, CCA class 34 can be used in the corporate income tax calculation. Class 34 allows 25%, 50%, and 25% of the capital value of the asset to be applied against income in the first, second, and third years respectively. If the project is not eligible for the program, Class 2 will apply and allows the capital value of the asset to be applied against income at a 6% declining rate.

Economic calculations for looping another 7 ft. pipeline indicated the present worth of the annual charges under class 34 to be \$3,467,000, (\$1984). If class 34 is not applicable, the present worth of the annual charges is \$5,266,000 (\$1984).

The benefit cost ratio under class 34 is 1.05:1. The benefit cost ratio under class 2 is 0.70:1.

Economic calculations for replacing the existing pipeline with a 9.25 ft. pipeline indicated the present worth of the annual charges under class 34 to be \$3,995,000 (\$1984). If CCA class 34 is not applicable, the present worth of the annual charges is \$6,073,000 (\$1984).

The benefit cost ratio under class 34 is 0.91:1. The benefit cost ratio under class 2 is 0.60:1.

A summary of economic calculation is:

| <u>Alternative</u> | <u>CCA Class</u> | <u>Benefit/Cost Ratio</u> |
|--------------------|------------------|---------------------------|
| 7 ft. pipeline | 34 | 1.05:1 |
| 7 ft. pipeline | 2 | 0.70:1 |
| 9.25 ft. pipeline | 34 | 0.91:1 |
| 9.25 ft. pipeline | 2 | 0.60:1 |

CONCLUSIONS

In conclusion, it is not economically feasible, at this time, to increase the plant output at Rattling Brook by increasing the penstock flow area. The increased output of 6,700,000 kWh cannot justify the expenditure of \$4,500,000.

The project is barely economical if the work is done under Class 34, and only if the Class 34 program is continued into 1985. It is not possible to design, receive material, and erect a new 7'0" pipeline at Rattling Brook in 1984.

| <u>Alternative</u> | <u>CCA Class</u> | <u>Benefit/Cost Ratio</u> |
|--------------------|------------------|---------------------------|
| 7 ft. pipeline | 34 | 1.05:1 |
| 7 ft. pipeline | 2 | 0.70:1 |
| 9.25 ft. pipeline | 34 | 0.91:1 |
| 9.25 ft. pipeline | 2 | 0.60:1 |

APPENDIX "A"

RATTLING DAMOK PLANT

SUMMARY MEASUREMENTS

November 3, 1983

Unit #1

| LOAD | % GATE #1 #2 | PRESSURE AT MACHINE | | HEAD AT MACHINE | | TOTAL LOSSES | LOSSES TO SURGE TANK | LOSSES TANK TO PLANT | DISCHARGE |
|------|-----------------|------------------------|-------|--------------------|-------|-----------------|-------------------------------|-------------------------------|-----------|
| | | #1 | #2 | #1 | #2 | | | | |
| (KW) | | | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) |
| 5000 | 50 | 135 | | 314.0 | | 20.7 | 8.9 | 11.8 | 290 |
| 5500 | 54 | 134 | | 311.6 | | 23.0 | 9.8 | 13.2 | 336 |
| 6000 | 61 | 132 | | 307.0 | | 27.6 | 11.4 | 16.2 | 345 |
| 6500 | 70 | 128 | | 297.7 | | 37.0 | 13.8 | 23.2 | 348 |
| 7000 | 93 | 127 | | 295.3 | | 39.4 | 18.8 | 20.6 | 420 |

RATTLING OOK PLANTSUMMARY MEASUREMENTS

Unit #1 & #2

November 3, 1983

| LOAD | % GATE | | PRESSURE AT | | HEAD AT | | TOTAL | LOSSES | | LOSSES | LOSSES | DISCHARGE |
|-------|--------|----|-------------|-------|---------|-------|-------|--------|-------|--------|--------|-----------|
| | #1 | #2 | #1 | #2 | #1 | #2 | | #1 | #2 | | | |
| (KW) | | | (psi) | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) |
| 5000 | 29 | 29 | 140 | 137 | 325.6 | 318.6 | 16.0 | | | 10.6 | 5.4 | 333 |
| 6000 | 33 | 35 | 137 | 135 | 318.6 | 314.0 | 20.6 | | | 17.2 | 3.4 | 382 |
| 7000 | 38 | 40 | 133 | 132 | 309.3 | 306.9 | 27.8 | | | 19.9 | 7.9 | 405 |
| 8000 | 43 | 46 | 130 | 130 | 302.3 | 302.3 | 32.4 | | | 24.1 | 8.3 | 434 |
| 9000 | 48 | 52 | 127 | 125 | 295.3 | 290.7 | 44.0 | | | 31.8 | 12.2 | 507 |
| 10000 | 58 | 61 | 121 | 122 | 281.4 | 283.7 | 51.0 | | | 37.3 | 13.7 | 550 |
| 10500 | 67 | 68 | 118 | 117 | 274.4 | 272.1 | 62.6 | | | 43.5 | 19.1 | 580 |
| 10600 | 72 | 73 | 116 | 115 | 269.7 | 267.4 | 67.3 | | | 47.9 | 19.4 | 586 |
| 10800 | 86 | 87 | 112 | 112 | 260.5 | 260.5 | 74.2 | | | 54.9 | 19.3* | 565* |

RATTLING TANK PLANT

SUMMARY MEASUREMENTS

September 16, 1982

Unit #1

| LOAD | MACHINE PRESSURE #1 | MACHINE PRESSURE #2 | HEAD AT MACHINE #1 | HEAD AT MACHINE #2 | TOTAL LOSSES | LOSSES TO SURGE TANK | LOSSES TANK TO PLANT | DISCHARGE | LOAD |
|------|---------------------------|---------------------------|--------------------------|--------------------------|-----------------|----------------------------|----------------------------|-----------|------|
| (KW) | (psi) | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) | (KW) |
| 0 | 144 | | 334.9 | | -- | -- | | | |
| 5000 | 136 | | 316.0 | | 18.9 | 9.0 | 9.9 | 247.0 | 5000 |
| 5500 | 135 | | 314.0 | | 20.9 | 10.9 | 10.0 | 293.5 | 5500 |
| 6000 | 133 | | 309.0 | | 25.9 | 13.2 | 12.7 | 316.0 | 6000 |
| 6500 | 130 | | 302.0 | | 32.9 | 15.7 | 17.2 | 343.0 | 6500 |
| 7000 | 126 | | 293.0 | | 41.9 | 21.9 | 20.0 | 445.0 | 7000 |

RATTLING .00K PLANT

SUMMARY MEASUREMENTS

Unit #2

November 3, 1983

| LOAD | % GATE #1 #2 | PRESSURE AT MACHINE | | HEAD AT MACHINE | | TOTAL LOSSES | LOSSES TO SURGE TANK | LOSSES TANK TO PLANT | DISCHARGE |
|------|-----------------|------------------------|----|--------------------|-------|-----------------|-------------------------------|-------------------------------|-----------|
| (KW) | | #1 | #2 | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) |
| 5000 | 50 | | | 135 | | 314.0 | 21.0 | -- | 284 |
| 5500 | 55 | | | 135 | | 314.0 | 21.0 | -- | 319 |
| 6000 | 62 | | | 132 | | 307.0 | 28.0 | -- | 348 |
| 6500 | 75 | | | 128 | | 297.7 | 37.3 | -- | 391 |
| 7000 | 93 | | | 126 | | 295.3 | 39.7 | -- | 420 |

RATTLING BUCK PLANT

SUMMARY MEASUREMENTS

September 16, 1982

Unit #1 & 2

| LOAD | MACHINE PRESSURE #1 | MACHINE PRESSURE #2 | HEAD AT MACHINE #1 | HEAD AT MACHINE #2 | TOTAL LOSSES | LOSSES TO SURGE TANK | LOSSES TANK TO PLANT | DISCHARGE | LOAD |
|-------|---------------------------|---------------------------|--------------------------|--------------------------|-----------------|----------------------------|----------------------------|-----------|-------|
| (KW) | (psi) | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) | (KW) |
| 9000 | 126 | 125 | 293.0 | 290.7 | 44.2 | 33.2 | 11.0 | 549 | 9000 |
| 9500 | 125 | 123 | 290.7 | 286.0 | 48.9 | 36.4 | 12.5 | 516 | 9500 |
| 10000 | 122 | 120 | 283.7 | 279.0 | 55.9 | 40.7 | 15.2 | 537 | 10000 |
| 10400 | 120 | 118 | 279.0 | 274.4 | 60.5 | 46.4 | 14.1 | 524 | 10400 |
| 10500 | 119 | 117 | 276.7 | 272.0 | 62.9 | 47.8 | 15.1 | 541 | 10500 |
| 10600 | 118 | 116 | 274.4 | 269.7 | 65.2 | 48.7 | 16.5 | 545 | 10600 |
| 10700 | 116 | 115 | 269.7 | 267.4 | 67.5 | 53.1 | 14.4 | 550 | 10700 |
| 10800 | 115 | 113 | 267.4 | 262.8 | 72.1 | 54.7 | 17.4 | 619 | 10800 |

RATTLING LOOK PLANT

SUMMARY MEASUREMENTS

Unit #2

September 16, 1982

| LOAD | MACHINE PRESSURE #1 | MACHINE PRESSURE #2 | HEAD AT MACHINE #1 | HEAD AT MACHINE #2 | TOTAL LOSSES | LOSSES TO SURGE TANK | LOSSES TANK TO PLANT | DISCHARGE | LOAD |
|------|---------------------------|---------------------------|--------------------------|--------------------------|-----------------|----------------------------|----------------------------|-----------|------|
| (KW) | (psi) | (psi) | (ft.) | (ft.) | (ft.) | (ft.) | (ft.) | (cfs) | (KW) |
| 0 | 144 | | 334.8 | | | | | | |
| 5000 | 136 | | 316.0 | | 18.8 | | | 235 | 5000 |
| 5500 | 134 | | 312.0 | | 22.8 | | | 254 | 5500 |
| 6000 | 132 | | 307.0 | | 27.8 | | | 279 | 6000 |
| 6500 | 130 | | 302.0 | | 32.8 | | | 302 | 6500 |
| 7000 | 126 | | 293.0 | | 41.8 | | | 355 | 7000 |

RATTLING BROOK PLANT

SUMMARY MEASUREMENTS

Unit 1

June 14, 1983

| LOAD | PRESSURE AT MACHINE | | HEAD AT MACHINE | | LOSSES | % GATE | DISCHARGE | LOAD | UNIT |
|----------|------------------------|-------|--------------------|-------|--------|--------|-----------|----------|----------|
| | #1 | #2 | #1 | #2 | | | | | |
| (KW) | (psi) | (psi) | (ft.) | (ft.) | (ft.) | | (cfs) | (KW) | |
| A11 Down | 145 | 145 | 337.0 | 337.0 | | | 9.66 | A11 Down | A11 Down |
| 0 | 145 | | 337.0 | | | | 37.40 | 0 | |
| 5000 | 137 | | 318.6 | | 18.4 | | 212.20 | 5000 | |
| 5500 | 136 | | 316.0 | | | | 255.10 | 5500 | |
| 6000 | 134 | | 311.6 | | 25.4 | | 294.70 | 6000 | |
| 6500 | 132 | | 307.0 | | 30.0 | 68% | 313.40 | 6500 | |
| 7000 | 127 | | 295.0 | | 42.0 | | 333.90 | 7000 | |
| 7100 | 126 | | 293.0 | | 44.0 | 100% | 406.00 | 7100 | |

RATTLING BROOK . LANT

SUMMARY MEASUREMENTS

June 14, 1983

Units 1 & 2

| LOAD | PRESSURE AT MACHINE | | HEAD AT MACHINE | | LOSSES | % GATE | DISCHARGE | LOAD |
|-------|------------------------|-------|--------------------|-------|--------|--------|-----------|-------|
| | #1 | #2 | #1 | #2 | | | | |
| (KW) | (psi) | (psi) | (ft.) | (ft.) | (ft.) | | (cfs) | (KW) |
| 9000 | 128 | 126 | 297.7 | 293.0 | 44.0 | | 508.2 | 9000 |
| 9500 | 125 | 123 | 290.7 | 286.0 | 51.0 | | 520.3 | 9500 |
| 10000 | 123 | 121 | 286.0 | 281.4 | 56.0 | | 554.5 | 10000 |
| 10400 | 121 | 119 | 281.4 | 276.7 | 60.5 | | 601.8 | 10400 |
| 10500 | 117 | 115 | 272.0 | 267.4 | 69.8 | | 622.3 | 10500 |
| 10600 | 117 | 115 | 272.0 | 267.4 | 69.8 | | 627.1 | 10600 |
| 10700 | 117 | 115 | 272.0 | 267.4 | 69.8 | | 627.1 | 10700 |
| 10800 | 115 | 114 | 267.4 | 265.0 | 72.0 | No. 1 | 599.0 | 10800 |
| | | | | | | No. 2 | | |

APPENDIX "B"

LOAD DURATION GRAPH

RATTLIN BROOK PLANT

SUMMARY MEASUREMENTS

June 14, 1983

No. 2 Machine

| LOAD | PRESSURE AT MACHINE #1 | AT MACHINE #2 | HEAD AT MACHINE #2 | LOSSES | % GATE | DISCHARGE | LOAD | UNIT |
|------|------------------------------|------------------|--------------------------|--------|--------|-----------|------|------|
| (KW) | (psi) | (psi) | (ft.) | (ft.) | | (cfs) | (KW) | |
| 0 | 145 | | 337 | | | 38.5 | 0 | |
| 5000 | 136 | | 316 | 21 | | 223.4 | 5000 | |
| 5500 | 133 | | 309 | 28 | | 263.1 | 5500 | |
| 6000 | 132 | | 307 | 30 | | 284.6 | 6000 | |
| 6500 | 130 | | 302 | 35 | 72% | 316.4 | 6500 | |
| 7000 | 125 | | 291 | 46 | | 402.4 | 7000 | |
| 7100 | 125 | | 291 | 46 | 100% | 406.0 | 7100 | |

APPENDIX "C"


ESTIMATES

7'0" PIPE AND 9'3" PIPE

\$1984

RATTLING BROOK PLANT LOAD FREQUENCY

1973 PRODUCTION YEAR



APPENDIX "C"

ESTIMATE

NEW 9'3" DIAMETER WOODSTAVE PIPELINE

| <u>Item</u> | <u>Description</u> | <u>Quantity</u> | <u>Unit Price</u> | <u>Amount</u> |
|-------------|-----------------------------|-----------------|-------------------|--------------------|
| 1. | Woodstave Material | 6,000 ft. | \$ 567 | \$3,400,000 |
| 2. | Woodstave Erection | 6,000 ft. | 100 | 600,000 |
| 3. | Demolish Existing Pipe | L.S. | | 150,000 |
| 4. | Steel Thimbles | | | 75,000 |
| 5. | Bed Alterations | | | 50,000 |
| 6. | Engineering and Supervision | | | 50,000 |
| 7. | Surveying | | | <u>10,000</u> |
| | Sub-Total | | | \$4,335,000 |
| | I.D.C. over 12 Months | | | 250,000 |
| | Contingency | | | <u>250,000</u> |
| | Total | | | <u>\$4,835,000</u> |

APPENDIX "C"

ESTIMATE

NEW 7'0" DIAMETER WOODSTAVE PIPELINE

| <u>Item</u> | <u>Description</u> | <u>Quantity</u> | <u>Unit Price</u> | <u>Amount</u> |
|-------------|-----------------------------|-----------------|-------------------|--------------------|
| 1. | Woodstave Material | 6,210 ft. | \$ 418 | \$2,600,000 |
| 2. | Woodstave Erection | 6,210 ft. | 75 | 465,750 |
| 3. | Bed Preparation | 6,210 ft. | 64 | 400,000 |
| 4. | Stream Crossings | 2 | 10,000 | 20,000 |
| 5. | Steel Thimbles | 2 | 38,000 | 76,000 |
| 6. | Rebuild Under Highway | L.S. | | 75,000 |
| 7. | Engineering and Supervision | | | 50,000 |
| 8. | Surveying | | | <u>10,000</u> |
| | Sub-Total | | | \$3,696,750 |
| | I.D.C. over 12 Months | | | 250,000 |
| | Contingency | | | <u>250,000</u> |
| | Total | | | <u>\$4,196,750</u> |

NOTE: To extend the two penstocks from the surge tank to the plant will cost an additional \$450,000.

APPENDIX "D"

CALCULATION FOR
INCREASE IN NET HEAD
FOR INCREASED FLOW AREA

| kW | LOSSES TO TANK | | V 7'0" PIPE (ft/sec) | 1.5 V ² /2g 7'0" PIPE (ft) | FRICTION LOSS TO TANK | | INCREASE NET HEAD (ft) |
|--------|----------------|------|----------------------------|---|-----------------------|-------------------|------------------------------|
| | Q (cfs) | (ft) | | | 7'0" PIPE (3-5) | 9.3" PIPE (ft) | |
| 5,000 | 290 | 8.9 | 7.5 | 1.31 | 7.59 | 2.8 | 4.8 |
| 5,500 | 336 | 9.8 | 8.7 | 1.76 | 8.04 | 2.96 | 5.1 |
| 6,000 | 345 | 11.4 | 8.9 | 1.84 | 9.56 | 3.54 | 6.0 |
| 6,500 | 348 | 13.8 | 9.0 | 1.88 | 11.92 | 4.41 | 7.5 |
| 7,000 | 420 | 18.8 | 10.9 | 2.76 | 16.04 | 5.85 | 10.2 |
| 8,000 | 434 | 24.1 | 11.3 | 2.97 | 21.13 | 7.70 | 13.4 |
| 9,000 | 507 | 31.8 | 13.2 | 4.06 | 27.74 | 10.27 | 17.6 |
| 10,000 | 550 | 37.3 | 14.3 | 4.76 | 32.54 | 11.91 | 20.6 |
| 10,500 | 580 | 43.5 | 15.1 | 5.31 | 38.19 | 13.98 | 24.2 |
| 10,600 | 605 | 47.9 | 15.7 | 5.74 | 42.16 | 15.60 | 26.8 |
| 10,800 | 620 | 54.9 | 16.1 | 6.03 | 48.87 | 17.86 | 31.0 |

APPENDIX "E"

INCREASE IN PRODUCTION

1973

ESTIMATED INCREASE IN PRODUCTION

1973

FLOW AREA DOUBLED

| LOAD GROUP (kW) | LOAD DURATION (% OF ANNUAL LOAD) | INCREASE NET HEAD (ft) | DISCHARGE (cfs) | INCREASE IN PRODUCTION (kWh) |
|--------------------|-------------------------------------|------------------------------|--------------------|------------------------------------|
| 0- 5,000 | 2 | 4.8 | 290 | 15,482 |
| 5,000- 5,500 | 14.5 | 5.1 | 336 | 138,180 |
| 5,500- 7,300 | 31.5 | 10.2 | 420 | 750,462 |
| 7,300-10,500 | 8 | 24.2 | 580 | 624,455 |
| 10,500-10,800 | 44 | 31.0 | 620 | <u>4,702,994</u> |
| | | | TOTAL | <u>6,231,573</u> |

Appendix B

Electrical Equipment Site Assessment

Electrical Equipment Site Assessment

May 28, 2004

Prepared By:
John W. Pardy, P.Eng.
Jack Casey, P. Eng

Table of Contents

| | Page |
|--|------|
| 1.0 General..... | 1 |
| 2.0 AC Distribution..... | 1 |
| 3.0 Station Service | 1 |
| 4.0 DC Distribution..... | 2 |
| 5.0 Battery Plant and Charger..... | 2 |
| 6.0 Generators | 2 |
| 7.0 Excitation Systems..... | 2 |
| 8.0 Switchgear..... | 3 |
| 9.0 Power Cables | 3 |
| 10.0 Grounding | 4 |
| 11.0 Protective Relays | 4 |
| 12.0 Alarm Annunciation..... | 4 |
| 13.0 Synchronizer | 5 |
| 14.0 Governor Interface | 5 |
| 15.0 Plant Control | 5 |
| 16.0 Mechanical Protection | 5 |
| 17.0 Instrumentation | 6 |
| 18.0 Bearing Cooling Water Control..... | 6 |
| 19.0 Heating and Ventilation | 6 |
| 20.0 Forebay Water level Monitoring and Control..... | 6 |
| 21.0 Conclusion | 7 |

1.0 General

The Rattling Brook hydro development went into service in December 1958. The generating station comprises two 8500 horsepower vertical shaft Francis turbines connected to separate generators each with an original rating of 7500 kVA.

Generating unit # 2 experienced an in-service failure of the windings and underwent a stator rewind in 2002. The planned rewind of generating unit #1 is scheduled to occur in September 2004.

In 1987 the turbine runners were replaced in each unit. In 1994, the Rattling Brook generating station was placed under remote control from the system control centre in St. John's. With the exception of these major projects, the plant remains in original condition.

2.0 AC Distribution

The existing 120/240V 3-phase AC service panel is located in a cell in the existing switchgear line up. This equipment is original to the plant and replacement breakers are no longer available. With additional loading from the proposed plant upgrading and the addition of new heating and ventilating equipment, this panel will no longer have sufficient capacity. It is preferred to locate the AC panel remote from the switchgear line up to provide ease of access for wiring future circuits.



3.0 Station Service

There are currently two station services connected to the 6900 volt generator bus. The original plant station service located in the switchgear cabinet consists of (3) 25 KVA 240 volt secondary transformers, with one transformer low voltage winding tapped to provide 120v secondary voltage. The second station service transformer was installed to supply the former control centre building located on this site. This service consists of a 150 kVA three-phase transformer with a 120/208 volt secondary. With the installation of new electrical equipment, it will be necessary to change the voltage of the existing plant station service transformer to satisfy the voltage requirements of the new equipment and increase transformer capacity to accommodate the additional load. Consideration will be given to providing redundant station services, a normal supply and an emergency supply to ensure the availability of this critical black start plant.

4.0 DC Distribution

The DC distribution panel is original to the plant. Additional circuit breakers will be required to protect the DC control circuits for the various electronic components to be included in the governor and unit control panels. Due to its age, additional circuit breakers for this panel are no longer available. Insufficient spare locations exist in the panel to accommodate the additional circuits requiring the installation of an additional panel. It is recommended that the DC distribution panel be replaced with one adequate for the additional DC powered equipment.



5.0 Battery Plant and Charger

The battery bank was installed in 1996 and is in good condition. The battery charger was installed in 1984. Its condition will be assessed and replacement considered. The concern to be addressed with the battery system is that the battery bank and the charger are located in the same room as the switchgear. This situation contravenes the Canadian Electrical Code and needs to be addressed. The plant refurbishment must include the construction of a separate battery room meeting CSA standards to house the battery bank.



6.0 Generators

Generator unit #2 was rewound in 2002 after failing in service. Generator unit #1 will be rewound in 2004. The existing termination cabinets attached to the generators as presently configured do not have space for a grounding transformer to enhance unit protection. The termination cabinets will be redesigned to accommodate a grounding transformer.

7.0 Excitation Systems

The exciters on generating units #1 and #2 are the original to the generating station but are in good condition. During the plant refurbishment, these exciters will be refurbished to ensure continued reliable service. Both units have Brown Boveri voltage regulators that are mechanical in nature and have been discontinued for many years. These voltage regulators will be replaced with digital voltage regulators. The excitation cables are original to plant and will be replaced as they are near the end of their service life.

8.0 Switchgear

The generator and incoming breakers are original units installed in 1958. The potential transformers (PT) and current transformers (CT) are integral to the switchgear and there is no indication that they have been replaced since their original installation. Concerns exist with the condition of the PT and CT windings due to their age. The critical role this equipment plays in the electrical protection of the generators dictates that they be replaced.

The existing switchgear design was based upon two incoming breakers fed from two separate power transformers. In 2002, the original transformers were replaced with a single power transformer. The two original incoming breakers and associated power cables are connected in parallel feeding the new power transformer. A replacement switchgear design will connect the 6900-volt bus to the power transformer with a single incoming breaker and single set of power cables capable of carrying the total maximum current of both generators.

Another issue to be addressed with the switchgear is the combining of the breaker protection and control with the generator sequencing, monitoring and control functions in a single panel. Replacement of generator control is best done in concert with the switchgear replacement since the existing design has incorporated both functions into a single panel.

9.0 Power Cables

The power cables from the generator termination cabinets to the switchgear are the original 1000 MCM paper insulated lead covered (PILC) cables with pitch filled pothead terminations. PILC cables typically have a long life expectancy. However, these cables are susceptible to stress fractures if the insulation is subjected to movement following years of resting in a fixed position. It is expected that the movement these cables will be subjected to during the reconstruction will cause stresses in the cables leading to premature failure. Therefore the power cables and terminations will need to be replaced when the switchgear is replaced.



Unit #1 Switchgear
Cable Terminations



Unit #1 Generator
Cable Terminations

10.0 Grounding

Both generators currently have their windings solidly connected to earth, which in the event of a fault will subject the windings to the electrical stresses of the total available fault current. Installation of grounding transformers will introduce a high impedance ground path. This will significantly reduce the available fault current thereby reducing the electrical and mechanical stresses on the generators under fault conditions thereby reducing the risk of catastrophic failure. It is recommended that the high impedance ground design be implemented, and related ground fault protection improvements be completed.

11.0 Protective Relays

The existing generator protection for both generating unit #1 and #2 is provided through electromechanical relays consisting of the following:

- 40 loss of field protection
- 49 stator thermal protection
- 51N neutral overcurrent
- 87G unit differential protection
- 87S split phase protection
- 51V Voltage restrained overcurrent

Over the past 50 years improvements in generator protection have been developed and the following additional protection is recommended:

- 59G over voltage relay for ground faults
- 87GN Sensitive ground fault protection
- 64F voltage relay for rotor ground faults
- 46 Stator unbalanced current protection
- 81 Over-frequency protection

The existing transformer protection is provided through a Alstom P632 digital relay and as a result can be maintained without modification.

12.0 Alarm Annunciation

The annunciator panel located in the switchgear line-up is original to the plant. It is a mechanical unit where metal targets drop down to annunciate an alarm. There are numerous targets no longer operational. With the installation of unit control panels equipped with human machine interfaces (HMI's), this device will be redundant and can be removed.



13.0 Synchronizer

The vacuum tube synchronizer design is original to the 1958 plant construction. The fact that the synchronizer is constructed from vacuum tube technology means that parts are no longer available. Within Newfoundland Power, no expertise exists in the maintenance of this device. It will be replaced with a modern synchronizer as part of the upgraded unit control panel.



14.0 Governor Interface

The original Woodward Type HR hydraulic governors are still in service on both units. It is becoming increasingly difficult to obtain replacement parts for these units. The original equipment manufacturer has declared the product as obsolete and will no longer manufacture replacement parts. Within the Company, there is also a decreasing knowledge base of expertise in the operation and maintenance of these governors, making it increasingly difficult to reliably maintain this equipment.

Electronic upgrades are available to replace the mechanical speed governing components from a number of different suppliers. These upgrades may be feasible if the power piston and oil reservoir are in good condition. An inspection of these components by the original equipment manufacturer would determine if this solution is viable.

15.0 Plant Control

Although this plant is remotely controlled and monitored, remote control functions are limited. Intervention by a local or remote operator is required to start and stop both units at this plant. Adjusting the load to efficient operation requires manual input from an operator and frequent adjustments. At present, there is no automation with respect to water management and automatic setting of loads.

Improving the plant control using a programmable logic controller would enable a variety of control modes best suited for the efficient operation of the plant.

16.0 Mechanical Protection

Unit #1 has been upgraded with a programmable logic controller (PLC) that provides a measure of mechanical protection through the monitoring of some equipment temperatures. Problems encountered in interfacing a PLC with the existing control systems have delayed the provision of mechanical protection on Unit #2. Neither unit has vibration monitoring which is critical in early detection of many mechanical failures.

17.0 Instrumentation

Thermocouples and resistance temperature devices (RTD) exist for most bearings surfaces, oil reservoirs, and cooling water systems. However it is difficult to assess their accuracy without first disassembling the generator. The integration of these temperature measuring devices into the existing control system is the cause of many false trips on the units. Integrating the thermocouples into a PLC based unit control panel will allow for finer control and pre-alarming functionality that can avoid potential false trips on the units.

18.0 Bearing Cooling Water Control

There are valves and piping in place for both units, and there is some automated control of these valves at present. Flow monitoring and controlled valves are installed to provide protection and control. This system will need to be integrated into any new control system for automating the plant.

19.0 Heating and Ventilation

There are anti-condensation heaters and infrared heaters installed for each unit controlled by a hand operated humidistat and thermostat respectively. All of the controls of heating and ventilation equipment should be upgraded so that desired building temperature and humidity can be monitored and controlled by the unit control PLC. Integrating the heating and ventilating control with the generator control PLC will ensure that a generator covered in condensation will not be energized and subsequently damaged.

20.0 Forebay Water Level Monitoring and Control

The existing water level probe and transducer are older vintage equipment. This equipment should be replaced with a new 4 to 20-milliamp water level transmitter at the forebay. The forebay cable is in good condition, but the cable terminations are in poor condition. The cable will be re-terminated.

21.0 Conclusion

The following is a list of the major recommendations that should be addressed during the refurbishment of the generating station:

- Upgrade electrical and mechanical protection system for Rattling Brook plant
- Replace voltage regulator, synchronizer and alarm annunciation
- Replace the power cables
- Replace existing relay control system with PLC based control system
- Refurbish or replace existing governor systems
- Replace or upgrade the existing switchgear, pending further internal inspections
- Replace AC and DC electrical distribution systems

Appendix C

Mechanical Site Assessment

Mechanical Site Assessment

June 18, 2004

Prepared By:
Kent Nicholson, P. Eng

Table of Contents

| | Page |
|---|------|
| 1.0 General..... | 1 |
| 2.0 Unit #1 Turbine Runner..... | 1 |
| 3.0 Unit #2 Turbine Runner..... | 1 |
| 4.0 Unit #1 Main Inlet Valve..... | 2 |
| 5.0 Unit #2 Main Inlet Valve..... | 2 |
| 6.0 Unit #2 Alignment..... | 3 |
| 7.0 Unit #1 & #2 Gate Shaft Governor & Pumping Units..... | 3 |
| 8.0 Unit #1 & #2 Bearing Cooling Water Systems..... | 4 |
| 9.0 Plant Heating & Ventilation..... | 5 |
| 10.0 Unit Instrumentation..... | 5 |
| 11.0 Balance of Plant Auxiliaries..... | 5 |
| 12.0 Conclusion..... | 5 |

1.0 General

The Rattling Brook hydro development went into service in December 1958. The generating station comprises two 8500 horsepower vertical shaft Francis turbines connected to separate generators each with an original rating of 7500 kVA.

Both units were overhauled in the 1986/1987 timeframe including the replacement of the runner and general mechanical overhaul of the machine. The wicket gates and bushings were not replaced and it has not been determined whether or not the stationary seals were replaced at that time.

An inspection of both turbine runners at Rattling Brook Plant was performed during the summer of 1998 and the balance of plant inspection was carried out in May 2004. The scope of the inspections in 1998 included: the high & low pressure sides of the runner; the wicket gates and seals; gate closure and water passage opening; general condition of the scroll case and the main valve disk; disk seat; and stationary seat.

2.0 Unit #1 Turbine Runner

Both runners on Unit #1 and Unit #2 are stainless steel cast construction. The inspection found several areas where erosion and cavitation have exposed faults in the stainless steel casting, possibly porosity during the casting process. This was concentrated near the root of the blades and the top band. The rest of the runner was in good condition with little evidence of erosion or cavitation.

Some of the wicket gates were repaired in the late 1980's using a Belzona plastic-metal product. For the most part this Belzona product has eroded away and separated from the gate leaving large crevasses exposed.

The general condition of the scroll case is good. During the inspection of this unit in 1998 a three foot long section of 2"x1/4" angle iron was found wedged in the scroll case. There was no damage to the wicket gates or turbine runner as the piece did not protrude out past the stay vanes. The surge tank and penstock inspections did not give any hard evidence as to the origin of the angle iron. No other pieces were found in the tank, pipeline or, the intake.

3.0 Unit #2 Turbine Runner

The runner has several areas where erosion and cavitation has exposed faults in the stainless steel casting. This erosion is concentrated near the root of the blading. There is evidence of hair line fractures tracking between the faulted areas. The wicket gates were repaired in the late 1980s with Belzona. This material has since eroded leaving large crevasses in the wicket gate body. The general condition of the scroll case is good. The draft tube door on Unit #2 is not sealing properly and will require some work.



Photo 1 – Shows localized cavitation and erosion of the turbine runner blades.

4.0 Unit #1 Main Inlet Valve

The valve body is in good condition. The disk seat has a small chip removed from the brass in the lap joint approximately 1/8" long, but otherwise the seal is in good shape. The stationary seat also looks to be in good condition.

Existing flexible pipe is to be replaced with new so that all piping will have generally the same life span.

5.0 Unit #2 Main Inlet Valve

The main valve disk seat is in fair condition with one area approximately 3/4" long x 1/2" wide where pitting is evident. The visual inspection showed that the disk and the stationary seat are in good condition.

Both valves do however leak around the disc edge on the butterfly valve. During our last internal inspection of the scroll casing the employees had to install a tarp downstream of the main inlet valve to cut down on the amount of water spray coming from around the circumference of the valve disc. It is recommended that the existing adjustable seats on the valves be adjusted to try and eliminate the leakage around the valve disc; if this is not successful the valves may require new valve seats on the disc and the stationary components.




Photo 2 – Shows a chipped and cracked area on the main inlet valve disc seat.

The 5-way valves that control the opening and closing of the main inlet valves have been experiencing operational problems. These 5-way valves should be replaced. The existing flexible pipe is to be replaced with new so that all piping will have generally the same life span.

6.0 Unit #2 Alignment

In December 2002 Voith Siemens Hydro Power Generation rewound Rattling Brook Unit #2 stator and performed a realignment of the turbine-generator unit. Voith Siemens found that a proper alignment of the machine would require a lateral move of the stator which Newfoundland Power was not prepared to undertake at that time. It is thought that this out-of-alignment problem in the stator may be due to some subsidence in the concrete foundations of either the machine or the building. During this project, the stator will be moved so that proper alignment can be accomplished.

7.0 Unit #1 & #2 Gate Shaft Governor & Pumping Units

The governors and control linkages were inspected for worn bushings and lost motion. In general these two gate shaft governors were found to be in reasonable condition. There is some movement in the operating ring, tower and guide blocks on both units. There is also some movement in the governor operating arm as well as in the cross head on Unit #2.

The pumping units are in relatively good condition, with no major oil leaks. However, the packings leak and should be replaced. The units still maintain proper operating pressure and accumulator air volume.

These governors are a key component in regulating the speed of the generators and the quality of the power delivered by the plant. Due to the fact that they are 46 years old and difficult to maintain due to availability of spare parts and due to the fact that there is unnecessary movement in regular operating components as noted above, it is recommended that the hydraulic control head on each unit be replaced with an electro-hydraulic control head.



Unit #1 Governor Control
And Wicket Gate Actuator



Unit #1 Oil Accumulator
And Governor Oil Pump

8.0 Unit #1 & #2 Bearing Cooling Water Systems

The units at Rattling Brook have been suffering from higher than normal bearing temperatures which are attributed to the use of the Hydrosafe oil that is breaking down and is leaving 'gluey' deposits on the bearing cooling coils. The bearing cooling water system piping is suffering from frequent plugging of the piping. These piping systems should be replaced along with appropriate shutdown solenoids and flow meters. The 1958 vintage twinned strainer for both units is leaking around the operating shaft stems and is in need of repair. The existing strainer was initially designed to supply water to the two units' obsolete fire suppression system that is no longer in use. Currently the system is only required to supply cooling water to the bearings and the eductor pump, thus a large twinned strainer is no longer required. The current arrangement has caused problems in that both units have to be shut down in the event that the strainer needs maintenance. This system should be changed to a more conventional duplex filter element system installed on each unit with its own take off supply.

9.0 Plant Heating & Ventilation

The generator cooling air intake dampers located overhead on the tailrace wall are in a state of disrepair and need to be replaced. The seals in the positioners for the operable dampers also need to be replaced. There is also a large amount of non-friable asbestos panelling located adjacent to these operable dampers, which should be removed during this project. Finally, some new grating and framing is required in this area to improve the safety of employees on the walkway, which runs along these operable dampers.

10.0 Unit Instrumentation

The instrumentation on Unit #2 was upgraded in 2002 during the rewinding of the generator stator by Voith Siemens. The instrumentation on Unit #1, however, was not upgraded and thus needs to be done. Unit #1 needs the following instrumentation upgrades:

1. New bearing oil level sensors
2. New bearing cooling water flow meters and switches
3. New bearing cooling water shut-off solenoid valves
4. Speed pickup for creep control and unit speed telemetry

11.0 Balance of Plant Auxiliaries

The existing plant air compressor is 46 years old and in fair condition and should be replaced as part of the plant overhaul.

The eductor pump in the sump pit has been failing and causing pit flooding. The building's pit eductor, piping and level switch in the sump pit should be replaced.

The building's intake louver cylinder and operator both need a new seal kit to be installed.

12.0 Conclusion

The following is a list of the major recommendations that should be addressed during the refurbishment of the generating station:

1. The runners should be removed for a detailed inspection. Weld repair cast runners based on results of inspection. This weld repair procedure will have to be performed by a contractor with experience in weld repairing cast stainless steel turbine runners.
2. It is recommended that the existing adjustable seats on the main inlet valves be adjusted to try and eliminate the leakage around the valve disc. If this is not successful the valves may require new valve seats on the disc and the stationary components.

3. The 5-way valves that control the opening and closing of the main inlet valves have been experiencing operational problems. These 5-way valves should be replaced.
4. Perform detailed inspection on the wicket gates. If the inspection indicates that a repair is not feasible; the wicket gates, wicket gate bushings and stationary seals on both units should be replaced.
5. It is recommended that Unit #2 stator be moved so that proper alignment can be accomplished.
6. It is recommended that the hydraulic control head on each of the Woodward gate shaft governor units replaced with a newer electro-hydraulic control head.
7. The bearing cooling water system piping is suffering from frequent plugging of the piping and all of these piping systems should be replaced. The use of one large twinned strainer unit for both units has caused problems in that both units have to be shutdown in the event that the strainer needs maintenance. This system should be changed to a more conventional duplex filter element system installed on each unit.
8. All cooling water piping and cooling coils to be inspected tested and replaced if necessary during the overhaul.
9. The operable intake dampers need to be replaced and new motor operators installed. The control for the plant heating and ventilation should be incorporated into the PLC logic control for the plant. There is some replacement required to the catwalk system along the operable dampers and some non-friable asbestos to be removed.
10. Unit #1 needs the following instrumentation upgrades:
 - New bearing oil level sensors/switches, one per bearing oil pot
 - New bearing cooling water flow meters and switches
 - New bearing cooling water shut-off solenoid valves
 - Speed pickup for creep control and unit speed telemetry
 - Bearing thermocouples or resistance temperature devices (two per bearing)
 - Vibration monitoring one per bearing
 - The existing stator resistance temperature devices should be fed into the new PLC based control system along with the bearing instrumentation for mechanical protection.
11. The eductor pump, piping and level switch in the sump pit should be replaced.

Appendix D
Feasibility Analysis

Feasibility Analysis

June 22, 2004

Table of Contents

| | Page |
|-----------------------------|------|
| 1.0 Introduction..... | 1 |
| 2.0 Capital Costs | 1 |
| 3.0 Operating Costs..... | 2 |
| 4.0 Benefits | 2 |
| 5.0 Financial Analysis..... | 2 |
| 6.0 Recommendation | 3 |

Schedule A: Summary of Capital Costs

Schedule B: Summary of Operating Costs

1.0 Introduction

The Rattling Brook hydroelectric development is located in the community of Norris Arm, in central Newfoundland. The generating plant at Rattling Brook was commissioned in 1958 and consists of two vertical Francis units, each with a maximum capacity of about 7500 KVA.

Newfoundland Power's continued long-term operation of the Rattling Brook hydroelectric development is dependent on the completion of capital improvement initiatives for major components within the system. As a result, various refurbishment projects are planned for the 2006 and 2007 construction seasons.

Several major components of the development are in need of replacement or refurbishment, including the woodstave penstock, surge tank, governors, generator controls/protection, and main valves. With substantial investment required in the near-term to permit the continued reliable operation of this plant, an economic analysis of this development over a 25-year horizon is warranted. A summary of the costs, benefits, and associated financial analysis is summarized in this report.

2.0 Capital Costs

All significant capital expenditures foreseen for the hydroelectric development over the next 25 years have been identified. The majority of these expenditures (\$11,402,000) are currently planned for 2005, 2006 and 2007, and the remaining (\$200,000) expenditures are planned for 2015. The capital expenditures required to maintain the safe and reliable operation of the facilities are summarized below.

| Hydroelectric Development Capital Expenditures | |
|---|-------------|
| Year | Cost |
| 2005 | 350,000 |
| 2006 | 5,643,000 |
| 2007 | 5,409,000 |
| 2015 | 200,000 |
| Total | 11,602,000 |

The total capital expenditure of all of the projects listed above is \$11,602,000 (in 2005 dollar values). A more comprehensive breakdown of capital costs is provided in Schedule "A".

3.0 Operating Costs

Operating cost for this hydroelectric system is estimated to be in the order of \$236,000 per year. This estimate is based primarily upon recent years' operating experience. The operating cost represents both direct charges for operations and maintenance at this plant as well as indirect costs related to activities associated with managing the environment, safety, dam safety inspections, staff training, etc.

The annual operating cost also includes a water power rental rate of \$0.80 per MWh. This fee is paid annually to the Provincial Department of Environment and Conservation (Water Resources Management Division) based on yearly hydro plant generation/output. Such a charge is not reflected in the historical annual operating costs for the Rattling Brook development. Therefore, an adjustment is applied to account for the associated increased operating expenses on a go-forward basis.

Penstock and surge tank maintenance has accounted for a portion of the operating costs of this plant in recent years. Future operating cost has been estimated to include an assumed reduction of \$10,000 per year to reflect the penstock and surge tank rehabilitation initiatives.

4.0 Benefits

The estimated long-term normal production at this plant under present operating conditions is 69.4 GWh/yr. This estimate is based on the results of the Water Management Study completed by Acres International Limited December 2000 adjusted for actual average production and practical operations.

Some of the capital improvement projects will result in decreased energy losses, and subsequent increases in capacity and generation. In particular, it is anticipated that a newly constructed 9.5 ft diameter steel penstock will significantly reduce headloss, eliminate penstock leakage and reduce water spillage. The annual energy generation is expected to increase by about 10% (7 GWh) per year at Rattling Brook.

The downtime associated with the 2006 and 2007 capital works at this plant will result in a higher amount of spill at the forebay compared to a normal operating year. It is anticipated that the potential lost generation may be in the order of 15 GWh/yr. Therefore, the analysis assumed production at Rattling Brook of 54 GWh in 2006 and 2007, and 76 GWh/yr thereafter.

5.0 Financial Analysis

An overall financial analysis of combined costs and benefits has been completed using the levelized cost of energy approach. The levelized cost of energy is representative of the revenue requirement required to support the combined capital and operating costs associated with the development.

The estimated levelized cost of energy from the Rattling Brook plant over the next 25 years is 1.7 cents per kWh. This figure includes all projected capital and operating costs necessary to operate and maintain the facility. Energy from Rattling Brook can be produced at a significantly lower price than the cost of replacement energy, assumed to come from Newfoundland Hydro's Holyrood Generating Station. Based on information provided in Newfoundland Hydro's 2003 GRA, incremental energy is estimated to cost 4.6 cents per kWh in the short term (assuming \$28.95 per barrel, and 630 kWh/barrel), with an associated levelized cost of 5.8 cents per kWh assuming a 2% long-term escalation rate.

The future capacity benefits of the continued availability of Rattling Brook hydro plant have not been considered in this analysis. If factored into future feasibility analysis, the financial benefit associated with system capacity would further support the viability of continued plant operations.

6.0 Recommendation

Newfoundland Power should proceed with this project in 2005 as planned. The project is will benefit the Company and its customers through improvement from the current situation in safety, environmental stewardship and reliability.

The results of this feasibility analysis show that that the continued operation of the Rattling Brook hydroelectric development is economically viable over the long term. Investing in the life extension of facilities at Rattling Brook guarantees the availability of low cost energy to the Province. Otherwise the annual production of nearly 69.4 GWh would be replaced by more expensive energy sources such as new generation or additional production from the Holyrood thermal generating station.

Schedule A
Summary of Capital Costs

**Rattling Brook Feasibility Analysis
Summary of Capital Costs**

| Description | Cost (2005) |
|---|---------------------|
| Civil | |
| Civil Engineering (2005) | \$ 150,000 |
| Penstock Replacement – Phase 1 (2006) | 3,940,000 |
| Penstock Replacement – Phase 2 (2007) | 3,840,000 |
| Refurbish Surge Tank (2007) | 892,000 |
| Amy’s Control Structure Rehab (2007) | 30,000 |
| Amy’s Dam Slope Improvements (2015) | 100,000 |
| Rattling Spillway Rehabilitation (2015) | 100,000 |
| Subtotal Civil | \$9,052,000 |
| Mech/Elec | |
| Refurbish Plant Engineering (2005) | \$ 200,000 |
| Unit 1 Refurbishment (2006) | 851,000 |
| Unit 1 Refurbishment (2007) | 230,000 |
| Unit 2 Refurbishment (2006) | 852,000 |
| Unit 2 Refurbishment (2007) | 375,000 |
| Forebay Water Level Control (2007) | 42,000 |
| Subtotal Mech/Elec | 2,550,000 |
| Total | \$11,602,000 |

Schedule B
Summary of Operating Costs

Rattling Brook Feasibility Analysis Summary of Operating Costs

Annual Operating Costs (actuals)

| <u>Year</u> | <u>Amount</u> |
|-------------|---------------|
| 1999 | \$158,963 |
| 2000 | \$149,301 |
| 2001 | \$237,556 |
| 2002 | \$172,364 |
| 2003 | \$232,081 |
| Average | \$190,053 |

5-year Average Operating Cost = \$190,053

Water Use Charges = \$56,000
(\$0.80/MWh * 70,000 MWh/yr)

Reduced Future Penstock Maintenance = \$10,000 (-ve)

Total Annual Operating Cost = \$236,053
(forecasted)

Project Title: **Rebuild Substations**

Location: **Greenspond, Grand Beach, Topsail and St. John's Main**

Classification: **Substations**

Project Cost: **\$351,000**

This project consists of a number of items as noted.

(a) Enclose Switchgear Buildings at St. John's Main Substation

Cost: \$251,000

Description: At St. John's Main substation there are three sections of 15kV metalclad switchgear housing a total of 17 air circuit breakers. This project involves the construction of two buildings around the switchgear to enclose and protect them from the weather.

Operating Experience: The existing weather enclosures for the three sections of switchgear are in advanced stages of deterioration. Deterioration is such that the roofs of the existing buildings are leaking and there is rusting of the metalclad weather enclosures and switchgear support frame to the extent that the buildings are no longer weatherproof. Corrective action needs to be taken to stop further deterioration (see attached pictures).



St. John's Main Substation
Deteriorated Metal Clad Switchgear
Picture #1



St. John's Main Substation
Deteriorated Metal Clad Switchgear
Picture #2



**St. John's Main Substation
Deteriorated Metal Clad Switchgear
Picture #3**

Justification: The overall project is justified based on employee safety and maintaining the reliability of the electrical system.

(b) Projects < \$50,000

Cost: \$100,000

The following is a list of projects estimated at less than \$50,000.

1. Greenspond – replace feeder by-pass switch
2. Grand Beach – replace substation fence
3. Topsail – replace transformer foundation
4. Stephenville – install personnel gates

| | |
|------------------------|--|
| Project Title: | Replacement & Standby Substation Equipment |
| Location: | Various Substations including Rocky Pond, Hardwoods, Twillingate, and Garnish |
| Classification: | Substations |
| Project Cost: | \$1,052,000 |

This project consists of a number of items as noted.

(a) Deteriorated Breaker/Recloser Replacement

Cost: \$81,000

Description: This project is part of an ongoing program to replace circuit breakers and reclosers that are deteriorated beyond economical repair.

In 2005 the 6.9 kV breaker at Rocky Pond will be replaced.

Operating Experience: The Rocky Pond unit is 27 years old. The arc extinguishing mechanisms has deteriorated and the manufacturer has informed us that parts are no longer available. Failure of these parts will limit the ability of the breaker to extinguish the arc produced during a fault. This can ultimately lead to catastrophic failure.

Justification: This project is justified based on the need to replace equipment to maintain reliable and safe operation of the electrical system.

(b) Underrated Interrupting Capacity Breaker Replacement

Cost: \$79,000

Description: This project replaces circuit breakers that have a fault current interrupting less than the fault current levels present at a substation.

In 2005, the 25 kV breaker serving Hardwoods – 04 distribution feeder will be replaced.

Operating Experience: At Hardwoods Substation the substation fault level is approximately 16 KA, which exceeds the maximum fault interrupting capacity of HWD-04 feeder breaker which has a fault interruption capacity of 12.5 KA.

Justification: This project is justified based on the fact that equipment ratings have been exceeded. This could result in failure of the equipment and compromise safety, reliability and the environment.

(c) Corporate Spares & Replacements

Cost: \$850,000

Description: Purchase equipment to be used for corporate spares.

For 2005, the budgeted figure includes:

- 1 – 15/25 kV Circuit Breaker
- 1 – 25 kV Electronic Recloser
- 3 – 138 kV Potential Transformers
- 3 – 66 kV Potential Transformers
- 6 – 15/25 kV 100 amp Voltage Regulators
- 9 – 15/25 kV 200 amp Voltage Regulators
- 10 – Universal Regulator Controls and Enclosures
- 1 – 15/25 kV 300 amp Voltage Regulator
- 2 – 48 Volt Battery Banks
- 3 – 120 Volt Battery Bank
- 2 – 48 Volt Battery Chargers
- 3 – 120 Volt Battery Chargers
- 6 – Transformer – on Load Tap Changers

This equipment is required to either replace equipment that fails in the field or to return corporate spares to appropriate levels.

Operating Experience: Every year the Company retires equipment due to vandalism, storm damage, lightning strikes, electrical or mechanical failure, corrosion damage, technical obsolescence, failure during maintenance testing, etc. This equipment is essential to the integrity and reliability of the electrical supply to our customers and as such, the Company has to be able to replace equipment that has failed, in a timely manner. Based on past operating experience, the above list is representative of what will need to be replaced in a typical year.

Justification: This project is justified on the basis that this equipment is necessary to maintain service in a reliable, safe, environmentally sound manner. The following provides details on the major components to be acquired in 2005.

Circuit Breakers:

Newfoundland Power has approximately 400 circuit breakers in service. Breakers are used to switch transmission lines, transformers, feeders, generators and other equipment on and off the electrical system. In conjunction with protective relaying, they are used to isolate electrical faults. The majority of breakers are either transmission breakers (138 or 66 kV) or distribution breakers (typically 15 or 25 kV). The remainder are required in generation stations. The older breakers are often oil-filled and represent an environmental risk. By the nature of their operation, breakers will deteriorate and even though they are maintained, unexpected failures can occur.

Based on past experience, the Company maintains a pool of spare breakers to respond to these failures. This pool normally contains one 138 kV, two 66 kV and two 25 kV breakers. The 25 kV units can be installed in either 15 or 25 kV installations, thereby reducing the number of spares required. The budget is based upon past experience and existing quantities in the pool.

Electronic Reclosers:

The Company has approximately 200 reclosers in service. Reclosers allow switching of rural feeders, which carry lighter loads and have smaller electrical fault levels than urban feeders. They have built-in control units that sense electrical faults and operate the recloser to de-energize the feeder in the event of a fault.

The Company's older reclosers can be divided into four basic types – hydraulic, relay, resistor, and electronic, depending upon controller. The ability to isolate an electrical fault and functionality increases in the order they are listed above. Therefore, as the electrical system has evolved, the units with lower functionality have fewer places where they can be installed.

Reclosers are replaced due to failure; deterioration; and, obsolescence. In order to respond to these situations, the Company maintains a pool of spare reclosers. The budget is based upon past experience and existing quantities in the pool. The purchased unit will be an oil free, low maintenance and digitally controlled so that it is capable of replacing any other recloser.

Potential Transformers (PTs):

The Company has approximately 220 PTs in-service. They measure voltage levels for input to protective relays, the SCADA system and metering circuitry. Failure of this equipment compromises the reliable operation of the electrical system. A failure can endanger staff and require clean up of oil. Each year unexpected PT replacements are required due to in-service failures. Based upon past experience and existing quantities in the pool, the budget includes purchases to allow for response to operational situations. Normally new units will be a *dry-type* design, eliminating the environmental risk associated with the older oil-filled units.

Voltage Regulators:

The Company has approximately 340 voltage regulators in service. These regulators are used to control voltages on rural feeders.

The regulators are replaced due to failure or deterioration. The budget is based upon past experience and existing quantities in the pool. The replacements will maintain the pool of spare voltage regulators at a level sufficient to respond to operational situations and maintenance programs. The new units can operate at 15 or 25 kV, allowing a reduction in the size of the pool. They also have stainless steel cases to reduce future corrosion related failures.

Direct Current Electrical Supply Systems (Batteries and Battery Chargers):

The substation direct current (DC) power supplies provide electricity for protective relays, circuit breakers, reclosers and emergency substation lighting.

The use of advanced battery testing methods has allowed the Company to adopt an approach whereby battery banks are replaced only when problems to a majority of batteries in the bank occur. Based upon past experience, the budget includes an allocation to replace battery banks as required.

Battery chargers are low maintenance, long life devices. The Company maintains a pool of units to allow prompt replacement of failed units to ensure the security of its DC electrical supplies. The units in the budget will allow for unexpected failures of battery chargers.

(d) Recording Voltmeter Replacement

Cost: \$42,000

Description: This project involves the replacement of broken recording voltmeters at Twillingate and Garnish.

Operating Experience: The existing recording voltmeter has deteriorated beyond repair.

Justification: The recording voltmeters are required to properly manage the power system and to address voltage quality concerns.

Project Title: Rebuild Transmission Lines

Location: Various

Classification: Transmission

Project Cost: \$2,597,000

This project consists of a number of items as noted.

(a) Rebuild 11L (Tors Cove – Mobile)

Cost: \$343,000

Description: This project consists of the replacement of deteriorated poles, hardware and conductor on 5.0 km of 11L.

Operating Experience: 11L is a 66 kV line that was built in 1942. It provides a tie between the Tors Cove hydro plant and the main electrical grid. In 2000, \$9,000 was spent and in 2002 \$15,000 was spent correcting deficiencies identified during regular inspections.

Justification: Inspections have determined that there is significant deterioration of the poles, crossarms and other hardware on the 5.0 km line. Upgrading of this line is necessary to ensure continuity of service to customers in the area as well as provide the Tors Cove hydro plant with a safe and secure connection to the main grid.

(b) Rebuild 43L (Hearts Content – New Chelsea)

Cost: \$707,000

Description: This project consists of the replacement of deteriorated poles, hardware and conductor on an 8.0 km section of 43L.

Operating Experience: 43L is a 66 kV line that was built in 1956. It is a 25.1 km radial line servicing in excess of 2,500 customers in the New Chelsea – Old Perlican area of the Bay de Verde peninsula. It also provides a tie between the New Chelsea hydro plant and the main electrical grid. In 2001, 2002 and 2003, \$85,000, \$6,000 and \$7,000 respectively was spent correcting deficiencies identified during normal inspection.

Justification: Inspections have determined that there is significant deterioration of the poles, crossarms and other hardware on 43L. Upgrading of this section of line is necessary to ensure continuity of service to customers in the New Chelsea – Old Perlican area as well as to provide the New Chelsea hydro plant with a secure connection to the main grid. It is anticipated that the remaining 17 km of line will be rebuilt during 2006 and 2007.

(c) Rebuild 124L (Clareville – Gambo)

Cost: \$500,000

Description: This project consists of rebuilding a 5.0 km section of 124L to establish and maintain adequate ground clearance.

Operating Experience: 124L is a 138 kV line that was built in 1964. The line which runs from Clareville to Gambo has a total length of 90 km. It is a loop line; however, it directly serves in excess of 2,700 customers in the Port Blandford, Glovertown and Eastport areas. It was constructed using a wind/ice loading criteria that is lower than today's standard. Inspections and surveys during the past few years have identified sections where the conductor has stretched and sagged to unacceptable levels due to past severe ice loading in the area.

In 2001 and 2003, a 5.2 km section and a 5.5 km section were rebuilt at a cost of \$323,000 and \$424,000 respectively.

During the winter of 2003, an older section of line experienced crossarm failure during a period of ice accumulation. This resulted in conductors falling to the ground, causing a lengthy outage.

Justification: Inspections have identified a number of locations where adequate ground clearance cannot be maintained during ice/wind conditions. Rebuilding a 5.0 km section will address a number of these locations.

It is anticipated that the remaining locations will be addressed through rebuilding a 6.4 km section in 2006.

(d) Projects < \$50,000

Cost: \$1,047,000

Description: There are approximately 50 other lines that require replacement of deteriorated items.

Operating Experience: Annual inspections have identified deteriorated items that need to be replaced.

Justification: This project is necessary to replace poles, crossarms, conductors, insulators and miscellaneous hardware due to deficiencies identified during annual inspections in order to ensure that such lines provide safe and reliable service to customers.

Project Title: **Distribution Reliability Initiative**

Location: **Lumsden/Cape Freels (WES-02), Carmanville/Gander Bay (GBY-02)**

Classification: **Distribution**

Project Cost: **\$872,000**

This project consists of a number of items as noted.

(a) Lumsden/Cape Freels (WES-02)

Cost: \$407,000

Description: This project involves the replacement of poles, conductor and hardware on various sections of WES-02. This is a 2-year project at a total cost of \$1,099,000 of which \$692,000 was spent in 2004.

Operating Experience: The reliability of this feeder is below the company average. See 2004 Capital Budget Application, *“A Review of Reliability Wesleyville-02 Feeder”*, Volume III, Distribution, Appendix 3, Attachment A.

Justification: This project is justified on the basis of reliability improvements.

(b) Carmanville/Gander Bay (GBY-02)

Cost: \$465,000

Description: This project involves the replacement of poles, conductor and hardware on various sections of GBY-02. This is a 2-year project at a total cost of \$863,000, consequently \$398,000 will be required in 2006.

Operating Experience: The reliability of this feeder is below the Company average. See *“A Review of Reliability – Gander Bay-02Feeder”*, Distribution, Appendix 1, Attachment A.

Justification: This project is justified on the basis of reliability improvements.

A Review of Reliability
Gander Bay-02 Feeder

June 18, 2004

Written by: Mick Ellsworth
Approved by: Peter Feehan, P. Eng

Table of Contents

| | Page |
|--|-------------|
| 1.0 Executive Summary | 1 |
| 2.0 Introduction..... | 1 |
| 3.0 Distribution Reliability | 1 |
| 4.0 GBY-02 Feeder..... | 2 |
| 5.0 Outage History for Feeder | 2 |
| 5.1 GBY-02 Feeder by Component that Failed | 3 |
| 5.2 GBY-02 Feeder by Cause | 4 |
| 6.0 Alternatives | 4 |
| 6.1 Install a New Substation at Carmanville..... | 5 |
| 6.2 Rebuild / Relocate GBY-02 Trunk Feeder | 5 |
| 7.0 Detailed Review of Selected Alternative..... | 6 |
| 7.1 All Sections of GBY-02 Feeder | 6 |
| 7.2 Gander Bay Substation to Harris Point (0.6 km) | 6 |
| 7.3 Harris Point (1.8 km) | 6 |
| 7.4 Harris Point to Old Road Intersection (1 km)..... | 7 |
| 7.5 Old Road Section (3.1 km) | 7 |
| 7.6 Davidsville Section (4.1 km) | 7 |
| 7.7 Structures along Route 330 (2.7 km) | 8 |
| 7.8 Carmanville (2.6 km) | 8 |
| 7.9 Carmanville to End of Feeder (1.2 km) | 8 |
| 7.10 Construction Cost..... | 9 |
| 8.0 Conclusion | 9 |
| Appendix A: Load Growth per Year Forecasted Undiversified Peak | |
| Appendix B: Map Showing Gander Bay Substation to Harris Point (0.6 km) | |
| Appendix C: Map Showing Harris Point (1.8 km) | |
| Appendix D: Map Showing Harris Point to Old Road Intersection (1 km) | |
| Appendix E: Map Showing Old Road Section (3.1 km) | |
| Appendix F: Map Showing Davidsville Section (4.1 km) | |
| Appendix G: Map Showing Regulator Structure along Route 330 (2.7 km) | |
| Appendix H: Map Showing Carmanville (2.6 km) | |
| Appendix I: Map Showing Carmanville to end of Feeder (1.2 km) | |
| Appendix J: Pictures | |

1.0 Executive Summary

The purpose of this report is to recommend measures to improve reliability on the Gander Bay-02 feeder (“GBY-02”), which has exhibited poor reliability performance. The feeder was examined in sections with a detailed look at the causes of outages and the components that failed. This was combined with field knowledge of the feeders to produce recommended actions to improve reliability.

GBY-02 originates at Gander Bay Substation in Gander Bay. It has been prone to failure, mainly due to the condition of its primary conductor (#2 ACSR) and the failure of insulators. Outages have been extended due to the inaccessibility of some sections of the line. Along this section of the north east coast, the feeder is exposed to high winds, salt spray, ice loading, and lightning strikes. Upgrading the feeder is recommended, at a cost of approximately \$863,000.

This project will have a positive effect on the reliability performance of this feeder, resulting in fewer outages to customers and lower operating costs. Due to the cost and resources required for the project, it is recommended that the work be completed over two years.

2.0 Introduction

This report recommends a plan to improve the reliability of GBY-02. This report contains information on the reliability performance and on how this feeder compares with other Newfoundland Power feeders. Also included is information about the outage history and the major causes and trouble areas. Recommendations are based on costs and the suitability of the options considered.

3.0 Distribution Reliability

A Newfoundland Power report titled “2004 Corporate Distribution Reliability Review” identified feeders that have exhibited consistently poor reliability. The report examined such items as the average annual total number of customer minutes of interruption, System Average Interruption Frequency Index (SAIFI), and the System Average Interruption Duration Index (SAIDI). The report concluded that GBY-02 was amongst the poorest reliability performers and should have work completed to improve its performance.

For the period 1999 to 2003, SAIFI was 3.45 and SAIDI was 8.18 hours. The Company average for the same period for SAIFI was 1.56 and for SAIDI was 2.30 hours.

4.0 GBY-02 Feeder

Located in the Gander operating area of the Western Region, GBY-02 feeder is a 25 kV line that originates at the Gander Bay Substation located in the community of Gander Bay and serves approximately 886 customers. The three-phase portion of this line extends from Gander Bay to

Carmanville, passing through the communities of Harris Point, Main Point and Davidsville. Taps from Carmanville also service the communities of Noggin Cove and Frederickton.

This line was originally constructed in 1965. The majority of this feeder is conductored with #2 ACSR (Aluminium Conductor Steel Reinforced). However, 3.5 kilometres has been reconducted with 4/0 AASC (Aluminium Alloy Stranded Conductor). Many of the original spans were quite long. However, approximately 18 out of 20 kilometres have been mid-spanned to reduce span lengths. Highway upgrading and rerouting have caused several sections of this feeder to become remote from the main road and, consequently, difficult to maintain.

The entire feeder is in an exposed area and is subject to salt contamination, very high winds, ice loading and lightning strikes.

A feeder inspection was completed in early 2004. The inspection revealed a number of items that need to be addressed. These include:

- Two Piece Insulators
- CP 8080 Deadend Insulators
- Porcelain Cutouts
- Lightning Arrestors
- Grounding and guying issues that could impact on employee and public safety
- Deteriorated Crossarms. These involve cracks developing in crossarms, rotting arms, woodpecker holes, etc.
- Conductor conditions such as broken strands, burn marks, etc.

5.0 Outage History for Feeder

The feeder is located 50 kilometres from Newfoundland Power's Gander Service Centre. Sections of the highway in this area are subject to heavy drifting, sometimes making the roads impassable for long periods of time. This can sometimes impact outage durations.

Sections of the main trunk of the feeder are located up to 1 kilometre off the new road right-of-way, making damage difficult to find and repair during winter storms. Another 3-kilometre section now crosses from Davidsville along the old highway, which is no longer maintained. These sections must be accessed by ATVs in the summer months. All sections located along the old road must be accessed by snowmobile during the winter months.

The bulk of the main trunk of the feeder is conductored with the original #2 ACSR. This conductor has poor operating characteristics in a salt spray environment. Over time, the outer aluminium strands break, leaving the steel core to carry the load. As the load increases, the steel core melts, breaking the conductor. Broken conductor has accounted for 38% of all distribution caused outages to the feeder. An inspection of the feeder conducted in 2004 noted several locations where the conductor is frayed.

As most of the main trunk of the feeder has been mid-spanned, the insulators on the newer structures are in good shape and have not caused outages. The remaining insulators on the original poles have been prone to failure. Outages due to insulator failure account for 21.5% of all distribution caused outages to the feeder.

5.1 GBY-02 Feeder by Component that Failed

Table 1 below shows a summary of the 115 problem calls received from 1999 to 2003, indicating which failed component caused the problem. In some occurrences, such as in sleet and windstorms, there are no components that failed. (Fuses and substation equipment that operate under these conditions are operating properly.)

| Table 1 Problem Call Summary by Component 1999 – 2003 | | |
|--|--------------------------|-------------------------|
| Component that Failed | Number of Outages | Customer Minutes |
| Conductor | 10 | 821,472 |
| Conductor Hardware | 1 | 440 |
| Fuses ¹ | 41 | 116,337 |
| Insulators | 7 | 461,446 |
| Other | 2 | 44,202 |
| Control Equipment at Sub ² | 9 | 682,675 |
| Pole Hardware | 3 | 1,030 |
| Transformers | 5 | 5,386 |
| Service Wires | 27 | 3,485 |
| Cutout / Switch | 10 | 33,837 |
| Total | 115 | 2,170,310 |

¹ Fuses operated as a result of sleet, wind, and lightning.

² Includes operations for wind, trees in line etc. Equipment operated as it should.

5.2 GBY-02 Feeder by Cause

Table 2 below summarizes the 115 problem calls received for the time frame from 1999 to 2003. Problems are sorted using the “Cause” as its base.

| <p style="text-align: center;">Table 2 Problem Call Summary by Cause 1999 – 2003</p> | | |
|---|--------------------------|-------------------------|
| Cause | Number of Outages | Customer Minutes |
| Salt Spray ¹ | 7 | 10,768 |
| Wind | 18 | 966,736 |
| Lightning | 7 | 2,962 |
| Broken/Defective Equipment ² | 64 | 923,281 |
| Damage Outside Party | 4 | 208,180 |
| Unexplained | 6 | 33,733 |
| Other | 1 | 18,837 |
| Overloaded Equipment | 2 | 1,831 |
| Animals | 5 | 3,972 |
| Fire | 1 | 10 |
| Total | 115 | 2,170,310 |

¹ Although only seven outages were reported as salt spray, most of the outages reported as wind involved salt contamination also.

² Broken/Defective Equipment includes items such as insulators, conductor and hardware. In a windstorm, outages can occur due to trees on line, damage to conductor, etc.

6.0 Alternatives

Two alternatives are considered to improve reliability of the GBY-02 feeder. These alternatives are:

1. Install a New Substation at Carmanville.
2. Rebuild / Relocate GBY-02 Trunk Feeder

These alternatives are discussed in the following sections.

6.1 *Install a New Substation at Carmanville*

Since the mid-1970's, several studies have examined the viability of building Carmanville Substation. Transmission line 129L, which extends from Gander Bay to Carmanville, was built in 1979, and utilized as a feeder with the expectation that the increased load in the area would warrant the building of the substation shortly thereafter. When the expected load growth did not materialize, plans to build Carmanville Substation were shelved.

Studies since then have supported the continued deferral of Carmanville Substation, which was accomplished by various means. 129L has been utilized as a distribution feeder (GBY-03) relieving the load requirements on GBY-02. Gander Bay Substation has changed from the original two power transformer set up to a single transformer with an on-line tap changer. This added transformer capacity to the area while also improving voltage regulation.

Load forecasts for the next 20 years do not indicate an overload condition on the power transformer (Appendix A provides the 20-year load forecast for this area). Feeder model computer simulation using the 20-year forecast does not indicate any overload or under voltage condition on GBY-02. However, the installation of the new substation would eliminate the need to rebuild/relocate the 3.3 km section of line along the abandoned highway near Davidsville. This section would be retired and not replaced. The capital cost of a new substation installation and feeder work directly related to the substation installation is estimated at \$1,834,900.

Although an already-constructed transmission line makes the Carmanville substation an option that ought to be looked at, building the new substation without upgrading the feeder will not address most of the reliability issues already identified. The alternative requires most of the same work on the feeder as the alternative described in Section 6.2, with the exception of the work on the 3.3 km section near Davidsville. Excluding the Davidsville section, the capital cost of correcting the identified feeder reliability issues is \$585,844. The total cost of this alternative is therefore \$2,420,744. Due to the considerable capital cost, this alternative is not recommended.

6.2 *Rebuild / Relocate GBY-02 Trunk Feeder*

The main trunk of this feeder was inspected to determine the cost of addressing deficiencies. This included access to the line, conductor replacement, insulator and pole replacements.

Relocating the main trunk of the feeder to the main road will shorten the time needed to patrol the line during feeder inspections and unscheduled outages. Currently, a feeder problem along the side of the abandoned road requires crews to return to Gander to obtain additional equipment. This increases the outage duration to customers.

Relocating the main trunk of the feeder to the road effectively places the distribution lines in the communities on side taps from the main feeder. Problems on these taps should not cause outages to other customers along the main trunk of the feeder. For example, under the existing situation, a problem on the primary in Harris Point results in a power interruption to 766 customers. If this

occurred on a tap off the main trunk, the same problem would be isolated by a fused cutout and would only cause an outage to the customers in the community of Harris Point.

This alternative would also correct a majority of the deficiencies noted in the feeder inspection. The total cost for this alternative is estimated at \$862,695.

Rebuilding / relocating the feeder using new 4/0 AASC primary conductor directly addresses the known problems and will have an immediate positive effect on the reliability of supply to our customers.

Details on each problem area follow in Section 7.

7.0 Detailed Review of Selected Alternative

The GBY-02 feeder was reviewed for location characteristics (i.e. subject to extreme salt spray conditions, ice loading etc.). Each section of the feeder was then analyzed to see if specific causes could be determined and appropriate solutions recommended.

7.1 All Sections of GBY-02 Feeder

1. Replace all 8080 and 2-piece insulators.
2. Correct all deficiencies identified in the inspection of the feeder conducted in 2004.

7.2 Gander Bay Substation to Harris Point (0.6 km)

This section of the main trunk of the feeder is conductored using #2 ACSR. It is located along Route 330 through Georges Point. This section will be reconductored using 4/0 AASC primary and a 1/0 AASC neutral. Deficiencies identified in the feeder inspection conducted in 2004 would be corrected.

Appendix B is a map of the area. Total estimated cost for this work is \$15,251.

7.3 Harris Point (1.8 km)

This section of the main feeder trunk is located away from Route 330 through the community of Harris Point. Relocating the main trunk to the highway would improve the overall condition of the main trunk while making patrol of the line easier. As noted above, placing Harris Point on a tap off the feeder will lessen the possibility of a problem in the community causing an outage on the remainder of the feeder. All new construction will use 4/0 AASC for the primary and 1/0 AASC for the neutral. The cost of the new construction is \$75,195. The cost associated with correcting deficiencies identified in the feeder inspection conducted in 2004 for this section of line is estimated at \$12,100.

Appendix C for a map of the area involved. The total estimated cost for completing all work required on this section is \$87,295.

7.4 *Harris Point to Old Road Intersection (1 km)*

This portion of the feeder consists of 500 metres of new construction that is located away from the road and another 500 metres of reconstruction along Route 330. Plans include relocating all portions of the feeder to the road right-of-way and upgrading the conductor to current standards using 4/0 AASC primary and a 1/0 AASC neutral. Moving the feeder to the right-of-way of Route 330 aids in the patrolling and inspection of the line, and also moves the line to a less wooded area. Deficiencies identified in the feeder inspection conducted in 2004 would be corrected.

Appendix D is a map of the area. The total estimated cost of this work is \$30,843.

7.5 *Old Road Section (3.1 km)*

This portion of the feeder consists of 3.3 kilometres of existing construction that is located along the old road. One half of the poles and insulators would have to be replaced in this section if the feeder was rebuilt in the existing location. All existing conductor here is #2 ACSR. This section must be accessed by ATVs in the summer months and snowmobiles during the winter months.

Relocating this section to the right-of-way of the new Route 330 would require 3.1 kilometres of new construction. Deficiencies identified in the feeder inspection conducted in 2004 would be eliminated by the retirement of the old line.

Appendix E is a map of the area. The total cost to rebuild this section is estimated at \$128,606.

7.6 *Davidsville Section (4.1 km)*

This portion of the existing feeder consists of 3.5 kilometres of line through the communities of Main Point and Davidsville and an additional 3.3 kilometres of line along the abandoned old highway. The existing conductor is #2 ACSR and 50% of the existing structures are original. This section must be accessed by ATVs in the summer months and snowmobiles during the winter months.

The new construction would see 4.1 kilometres of new line built along Route 330, making Main Point and Davidsville a tap off the main trunk of the feeder. The 3.3 kilometres along the abandoned highway would be removed. All new conductors would be 4/0 AASC primary and 1/0 AASC neutral. The cost estimate for this relocation / reconfiguration is \$276,851.

Relocating this section to the right-of-way of the new Route 330 will eliminate the need to correct deficiencies identified in the feeder inspection conducted in 2004 on the section of feeder along the abandoned road. The cost of correcting deficiencies on the 3.5 kilometres of line through the communities of Davidsville and Main Point is estimated at \$42,270.

In changing the configuration of the feeder, other customers on the feeder would be isolated from the impact of problems originating in the communities of Main Point and Davidsville. The two communities would now be on a tap that would be protected by a fuse. In the event of a problem on the tap, the fuse would operate, isolating the problem from the remainder of the feeder.

Appendix F is a map of the area. The total cost to relocate this section of line and correct deficiencies identified in the feeder inspection conducted in 2004 is estimated at \$319,121.

7.7 *Structures along Route 330 (2.7 km)*

This portion of the planned work consists of 2.7 kilometres of reconstruction along Route 330. Plans include replacing all existing #2 ACSR, re-insulating older structures, and correcting deficiencies identified in the feeder inspection conducted in 2004.

Appendix G is a map of the area. The total cost estimate for rebuilding this section of feeder is \$31,703.

7.8 *Carmanville (2.6 km)*

Plans for this section include the rerouting of the main line out of the Town of Carmanville to the right-of-way of Route 330. The Town of Carmanville will be supplied from a tap off the main feeder and outages in the town will be isolated and will not affect other customers on the feeder. In addition, Carmanville would now be energized from two directions. This will further add flexibility in isolating faults and minimizing customer outages.

The cost to rebuild this section of feeder is estimated at \$87,161. The cost of correcting deficiencies identified in the feeder inspection conducted in 2004 in the communities of Carmanville, Noggin Cove and Frederickton is \$145,157.

Appendix H is a map of the area. The total cost to rebuild this section in the new location and correct the identified deficiencies is estimated at \$232,318.

7.9 *Carmanville to End of Feeder (1.2 km)*

This portion of the planned work consists of 1.2 kilometres of reconstruction along Route 330. Plans include replacing all existing #2 ACSR, re-insulating older structures, and correcting deficiencies identified in the feeder inspection conducted in 2004.

Appendix I is a map of the area. The total cost estimate for rebuilding this section of feeder is \$17,558.

7.10 Construction Cost

| Gander Bay-02 Feeder Construction Cost | |
|---|------------------|
| Section | Cost |
| 7.2: Gander Bay Substation to Harris Point (0.6 km) | \$15,251 |
| 7.3: Harris Point (1.8 km) | 87,295 |
| 7.4: Harris Point to Old Road Intersection (1 km) | 30,843 |
| 7.5: Old Road Section (3.1 km) | 128,606 |
| 7.6: Davidsville Section (4.1 km) | 319,121 |
| 7.7: Structures along route 330 (2.7 km) | 31,703 |
| 7.8: Carmanville (2.6 km) | 232,318 |
| 7.9: Carmanville to end of feeder (1.2 km) | 17,558 |
| Total | \$862,695 |

8.0 Conclusion

Outage data does not indicate that GBY-02 should be built using heavy loading construction. Seventy-seven per cent of all outages were directly related to conductor, conductor and pole hardware, trees in line, cutout failure and insulators. Rebuilding of the feeder will correct these problems. Relocating the feeder will shorten patrol times in responding to problem calls as well as help in the isolation of the problem area from the rest of the feeder.

Deficiencies identified in the feeder inspection conducted in 2004 should be corrected. These are known problems that could result in unscheduled outages or unsafe conditions to our customers and employees if not corrected.

There were two different options for improving the reliability of this feeder considered.

- Installing a new substation at Carmanville
- Rebuild / Relocate GBY-02 Trunk Feeder

The Rebuild / Relocate GBY-02 Trunk Feeder offered the best solution to the current problems on this feeder. The Rebuild / Relocate GBY-02 Feeder Project for the trunk feeder will result in a reduction in the number and duration of outages to customers along this feeder. By supplying communities along the feeder through taps from the main trunk, we will be minimizing the impact of a problem on one section of the feeder causing outages to all customers on the feeder.

Overall, the \$862,695 investment to improve areas of the feeder with known problems will result in improved reliability for the customers. Due to the size and nature of the project, it is proposed to complete all the work over a two-year period. The work identified in Sections 7.5, 7.7, 7.8 and 7.9, along with the deficiencies identified in the feeder inspection conducted in 2004 noted

in Sections 7.3 and 7.6, should be completed in 2005. The total cost of this work is estimated at \$464,555. The remaining work, estimated at \$398,140, should be completed in 2006.

Appendix A

**Load Growth per Year
Forecasted Undiversified Peak**

| Appendix A Load Growth per Year Forecasted Undiversified Peak | | |
|--|---------------------|-------------------|
| Year | Growth | Load (Mva) |
| 2003 | | 7.30 |
| 2004 | 13.12% ¹ | 8.26 |
| 2005 | 0.76% | 8.32 |
| 2006 | 0.56% | 8.37 |
| 2007 | 1.97% | 8.53 |
| 2008 | 1.82% | 8.69 |
| 2009 | 0.73% | 8.75 |
| 2010 | 0.75% | 8.82 |
| 2011 | 0.77% | 8.88 |
| 2012 | 0.79% | 8.95 |
| 2013 | 0.81% | 9.03 |
| 2014 | 0.82% | 9.10 |
| 2015 | 0.84% | 9.18 |
| 2016 | 0.86% | 9.26 |
| 2017 | 0.88% | 9.34 |
| 2018 | 0.90% | 9.42 |
| 2019 | 0.91% | 9.51 |
| 2020 | 0.93% | 9.60 |
| 2021 | 0.95% | 9.69 |
| 2022 | 0.97% | 9.78 |
| 2023 | 0.99% | 9.88 |
| 2024 | 1.00% | 9.98 |

¹ The 13.12% growth in 2004 reflects both the normal load growth, similar in size to the subsequent years, and an allowance for a colder than normal peak. This allowance is based on one in ten year's worse case peak.

Source:

2003 – Actual


2004 to 2009 - 2004 5 year Substation Load Forecast

2010 to 2024 - Load growth in 2024 to be 1%. All other years prorated to this

Appendix B

**Map Showing Gander Bay Substation
to Harris Point (0.6 km)**


Appendix B



Appendix C

Map Showing Harris Point (1.8 km)


Appendix C



Appendix D

**Map Showing Harris Point to
Old Road Intersection (1 km)**


Appendix D



Appendix E

Map Showing Old Road Section (3.1 km)


Appendix E



Appendix F

Map Showing Davidsville Section (4.1 km)


Appendix F



Appendix G

**Map Showing Regulator Structure
along Route 330 (2.7 km)**


Appendix G



Appendix H

Map Showing Carmanville (2.6 km)


Appendix H



Appendix I

**Map Showing Carmanville to
End of Feeder (1.2 km)**

Appendix I



Appendix J

Pictures

Appendix J



**Center Phase has “Bird caging” along old splice.
Note previous repair on outside phase.
Picture #1**



**Another location with “Bird Caging” with a splice in the conductor.
Picture #2**



**Another Span with 3 splices in the #2 ACSR.
Picture #3**



**This is typical of the sections of the feeder that follow the abandoned road.
This location is along Davidsville to the Regulator Structure.
Picture #4**

Project Title: Feeder Additions and Upgrades to Accommodate Growth

Location: Virginia Waters, Broad Cove and Grand Bay

Classification: Distribution

Project Cost: \$441,000

This project consists of a number of items as noted.

(a) Install New Feeder – VIR-08

Cost: \$319,000 – Distribution, \$51,000 – Substations, \$268,000

Description: This project involves the construction of a distribution feeder from Virginia Waters substation on Snows Lane.

Operating Experience: Load and customer growth in the east end of St. John's is causing certain electrical system parameters to exceed recommended guidelines.

Justification: An engineering study, "*St. John's East End Planning Study*" indicates that this proposal is the low cost alternative to maintain electrical system parameters within recommended guidelines. See Distribution, Appendix 2, Attachment A.

(b) Install Voltage Regulators – GBS-02 and BCV-04

Cost: \$122,000

Description: Install a bank of voltage regulators on GBS-02 and BCV-04.

Operating Experience: Voltage measurements taken during peak load conditions show that customers in the areas served by GBS-02 and BCV-04 experience voltage levels lower than the CSA recommended minimum.

Justification: This project is required to add voltage regulation to the system in order to alleviate voltage problems for customers in the area.

**St. John's East End Planning Study:
Virginia Waters, Ridge Road,
Broad Cove and Pulpit Rock Substations**

July 21, 2004

Prepared By:
Jennifer Meaney-Williams, P. Eng.

Table of Contents

| | Page |
|--|-------------|
| 1.0 Introduction | 1 |
| 2.0 Description of Existing System | 1 |
| 3.0 Technical Criteria | 2 |
| 4.0 Load Forecast and Capacity Limitations | 2 |
| 5.0 Alternatives | 3 |
| 5.1 Development of Alternatives | 3 |
| 5.1.1 Alternative # 1 | 3 |
| 5.1.2 Alternative # 2 | 4 |
| 5.1.3 Alternative # 3 | 5 |
| 5.2 Economic Analysis | 6 |
| 6.0 Recommendations | 7 |
| Appendix A: Substation and Feeder Load Forecast | |
| Appendix B: Feeder Capacity Ratings | |
| Appendix C: Substation and Feeder Drawing | |
| Appendix D: Alternative #1 Substation and Feeder Load Forecast | |
| Appendix E: Alternative #2 Substation and Feeder Load Forecast | |
| Appendix F: Alternative #3 Substation and Feeder Load Forecast | |

1.0 Introduction

The purpose of this study is to determine the distribution system alternative that best meets the electrical demands of the east end of St. John's, in the Winsor Lake, Virginia Waters and Newfoundland Drive areas. The installation in 2003 of an additional 25 MVA transformer at Virginia Waters (VIR) substation addressed an existing transformer overloading issue. However, two issues remain. The first issue is continued growth in the commercial and residential sectors near the VIR substation including addition of a water filtration plant in 2005 at Winsor Lake. The second issue is the forecasted loading on particular distribution feeders at the VIR, Ridge Road (RRD), Pulpit Rock (PUL) and Broad Cove (BCV) substations.

This study projects the electrical demands for the St. John's east end to the year 2023, develops technical alternatives to meet these demands, and determines the most cost effective alternative.

2.0 Description of Existing System

The St. John's east end is electrically supplied from the island grid through the Oxen Pond 230/66 kV substation. 66 kV transmission lines connect the Oxen Pond supply point to a number of 66/12.5 kV substations in the east end. These 66/12.5 kV substations supply feeders that distribute electricity to the various customers within the east end of the city.

The VIR substation is located on Snow's Lane in St. John's. It currently has seven distribution feeders serving 5,800 customers. This substation has experienced a high load growth over the past 7 years associated with the Stavanger Drive commercial area, and residential subdivisions such as Clovelly, King William Estates, Caroline Estates, Pine Ridge Creek and the Woodlands development. To address this increasing load, a distribution feeder was added in 2000 and a transformer was added in 2003.

The Ridge Road (RRD) substation is located at the intersection of Ridge Road and Higgin's Line in St. John's. It has 8 distribution feeders serving a total of 4,200 Customers. This area has also experienced growth primarily associated with residential construction along Airport Heights Drive. Future residential growth in this area will be somewhat restricted by the St. John's watershed, Pippy Park golf course and the airport. Planned commercial activity in the area includes the addition of a water filtration plant at Winsor Lake.

The Broad Cove (BCV) substation is located in St. Philip's on Belbins Road and has four distribution feeders, all operating at 12.5 kV. The total number of customers supplied from this substation is 4,100. The BCV substation is experiencing moderate growth. Most of the growth is composed of small subdivision (5-15 lots) and infill housing. In order to defer the addition of a second transformer at Broad Cove, during the past few years, portions of a Broad Cove feeder (BCV-03) have been converted to 25 kV and transferred to Hardwoods substation.

The Pulpit Rock (PUL) substation is located in Torbay on Whiteway's Pond Road and currently has two feeders, PUL-01 and PUL-02, both operating at 12.5 kV. The total number of customers fed from this substation is 3,500. A third feeder, PUL-03, is being added in 2004. These feeders are also experiencing moderate growth, with small subdivisions and infill housing being constructed throughout the service area.

3.0 Technical Criteria

The following technical criteria were utilized to develop various alternatives that meet the forecasted load growth:

- The steady state substation power transformer loading should not exceed the transformer nameplate rating.
- The conductor loading should not exceed the ampacity rating established in the Company's Distribution Planning Guidelines.
- The distribution feeder normal peak loading should be restricted to permit load pickup during outage conditions. These restrictions are based on three factors: substation equipment capacity, underground cable capacity and trunk feeder conductor capacity.

4.0 Load Forecast and Capacity Limitations

Base case values for the load forecast for each individual feeder utilized historical data for the period 1996 to 2003.

Growth projections were developed through the analysis of existing loads and in consultation with personnel familiar with the growth in the areas in question. It was determined that the future growth will be mostly residential, as most of the Stavanger Drive commercial area is complete. The growth will occur mainly in: the area bound by Clovelly Golf Course, Pine Line and Logy Bay Road; the area bound by King William Estates and Logy Bay Road; continued growth in the Pine Ridge Creek area; and some additional residential growth in the Airport Heights vicinity. Based on these assumptions, various growth rates were allocated to each feeder. This information was then used to create a 20-year load forecast for capacity planning purposes. The 20 year substation and feeder base load forecast and associated substation capacities are set out in Appendix A. As well, feeder ampacity ratings are noted in Appendix B. The feeder limitation is the winter planning rating of the feeder (MVA). Cold load pickup (CLPU) factors were assigned to various substations as follows:

1. VIR and RRD are assigned a CLPU factor of 2.0 due to high penetration of electric heat.
2. BCV and PUL are assigned a CLPU factor of 1.6 due to the nature of rural feeders. The exception is BCV-02, which has two down line reclosers that are sectionalized when picking up load; therefore, the CLPU factor is 1.33.

The load forecast (see Appendix A) indicates that the peak load on feeders VIR-06 and RRD-09 exceeds feeder capacity in the short term. The 2003 transformer capacity addition at VIR has resulted in significant transformer capacity being available at VIR. However, there are loading issues associated with transformer capacity at RRD, BCV and PUL. If no action is taken, the transformer loads at RRD, BCV and PUL will exceed capacity in 2011, 2016 and 2017 respectively. The transformer capacity deficit can be met through either adding transformer capacity at the substation or transferring load from RRD, BCV and PUL substations to neighbouring substations. If no action is taken, at the end of the 20-year substation forecast period, RRD will be at 140% of transformer capacity, BCV will be at 110%, VIR will be at 97%, and PUL will be at 113% of capacity.

The results of the base case load forecast contain the following technical criteria violations for the existing system:

1. VIR-06 peak load exceeds feeder capacity in 2004.
2. RRD-09 peak load exceeds feeder capacity in 2006 (includes filtration plant load).
3. RRD transformer peak load exceeds capacity in 2011.
4. PUL-02 peak load exceeds feeder capacity in 2012.
5. VIR-02 peak load exceeds feeder capacity in 2013.
6. VIR-03 peak load exceeds feeder capacity in 2013.
7. BCV transformer peak load exceeds capacity in 2016.
8. PUL transformer peak load exceeds capacity in 2017.

Consideration has also been given to load forecast sensitivity. Even with forecasts 2% higher or lower than the base case forecast, both VIR-06 and RRD-09 peak loads exceed recommended peak loads in 2004 and 2006, respectively.

5.0 Alternatives

5.1 *Development of Alternatives*

Alternatives are developed to meet the forecasted electrical demands and are limited to those that meet the technical criteria. These alternatives are evaluated using economic criteria. Based on this analysis, a preferred alternative is selected.

As an aid in interpreting each alternative, a substation feeder drawing is contained in Appendix C.

A description of each alternative follows.

5.1.1 *Alternative #1*

The first alternative is to construct a new 12.5 kV feeder (VIR-08) from the VIR substation in 2005. As well, when additional load is requested for the filtration plant at Winsor Lake, VIR-02 will be extended to the location at Winsor Lake. Load will be transferred to VIR-08 and VIR-05

from VIR-06 and VIR-02. In later years, an additional feeder is required at VIR, at PUL and at BCV. Additional load transfers within the substations accompany the new feeder construction to optimize feeder usage. The load forecast shows transformer capacity is required at RRD in 2013, at PUL in 2014, at BCV in 2018. The new feeders and associated transfers alleviate loading issues at RRD and VIR.

The following table notes timing, cost in today's dollars, and cost in escalated dollars for each component of Alternative 1. Capital costs are escalated by 2% per year.

| Alternative # 1 (\$000s) | | | |
|--|-------------|--|--|
| Description | Year | Capital Cost \$2005 x 1,000 | Escalated Cost 2%/ yr x \$1,000 |
| Construction of VIR-08 feeder | 2005 | 318 | 318 |
| Transfer 5 MVA from VIR-06 to VIR-08 and from 750 kVA VIR-02 to VIR-05 | 2005 | 1 | 1 |
| Construction of VIR-09 | 2013 | 350 | 410 |
| Construction of PUL-04 | 2013 | 300 | 351 |
| Construction of BCV-05 | 2013 | 300 | 351 |
| Load transfers within VIR, PUL, BCV | 2013 | 30 | 35 |
| Add additional 66-12.5, 25 MVA transformer at RRD substation | 2013 | 1,200 | 1,407 |
| Add additional 66-12.5, 25 MVA transformer at PUL substation | 2014 | 1,200 | 1,434 |
| Add additional 66-12.5, 25 MVA transformer at BCV substation | 2018 | 1,200 | 1,552 |
| Total Cost | | 4,899 | 5,859 |

See Appendix D for the load forecast by feeder and substation resulting from this alternative.

5.1.2 Alternative #2

The second alternative is to construct a new feeder from the RRD substation (RRD-11) in 2005. This alleviates the loading issue on RRD-09. There is a spare cubicle at RRD substation but the work to construct a new feeder is complex. Transformer capacity will still be an issue at RRD and so a 25 MVA transformer is added in 2006. In addition to dealing with RRD, the VIR-06 overloading should be addressed. To address this, VIR-06 will be offloaded onto PUL-01 and VIR-02, which will then be offloaded onto RRD-09. Future feeders are required at PUL in 2012, at VIR in 2013, and at BCV in 2018. Associated with all new feeder construction will be load transfers within the substation to optimize feeder usage. Transformer capacity is required at RRD in 2006, at PUL in 2013, and at BCV in 2016.

The following table notes timing, cost in today's dollars, and cost in escalated dollars for each component of Alternative 2.

| Alternative # 2 (\$000s) | | | |
|--|-------------|--|--|
| Description | Year | Capital Cost \$2005 x 1,000 | Escalated Cost 2%/ yr x \$1,000 |
| Construction of RRD-11 feeder | 2005 | 450 | 450 |
| Transfer 4.5 MVA from RRD-09 to RRD-11 | 2005 | 1 | 1 |
| Transfer 3.0 MVA from VIR-02 to RRD-09 | 2005 | 1 | 1 |
| Transfer 3.0 MVA from VIR-06 to VIR-02 | 2005 | 1 | 1 |
| Transfer 1.0 MVA from PUL-01 to PUL-03 | 2005 | 1 | 1 |
| Transfer 2 MVA from VIR-06 to PUL-01. | 2005 | 1 | 1 |
| Add additional 66-12.5, 25 MVA transformer at RRD Substation | 2006 | 1,200 | 1,224 |
| Add additional 66-12.5, 25 MVA transformer at PUL Substation | 2012 | 1,200 | 1,378 |
| Construction of PUL-04 | 2012 | 300 | 345 |
| Load transfers within PUL | 2012 | 10 | 12 |
| Construction of VIR-08 | 2013 | 350 | 410 |
| Load transfers within VIR | 2013 | 10 | 12 |
| Add additional 66-12.5, 25 MVA transformer at BCV Substation | 2015 | 1,200 | 1,463 |
| Construction of BCV-05 | 2018 | 300 | 388 |
| Load transfers within BCV | 2018 | 10 | 13 |
| Total Cost | | 5,035 | 5,700 |

See Appendix E for the load forecast by feeder and substation resulting from this alternative.

5.1.3 Alternative #3

This alternative is to construct a new PUL feeder to split the load on PUL-01 and VIR-06. As well, new feeders at VIR in 2012 and 2023, one new feeder at BCV in 2015 and one at RRD in 2018 is required. Associated with all new feeder construction will be load transfers within the substation to optimize feeder usage. The load forecast shows transformer capacity is required at PUL in 2007, at BCV in 2013 and at RRD in 2014. To address the VIR-06 overload, load will be transferred to PUL-01. Further load reconfiguration will occur within the PUL feeders to spread the load over all PUL feeders.

The following table notes timing, cost in today's dollars, and cost in escalated dollars for each component of Alternative 3.

| Alternative # 3 (\$000s) | | | |
|---|-------------|--|--|
| Description | Year | Capital Cost \$2005 x 1,000 | Escalated Cost 2%/ yr x \$1,000 |
| Construction of PUL-04 Feeder | 2005 | 450 | 450 |
| Transfer 4.5 MVA from VIR-06 to PUL-01 & 04 | 2005 | 1 | 1 |
| Transfer 1.0 MVA from RRD-09 to VIR-02 | 2005 | 1 | 1 |
| Transfer .75 MVA from RRD-09 to BCV-01 | 2005 | 1 | 1 |
| Transfer 1.5 MVA from VIR-02 to VIR-05 | 2005 | 1 | 1 |
| Transfer 1.5 MVA from PUL-01 to PUL-04 | 2005 | 1 | 1 |
| Transfer 1.5 MVA from PUL-02 to PUL-04 | 2005 | 1 | 1 |
| Transfer 1.0 MVA from PUL-03 to PUL-04 | 2005 | 1 | 1 |
| Add additional 66-25/12.5, 25 MVA transformer at PUL Substation | 2007 | 1,200 | 1,248 |
| Construction of VIR-08 | 2012 | 350 | 402 |
| Load transfers within VIR | 2012 | 10 | 12 |
| Add additional 66-25/12.5, 25 MVA transformer at BCV Substation | 2013 | 1,200 | 1,406 |
| Add additional 66-25/12.5, 25 MVA transformer at RRD Substation | 2014 | 1,200 | 1,434 |
| Construction of BCV-05 | 2015 | 300 | 366 |
| Load transfers within BCV | 2015 | 10 | 12 |
| Construction of RRD-11 | 2018 | 450 | 582 |
| Load transfers within RRD. | 2018 | 10 | 13 |
| Construction of VIR-08 | 2023 | 350 | 500 |
| Total Cost | | 5,537 | 6,432 |

See Appendix F for the load forecast by feeder and substation resulting from this alternative.

5.2 Economic Analysis

A NPV (net present values) analysis was performed for the capital costs associated with each alternative. Within each alternative, capital cost were present worth by first escalating the capital cost by 2% per year for price escalation and then present worthing each capital cost by the WAIC (weighted average incremental cost of capital at 8.52%).

The capital cost and NPV for each alternative is shown in the Net Present Value Analysis Table. The Table indicates that while the capital costs for the alternatives vary by 13% the NPV totals vary by 27%. Alternative #2 has the lowest escalated cost by 3%, and alternative #1 has the lowest NPV cost by 24%. This is primarily due to the much smaller costs in the very early years of the analysis period for alternative #1.

| Net Present Value Analysis (\$1,000) | | |
|---|-----------------------|--------------|
| Alternative | Escalated Cost | NPV |
| #1 | 5,859 (103%) | 2,870 (100%) |
| #2 | 5,700 (100%) | 3,566 (124%) |
| #3 | 6,432 (113%) | 3,655 (127%) |

6.0 Recommendations

A 20-year load forecast by feeder has projected the electrical demands for the east end of St. John's in the Stavanger Drive area and vicinity. The development and analysis of alternatives has established a preferred expansion plan to meet these needs.

The lowest NPV alternative that meets all of the technical criteria is alternative #1. It includes the 2005 construction of the VIR-08 feeder, as well as the offloading of VIR-06. It also includes future feeder construction and additional transformer capacity in the east end.

Appendix A

Substation and Feeder Load Forecast

APPENDIX A - Estimated Load Forecast (BASE) - CLPU factor = 1.6 for BCV and PUL (Rural) except 1.33 for BCV-02 and CLPU = 2.0 for VIR and RRD

| Feeders | CLPU Emerg | CLPU kVA | Planning | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 |
|-------------------|------------|----------|----------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|--------|--------|--------|--------|--------|
| VIR-01 | 785 | 16976 | 8488 | 5462 | 6157 | 6442 | 6711 | 6995 | 7217 | 7404 | 7596 | 7791 | 7992 | 8196 | 8405 | 8619 | 8837 | 9060 | 9288 | 9521 | 9759 | 10003 | 10251 |
| VIR-02 | 785 | 16976 | 8488 | 5854 | 6549 | 6834 | 7103 | 7387 | 7608 | 7796 | 7988 | 8183 | 8383 | 8588 | 8797 | 9011 | 9229 | 9452 | 9680 | 9913 | 10151 | 10395 | 10643 |
| VIR-03 | 785 | 16976 | 8488 | 5948 | 6643 | 6928 | 7197 | 7481 | 7703 | 7890 | 8082 | 8277 | 8478 | 8682 | 8891 | 9105 | 9323 | 9546 | 9774 | 10007 | 10245 | 10489 | 10737 |
| VIR-04 | 785 | 16976 | 8488 | 5199 | 5668 | 5860 | 6041 | 6233 | 6383 | 6509 | 6638 | 6770 | 6905 | 7043 | 7184 | 7328 | 7475 | 7626 | 7780 | 7937 | 8097 | 8262 | 8429 |
| VIR-05 | 785 | 16976 | 8488 | 5450 | 5919 | 6111 | 6292 | 6484 | 6633 | 6760 | 6889 | 7021 | 7156 | 7294 | 7435 | 7579 | 7726 | 7877 | 8030 | 8188 | 8348 | 8512 | 8680 |
| VIR-06 | 785 | 16976 | 8488 | 9154 | 10302 | 10772 | 11216 | 11686 | 12051 | 12361 | 12677 | 13001 | 13331 | 13669 | 14014 | 14366 | 14727 | 15095 | 15472 | 15857 | 16250 | 16652 | 17062 |
| VIR-07 | 785 | 16976 | 8488 | 5734 | 5960 | 6053 | 6140 | 6233 | 6305 | 6366 | 6429 | 6492 | 6557 | 6624 | 6692 | 6762 | 6833 | 6905 | 6980 | 7055 | 7133 | 7212 | 7293 |
| Sub Total | | | | 42800 | 47200 | 49000 | 50700 | 52500 | 53900 | 55086 | 56298 | 57536 | 58802 | 60096 | 61418 | 62769 | 64150 | 65561 | 67004 | 68478 | 69984 | 71524 | 73097 |
| VIR T1, T2, T3 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 |
| TFMR Requirements | | | | 42800 | 47200 | 49000 | 50700 | 52500 | 53900 | 55086 | 56298 | 57536 | 58802 | 60096 | 61418 | 62769 | 64150 | 65561 | 67004 | 68478 | 69984 | 71524 | 73097 |
| Capacity | | | | 32200 | 27800 | 26000 | 24300 | 22500 | 21100 | 19914 | 18702 | 17464 | 16198 | 14904 | 13582 | 12231 | 10850 | 9439 | 7996 | 6522 | 5016 | 3476 | 1903 |
| RRD-02 | 658 | 14229 | 7115 | 4538 | 4469 | 4485 | 4506 | 4524 | 4540 | 4568 | 4596 | 4625 | 4655 | 4685 | 4717 | 4749 | 4782 | 4816 | 4851 | 4887 | 4924 | 4962 | 5001 |
| RRD-03 | 462 | 9991 | 4995 | 3174 | 3105 | 3121 | 3142 | 3161 | 3176 | 3204 | 3232 | 3261 | 3291 | 3322 | 3353 | 3385 | 3418 | 3452 | 3487 | 3523 | 3560 | 3598 | 3637 |
| RRD-04 | 658 | 14229 | 7115 | 5570 | 4886 | 5044 | 5254 | 5439 | 5596 | 5871 | 6154 | 6444 | 6742 | 7048 | 7362 | 7684 | 8016 | 8356 | 8706 | 9064 | 9433 | 9812 | 10200 |
| RRD-05 | 708 | 15311 | 7655 | 4197 | 4128 | 4144 | 4165 | 4183 | 4199 | 4227 | 4255 | 4284 | 4314 | 4344 | 4376 | 4408 | 4441 | 4475 | 4510 | 4546 | 4583 | 4621 | 4660 |
| RRD-07 | 658 | 14229 | 7115 | 4277 | 3935 | 4014 | 4119 | 4211 | 4290 | 4427 | 4569 | 4714 | 4862 | 5015 | 5173 | 5334 | 5500 | 5670 | 5844 | 6024 | 6208 | 6397 | 6592 |
| RRD-08 | 708 | 15311 | 7655 | 4413 | 4071 | 4150 | 4255 | 4347 | 4426 | 4564 | 4705 | 4850 | 4999 | 5152 | 5309 | 5470 | 5636 | 5806 | 5981 | 6160 | 6345 | 6534 | 6728 |
| RRD-09 | 708 | 15311 | 7655 | 6423 | 6938 | 8396 | 8607 | 8791 | 8949 | 9224 | 9506 | 9796 | 10094 | 10400 | 10714 | 11037 | 11368 | 11708 | 12058 | 12417 | 12785 | 13164 | 13553 |
| RRD-10 | 708 | 15311 | 7655 | 3510 | 3167 | 3246 | 3352 | 3444 | 3523 | 3660 | 3801 | 3946 | 4095 | 4248 | 4405 | 4567 | 4732 | 4903 | 5077 | 5257 | 5441 | 5630 | 5825 |
| Sub Total | | | | 36100 | 34700 | 36600 | 37400 | 38100 | 38700 | 39745 | 40818 | 41920 | 43052 | 44214 | 45408 | 46634 | 47893 | 49186 | 50514 | 51878 | 53279 | 54718 | 56195 |
| RRD T1, T2 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 |
| TFMR Requirements | | | | 36100 | 34700 | 36600 | 37400 | 38100 | 38700 | 39745 | 40818 | 41920 | 43052 | 44214 | 45408 | 46634 | 47893 | 49186 | 50514 | 51878 | 53279 | 54718 | 56195 |
| Capacity | | | | 3900 | 5300 | 3400 | 2600 | 1900 | 1300 | 255 | -818 | -1920 | -3052 | -4214 | -5408 | -6634 | -7893 | -9186 | -10514 | -11878 | -13279 | -14718 | -16195 |
| BCV-01 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 5946 | 6024 | 6104 | 6185 | 6267 | 6350 | 6434 | 6519 | 6605 | 6692 | 6780 |
| BCV-02 | 474 | 10250 | 7707 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 |
| BCV-03 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 5946 | 6024 | 6104 | 6185 | 6267 | 6350 | 6434 | 6519 | 6605 | 6692 | 6780 |
| BCV-04 | 474 | 10250 | 6406 | 5165 | 4665 | 4865 | 4615 | 4915 | 5065 | 5214 | 5366 | 5519 | 5674 | 5832 | 5991 | 6153 | 6316 | 6482 | 6650 | 6820 | 6993 | 7167 | 7344 |
| Sub Total | | | | 23200 | 22200 | 22600 | 22100 | 22700 | 23000 | 23299 | 23602 | 23909 | 24220 | 24534 | 24853 | 25176 | 25504 | 25835 | 26171 | 26511 | 26856 | 27205 | 27559 |
| BCV T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 |
| TFMR Requirements | | | | 23200 | 22200 | 22600 | 22100 | 22700 | 23000 | 23299 | 23602 | 23909 | 24220 | 24534 | 24853 | 25176 | 25504 | 25835 | 26171 | 26511 | 26856 | 27205 | 27559 |
| Capacity | | | | 1800 | 2800 | 2400 | 2900 | 2300 | 2000 | 1701 | 1398 | 1091 | 780 | 466 | 147 | -176 | -504 | -835 | -1171 | -1511 | -1856 | -2205 | -2559 |
| PUL-01 | 630 | 13624 | 8515 | 5718 | 5796 | 5912 | 6068 | 6262 | 6418 | 6578 | 6742 | 6908 | 7078 | 7251 | 7427 | 7606 | 7789 | 7976 | 8166 | 8359 | 8556 | 8757 | 8962 |
| PUL-02 | 474 | 10250 | 6406 | 5741 | 5785 | 5852 | 5941 | 6052 | 6141 | 6232 | 6326 | 6421 | 6518 | 6617 | 6717 | 6820 | 6924 | 7031 | 7139 | 7250 | 7363 | 7477 | 7595 |
| PUL-03 | 785 | 16976 | 10610 | 8441 | 8519 | 8636 | 8791 | 8986 | 9141 | 9302 | 9465 | 9632 | 9801 | 9974 | 10150 | 10330 | 10513 | 10699 | 10889 | 11083 | 11280 | 11481 | 11686 |
| Sub Total | | | | 19900 | 20100 | 20400 | 20800 | 21300 | 21700 | 22112 | 22532 | 22961 | 23397 | 23841 | 24294 | 24756 | 25226 | 25706 | 26194 | 26692 | 27199 | 27716 | 28242 |
| PUL T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 |
| TFMR Requirements | | | | 19900 | 20100 | 20400 | 20800 | 21300 | 21700 | 22112 | 22532 | 22961 | 23397 | 23841 | 24294 | 24756 | 25226 | 25706 | 26194 | 26692 | 27199 | 27716 | 28242 |
| Capacity | | | | 5100 | 4900 | 4600 | 4200 | 3700 | 3300 | 2888 | 2468 | 2039 | 1603 | 1159 | 706 | 244 | -226 | -706 | -1194 | -1692 | -2199 | -2716 | -3242 |

VIR Substation Growth

2.20%

RRD Substation Growth

1.70%

BCV Substation Growth

1.30%

PUL Substation Growth

1.9%


**Appendix B
Feeder Capacity Ratings**

| Feeder | | Appendix B - Feeder Capacity Ratings | | | |
|--------|--------------------------|--------------------------------------|----------------------------------|--------------------------------------|--|
| | Cold Load Pick Up Factor | Cold Load Rating of Feeder (A) | Cold Load Rating of Feeder (MVA) | Winter Planning Rating of Feeder (A) | Winter Planning Rating of Feeder (MVA) |
| VIR-01 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-02 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-03 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-04 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-05 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-06 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| VIR-07 | 2.0 | 785 | 16,956 | 393 | 8,489 |
| | | | | | |
| RRD-02 | 2.0 | 658 | 14,213 | 329 | 7,106 |
| RRD-03 | 2.0 | 462 | 9,979 | 231 | 4,990 |
| RRD-04 | 2.0 | 658 | 14,213 | 329 | 7,106 |
| RRD-05 | 2.0 | 708 | 15,293 | 354 | 7,646 |
| RRD-07 | 2.0 | 658 | 14,213 | 329 | 7,106 |
| RRD-08 | 2.0 | 708 | 15,293 | 354 | 7,646 |
| RRD-09 | 2.0 | 708 | 15,293 | 354 | 7,646 |
| RRD-10 | 2.0 | 708 | 15,293 | 354 | 7,646 |
| | | | | | |
| BCV-01 | 1.6 | 474 | 10,238 | 237 | 5,119 |
| BCV-02 | 1.33 | 474 | 10,238 | 237 | 5,119 |
| BCV-03 | 1.6 | 474 | 10,238 | 237 | 5,119 |
| BCV-04 | 1.6 | 474 | 10,238 | 237 | 5,119 |
| | | | | | |
| PUL-01 | 1.6 | 630 | 13,608 | 393 | 8,489 |
| PUL-02 | 1.6 | 474 | 10,238 | 237 | 5,119 |

Appendix C

Substation and Feeder Drawing

Feeder & Substations
Impacting St. John's East End Planning Study



Appendix D

**Alternative #1
Substation and Feeder Load Forecast**

APPENDIX D - Estimated Load Forecast (BASE) - Alternative #1

| Feeders | CLPU Emerg | CLPU kVA | Planning | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 |
|-------------------|---------------|-------------|----------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| VIR-01 | 785 | 16976 | 8488 | 5462 | 6124 | 6394 | 6650 | 6920 | 7131 | 7312 | 7498 | 7688 | 6373 | 6562 | 6755 | 6952 | 7154 | 7360 | 7570 | 7785 | 8005 | 8230 | 8460 |
| VIR-02 | 785 | 16976 | 8488 | 5854 | 4216 | 5786 | 6042 | 6312 | 6523 | 6704 | 6890 | 7080 | 6265 | 6454 | 6647 | 6844 | 7046 | 7252 | 7462 | 7677 | 7897 | 8122 | 8352 |
| VIR-03 | 785 | 16976 | 8488 | 5948 | 6610 | 6880 | 7136 | 7406 | 7617 | 7798 | 7984 | 8174 | 6359 | 6548 | 6741 | 6938 | 7140 | 7346 | 7556 | 7771 | 7991 | 8216 | 8446 |
| VIR-04 | 785 | 16976 | 8488 | 5199 | 5645 | 5828 | 6000 | 6183 | 6325 | 6447 | 6572 | 6700 | 6825 | 6952 | 7082 | 7215 | 7351 | 7490 | 7632 | 7777 | 7926 | 8077 | 8232 |
| VIR-05 | 785 | 16976 | 8488 | 5450 | 5896 | 6079 | 6251 | 6434 | 6576 | 6698 | 6823 | 6951 | 7076 | 7203 | 7333 | 7466 | 7602 | 7741 | 7883 | 8028 | 8177 | 8328 | 8483 |
| VIR-06 | 785 | 16976 | 8488 | 9154 | 4746 | 5193 | 5615 | 6062 | 6410 | 6709 | 7016 | 7329 | 5134 | 5346 | 5665 | 5990 | 6323 | 6664 | 7011 | 7367 | 7730 | 8101 | 8480 |
| VIR-07 | 785 | 16976 | 8488 | 5734 | 5949 | 6037 | 6121 | 6209 | 6277 | 6336 | 6397 | 6459 | 7519 | 7581 | 7644 | 7708 | 7773 | 7840 | 7909 | 7979 | 8051 | 8124 | 8199 |
| VIR-08 | 785 | 16976 | 8488 | | 7715 | 7803 | 7887 | 7975 | 8043 | 8102 | 8136 | 8225 | 7285 | 7347 | 7410 | 7474 | 7539 | 7606 | 7675 | 7745 | 7817 | 7890 | 7965 |
| VIR-09 | 785 | 16976 | 8488 | | | | | | | | | | 7060 | 7222 | 7285 | 7349 | 7414 | 7481 | 7550 | 7620 | 7692 | 7765 | 7840 |
| Sub Total | | | | 42801 | 46901 | 50000 | 51702 | 53501 | 54902 | 56106 | 57316 | 58606 | 59895 | 61213 | 62560 | 63936 | 65343 | 66780 | 68249 | 69751 | 71285 | 72854 | 74456 |
| VIR T1, T2, T3 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 |
| TFMR Requirements | | | | 42801 | 46901 | 50000 | 51702 | 53501 | 54902 | 56106 | 57316 | 58606 | 59895 | 61213 | 62560 | 63936 | 65343 | 66780 | 68249 | 69751 | 71285 | 72854 | 74456 |
| Capacity | | | | 32199 | 28099 | 25000 | 23298 | 21499 | 20098 | 18894 | 17684 | 16394 | 15105 | 13787 | 12440 | 11064 | 9657 | 8220 | 6751 | 5249 | 3715 | 2146 | 544 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| RRD-02 | 658 | 14229 | 7115 | 4538 | 4469 | 4485 | 4506 | 4524 | 4540 | 4557 | 4574 | 4592 | 4609 | 4627 | 4646 | 4664 | 4683 | 4703 | 4722 | 4742 | 4763 | 4783 | 4804 |
| RRD-03 | 462 | 9991 | 4995 | 3174 | 3105 | 3121 | 3142 | 3161 | 3176 | 3193 | 3210 | 3228 | 4246 | 4264 | 4282 | 4301 | 4320 | 4339 | 4359 | 4379 | 4399 | 4419 | 4440 |
| RRD-04 | 658 | 14229 | 7115 | 5070 | 4386 | 4544 | 4754 | 4939 | 5096 | 5265 | 5437 | 5611 | 4789 | 4969 | 5152 | 5339 | 5529 | 5722 | 5918 | 6118 | 6321 | 6527 | 6737 |
| RRD-05 | 708 | 15311 | 7655 | 4697 | 4628 | 4644 | 4665 | 4683 | 4699 | 4716 | 4733 | 4751 | 4768 | 4786 | 4805 | 4823 | 4842 | 4862 | 4881 | 4901 | 4922 | 4942 | 4963 |
| RRD-07 | 658 | 14229 | 7115 | 4277 | 5435 | 5514 | 5619 | 5711 | 5790 | 5874 | 5960 | 6047 | 6136 | 6226 | 6318 | 6411 | 6506 | 6603 | 6701 | 6800 | 6902 | 7005 | 7110 |
| RRD-08 | 708 | 15311 | 7655 | 4413 | 4071 | 4150 | 4255 | 4347 | 4426 | 4511 | 4596 | 4684 | 4772 | 4862 | 4954 | 5048 | 5142 | 5239 | 5337 | 5437 | 5538 | 5642 | 5747 |
| RRD-09 | 708 | 15311 | 7655 | 6423 | 5738 | 5896 | 6107 | 6291 | 6449 | 6617 | 6789 | 6963 | 7141 | 7321 | 7505 | 6191 | 6381 | 6574 | 6770 | 6970 | 7173 | 7380 | 7590 |
| RRD-10 | 708 | 15311 | 7655 | 3510 | 3167 | 3246 | 3352 | 3444 | 3523 | 3607 | 3693 | 3780 | 3369 | 3459 | 3551 | 5144 | 5239 | 5335 | 5434 | 5533 | 5635 | 5738 | 5843 |
| Sub Total | | | | 36100 | 35000 | 35600 | 36400 | 37100 | 37700 | 38341 | 38993 | 39656 | 39830 | 40515 | 41213 | 41922 | 42643 | 43376 | 44122 | 44881 | 45652 | 46437 | 47235 |
| RRD T1, T2 (& T3) | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 |
| TFMR Requirements | | | | 36100 | 35000 | 35600 | 36400 | 37100 | 37700 | 38341 | 38993 | 39656 | 39830 | 40515 | 41213 | 41922 | 42643 | 43376 | 44122 | 44881 | 45652 | 46437 | 47235 |
| Capacity | | | | 3900 | 5000 | 4400 | 3600 | 2900 | 2300 | 1659 | 1007 | 344 | 25170 | 24485 | 23787 | 23078 | 22357 | 21624 | 20878 | 20119 | 19348 | 18563 | 17765 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| BCV-01 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 4420 | 4455 | 4490 | 4526 | 4562 | 4599 | 4636 | 4674 | 4712 | 4750 | 4790 |
| BCV-02 | 474 | 10250 | 7707 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 |
| BCV-03 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 4420 | 4455 | 4490 | 4526 | 4562 | 4599 | 4636 | 4674 | 4712 | 4750 | 4790 |
| BCV-04 | 474 | 10250 | 6406 | 5165 | 4665 | 4865 | 4615 | 4915 | 5065 | 5214 | 5366 | 5519 | 4623 | 4692 | 4763 | 4834 | 4907 | 4980 | 5055 | 5130 | 5206 | 5284 | 5362 |
| BCV-05 | 474 | 10250 | 6406 | | | | | | | | | | 4000 | 4070 | 4140 | 4212 | 4284 | 4358 | 4432 | 4507 | 4584 | 4661 | 4739 |
| Sub Total | | | | 23201 | 22201 | 22601 | 22101 | 22701 | 23001 | 23300 | 23602 | 23909 | 24116 | 24325 | 24537 | 24752 | 24969 | 25190 | 25413 | 25639 | 25868 | 26099 | 26334 |
| BCV T1 (& T2) | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 23201 | 22201 | 22601 | 22101 | 22701 | 23001 | 23300 | 23602 | 23909 | 24116 | 24325 | 24537 | 24752 | 24969 | 25190 | 25413 | 25639 | 25868 | 26099 | 26334 |
| Capacity | | | | 1799 | 2799 | 2399 | 2899 | 2299 | 1999 | 1700 | 1398 | 1091 | 884 | 675 | 463 | 248 | 31 | 24810 | 24587 | 24361 | 24132 | 23901 | 23666 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| PUL-01 | 630 | 13624 | 8515 | 5718 | 6296 | 6412 | 6568 | 6762 | 6918 | 7089 | 7264 | 8442 | 6573 | 6705 | 6841 | 6979 | 7119 | 7263 | 7409 | 7557 | 7709 | 7864 | 8021 |
| PUL-02 | 474 | 10250 | 6406 | 5741 | 6285 | 6352 | 6441 | 6552 | 6641 | 6739 | 6838 | 5940 | 5015 | 5091 | 5168 | 5247 | 5327 | 5409 | 5492 | 5577 | 5664 | 5752 | 5842 |
| PUL-03 | 785 | 16976 | 10610 | 8441 | 9019 | 9136 | 9291 | 9486 | 9641 | 9813 | 9987 | 10165 | 7796 | 7928 | 8064 | 8202 | 8342 | 8486 | 8632 | 8780 | 8932 | 9087 | 9244 |
| PUL-04 | 785 | 16976 | 10610 | | | | | | | | | | 5631 | 5763 | 5899 | 6037 | 6177 | 6321 | 6467 | 6615 | 6767 | 6922 | 7079 |
| Sub Total | | | | 19900 | 21600 | 21900 | 22300 | 22800 | 23200 | 23641 | 24089 | 24547 | 25013 | 25488 | 25972 | 26464 | 26966 | 27478 | 28000 | 28531 | 29072 | 29624 | 30186 |
| PUL T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 19900 | 21600 | 21900 | 22300 | 22800 | 23200 | 23641 | 24089 | 24547 | 25013 | 25488 | 25972 | 26464 | 26966 | 27478 | 28000 | 28531 | 29072 | 29624 | 30186 |
| Capacity | | | | 5100 | 3400 | 3100 | 2700 | 2200 | 1800 | 1359 | 911 | 453 | -13 | 24512 | 24028 | 23536 | 23034 | 22522 | 22000 | 21469 | 20928 | 20376 | 19814 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |

VIR Substation Growth

2.20%

RRD Substation Growth

1.70%

BCV Substation Growth

1.30%

PUL Substation Growth

1.9%

Appendix E

**Alternative #2
Substation and Feeder Load Forecast**

APPENDIX E - Estimated Load Forecast (Medium) - Alternative #2

| Feeders | CLPU Emerg | CLPU kVA | Planning | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 |
|-------------------|------------|----------|----------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| VIR-01 | 785 | 16976 | 8488 | 5462 | 6157 | 6442 | 6711 | 6995 | 7217 | 7387 | 7560 | 7738 | 7872 | 6929 | 7079 | 7233 | 7390 | 7551 | 7715 | 7882 | 8054 | 8229 | 8408 |
| VIR-02 | 785 | 16976 | 8488 | 5854 | 6549 | 6834 | 7103 | 7387 | 7608 | 7779 | 7952 | 8130 | 8274 | 6921 | 7071 | 7225 | 7382 | 7543 | 7707 | 7874 | 8046 | 8221 | 8400 |
| VIR-03 | 785 | 16976 | 8488 | 5948 | 6643 | 6928 | 7197 | 7481 | 7703 | 7873 | 8046 | 8224 | 8368 | 6915 | 7065 | 7219 | 7376 | 7537 | 7701 | 7868 | 8040 | 8215 | 8394 |
| VIR-04 | 785 | 16976 | 8488 | 5199 | 5668 | 5860 | 6041 | 6233 | 6383 | 6497 | 6614 | 6734 | 7031 | 7130 | 7232 | 7335 | 7441 | 7550 | 7660 | 7773 | 7889 | 8007 | 8128 |
| VIR-05 | 785 | 16976 | 8488 | 5450 | 5919 | 6111 | 6292 | 6484 | 6633 | 6748 | 6865 | 6985 | 7282 | 7381 | 7483 | 7586 | 7692 | 7801 | 7911 | 8024 | 8140 | 8258 | 8379 |
| VIR-06 | 785 | 16976 | 8488 | 9154 | 5302 | 5772 | 6216 | 6686 | 7051 | 7332 | 7619 | 7912 | 5750 | 5993 | 6241 | 6495 | 6754 | 7019 | 7290 | 7567 | 7850 | 8139 | 8434 |
| VIR-07 | 785 | 16976 | 8488 | 5734 | 5960 | 6053 | 6140 | 6233 | 6305 | 6361 | 6417 | 6475 | 7222 | 7270 | 7319 | 7369 | 7420 | 7472 | 7526 | 7580 | 7636 | 7693 | 7751 |
| VIR-08 | 785 | 16976 | 8488 | | | | | | | | | | 5738 | 5981 | 6229 | 6483 | 6742 | 7007 | 7278 | 7555 | 7838 | 8127 | 8422 |
| VIR-09 | 785 | 16976 | 8488 | | | | | | | | | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Sub Total | | | | 42801 | 42198 | 44000 | 45700 | 47499 | 48900 | 49977 | 51073 | 52198 | 53346 | 54520 | 55719 | 56945 | 58198 | 59478 | 60787 | 62124 | 63491 | 64888 | 66315 |
| VIR T1, T2, T3 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 |
| TFMR Requirements | | | | 42801 | 42198 | 44000 | 45700 | 47499 | 48900 | 49977 | 51073 | 52198 | 53346 | 54520 | 55719 | 56945 | 58198 | 59478 | 60787 | 62124 | 63491 | 64888 | 66315 |
| Capacity | | | | 32199 | 32802 | 31000 | 29300 | 27501 | 26100 | 25023 | 23927 | 22802 | 21654 | 20480 | 19281 | 18055 | 16802 | 15522 | 14213 | 12876 | 11509 | 10112 | 8685 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| RRD-02 | 658 | 14229 | 7115 | 4538 | 4484 | 4496 | 4513 | 4528 | 4540 | 4555 | 4570 | 4586 | 4601 | 4617 | 4634 | 4650 | 4667 | 4684 | 4702 | 4719 | 4737 | 4756 | 4774 |
| RRD-03 | 462 | 9991 | 4995 | 3174 | 4120 | 4132 | 4149 | 4164 | 4176 | 4191 | 4206 | 4222 | 4237 | 4253 | 4270 | 4286 | 4303 | 4320 | 4338 | 4355 | 4373 | 4392 | 4410 |
| RRD-04 | 658 | 14229 | 7115 | 5570 | 4028 | 4153 | 4320 | 4466 | 4591 | 4740 | 4893 | 5047 | 5205 | 5365 | 5528 | 5693 | 5861 | 6033 | 6207 | 6384 | 6564 | 6747 | 6933 |
| RRD-05 | 708 | 15311 | 7655 | 4197 | 4143 | 4155 | 4172 | 4187 | 4199 | 4214 | 4229 | 4245 | 4260 | 4276 | 4293 | 4309 | 4326 | 4343 | 4361 | 4378 | 4396 | 4415 | 4433 |
| RRD-07 | 658 | 14229 | 7115 | 4277 | 4006 | 4069 | 4152 | 4225 | 4287 | 4362 | 4438 | 4516 | 4594 | 4674 | 4756 | 4839 | 4923 | 5008 | 5095 | 5184 | 5274 | 5366 | 5459 |
| RRD-08 | 708 | 15311 | 7655 | 4413 | 4142 | 4205 | 4288 | 4361 | 4423 | 4498 | 4574 | 4652 | 4730 | 4810 | 4892 | 4975 | 5059 | 5144 | 5231 | 5320 | 5410 | 5502 | 5595 |
| RRD-09 | 708 | 15311 | 7655 | 6423 | 4331 | 5756 | 5923 | 6069 | 5194 | 5343 | 5496 | 5650 | 5808 | 5968 | 6131 | 6296 | 6464 | 6636 | 6810 | 6987 | 7167 | 7350 | 7536 |
| RRD-10 | 708 | 15311 | 7655 | 3510 | 4489 | 4552 | 4635 | 4708 | 5770 | 5845 | 5921 | 5999 | 6077 | 6157 | 6239 | 6322 | 6406 | 6491 | 6578 | 6667 | 6757 | 6849 | 6942 |
| RRD-11 | 708 | 15311 | 7655 | 0 | 4500 | 4625 | 4792 | 4938 | 5063 | 5212 | 5364 | 5519 | 5676 | 5836 | 5999 | 6165 | 6333 | 6504 | 6678 | 6856 | 7036 | 7219 | 7405 |
| Sub Total | | | | 36102 | 38244 | 40144 | 40944 | 41644 | 42244 | 42962 | 43692 | 44435 | 45190 | 45959 | 46740 | 47534 | 48343 | 49164 | 50000 | 50850 | 51715 | 52594 | 53488 |
| RRD T1, T2 (&T3) | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 40000 | 40000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 |
| TFMR Requirements | | | | 36102 | 38244 | 40144 | 40944 | 41644 | 42244 | 42962 | 43692 | 44435 | 45190 | 45959 | 46740 | 47534 | 48343 | 49164 | 50000 | 50850 | 51715 | 52594 | 53488 |
| Capacity | | | | 3898 | 1756 | 24856 | 24056 | 23356 | 22756 | 22038 | 21308 | 20565 | 19810 | 19041 | 18260 | 17466 | 16657 | 15836 | 15000 | 14150 | 13285 | 12406 | 11512 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| BCV-01 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 5946 | 6024 | 6104 | 6185 | 6267 | 6348 | 6429 | 6510 | 6591 | 6672 | 6753 |
| BCV-02 | 474 | 10250 | 7707 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 |
| BCV-03 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5716 | 5791 | 5868 | 5946 | 6024 | 6104 | 6185 | 6267 | 6348 | 6429 | 6510 | 6591 | 6672 | 6753 |
| BCV-04 | 474 | 10250 | 6406 | 5165 | 4665 | 4865 | 4615 | 4915 | 5065 | 5214 | 5366 | 5519 | 5674 | 5832 | 5991 | 6153 | 6316 | 6479 | 6642 | 6805 | 6968 | 7131 | 7294 |
| BCV-05 | 474 | 10250 | 6406 | | | | | | | | | | | | | | | 5111 | 5227 | 5345 | 5464 | 5585 | 5707 |
| Sub Total | | | | 23201 | 22201 | 22601 | 22101 | 22701 | 23001 | 23300 | 23602 | 23909 | 24220 | 24534 | 25853 | 25177 | 25504 | 26836 | 27184 | 27538 | 27896 | 28258 | 28626 |
| BCV T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 23201 | 22201 | 22601 | 22101 | 22701 | 23001 | 23300 | 23602 | 23909 | 24220 | 24534 | 25853 | 25177 | 25504 | 26836 | 27184 | 27538 | 27896 | 28258 | 28626 |
| Capacity | | | | 1799 | 2799 | 2399 | 2899 | 2299 | 1999 | 1700 | 1398 | 1091 | 780 | 466 | 24147 | 24823 | 24496 | 23164 | 22816 | 22462 | 22104 | 21742 | 21374 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| PUL-01 | 630 | 13624 | 8515 | 5718 | 6796 | 6912 | 7068 | 7262 | 7418 | 7593 | 7771 | 7902 | 8035 | 8171 | 8310 | 8451 | 8595 | 8741 | 8891 | 9043 | 9198 | 9356 | 9517 |
| PUL-02 | 474 | 10250 | 6406 | 5741 | 5785 | 5852 | 5941 | 6052 | 6141 | 6241 | 6343 | 6418 | 6494 | 6572 | 6651 | 6732 | 6814 | 6897 | 6981 | 7065 | 7150 | 7236 | 7323 |
| PUL-03 | 785 | 16976 | 10610 | 8441 | 9519 | 9636 | 9791 | 9986 | 10141 | 10371 | 10495 | 8126 | 8259 | 8395 | 8534 | 8675 | 8819 | 8965 | 9115 | 9267 | 9422 | 9580 | 9741 |
| PUL-04 | 785 | 16976 | 10610 | | | | | | | | | 6131 | 6264 | 6400 | 6539 | 6680 | 6824 | 6970 | 7120 | 7272 | 7427 | 7585 | 7746 |
| Sub Total | | | | 19900 | 22100 | 22400 | 22800 | 23300 | 23700 | 24205 | 24609 | 25077 | 25553 | 26039 | 26533 | 27037 | 27551 | 28075 | 28608 | 29152 | 29705 | 30270 | 30845 |
| PUL T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 19900 | 22100 | 22400 | 22800 | 23300 | 23700 | 24205 | 24609 | 25077 | 25553 | 26039 | 26533 | 27037 | 27551 | 28075 | 28608 | 29152 | 29705 | 30270 | 30845 |
| Capacity | | | | 5100 | 2900 | 2600 | 2200 | 1700 | 1300 | 795 | 391 | 24923 | 24447 | 23961 | 23467 | 22963 | 22449 | 21925 | 21392 | 20848 | 20295 | 19730 | 19155 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |

VIR Substation Growth

2.20%

RRD Substation Growth

1.70%

BCV Substation Growth

1.30%

PUL Substation Growth = 1.9%

Appendix F

**Alternative #3
Substation and Feeder Load Forecast**

APPENDIX F - Estimated Load Forecast (BASE) - Alternative #3

| Feeders | CLPU Emerg | CLPU kVA | Planning | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | 2018 | 2019 | 2020 | 2021 | 2022 | 2023 |
|-------------------|------------|----------|----------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| VIR-01 | 785 | 16976 | 8488 | 6462 | 6157 | 6442 | 6711 | 6895 | 7217 | 7392 | 7571 | 6295 | 6473 | 6655 | 6841 | 7030 | 7224 | 7423 | 7625 | 7832 | 8044 | 8260 | 7471 |
| VIR-02 | 785 | 16976 | 8488 | 5854 | 6049 | 6334 | 6603 | 6887 | 7108 | 7284 | 7463 | 6312 | 6490 | 6672 | 6858 | 7047 | 7241 | 7440 | 7642 | 7849 | 8061 | 8277 | 7488 |
| VIR-03 | 785 | 16976 | 8488 | 5948 | 6643 | 6928 | 7197 | 7481 | 7703 | 7878 | 8057 | 6731 | 6909 | 7091 | 7277 | 7466 | 7660 | 7859 | 8016 | 8268 | 8480 | 8696 | 7907 |
| VIR-04 | 785 | 16976 | 8488 | 5199 | 5668 | 5860 | 6041 | 6233 | 6383 | 6501 | 6622 | 6989 | 7109 | 7232 | 7357 | 7485 | 7616 | 7750 | 7886 | 8026 | 8169 | 8315 | 7457 |
| VIR-05 | 785 | 16976 | 8488 | 5450 | 7419 | 7611 | 7792 | 7984 | 8133 | 8252 | 8372 | 7014 | 7134 | 7257 | 7382 | 7510 | 7641 | 7775 | 7911 | 8051 | 8194 | 8340 | 7482 |
| VIR-06 | 785 | 16976 | 8488 | 9154 | 5802 | 6272 | 6716 | 7186 | 7551 | 7841 | 8137 | 4875 | 5168 | 5469 | 5775 | 6089 | 6409 | 6736 | 7071 | 7412 | 7762 | 8119 | 7967 |
| VIR-07 | 785 | 16976 | 8488 | 5734 | 5960 | 6053 | 6140 | 6233 | 6305 | 6362 | 6421 | 7778 | 7836 | 7895 | 7955 | 8017 | 8080 | 8145 | 8211 | 8278 | 8347 | 8417 | 7986 |
| VIR-08 | 785 | 16976 | 8488 | | | | | | | | | 7807 | 7865 | 7866 | 7926 | 7988 | 8051 | 8116 | 8182 | 8249 | 8318 | 8388 | 7957 |
| VIR-09 | 785 | 16976 | 8488 | | | | | | | | | | | | | | | | | | | | 6569 |
| Sub Total | | | | 43801 | 43698 | 45500 | 47200 | 48999 | 50400 | 51510 | 52643 | 53801 | 54984 | 56137 | 57371 | 58632 | 59922 | 61244 | 62544 | 63965 | 65375 | 66812 | 68282 |
| VIR T1, T2, T3 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 | 75000 |
| TFMR Requirements | | | | 43801 | 43698 | 45500 | 47200 | 48999 | 50400 | 51510 | 52643 | 53801 | 54984 | 56137 | 57371 | 58632 | 59922 | 61244 | 62544 | 63965 | 65375 | 66812 | 68282 |
| Capacity | | | | 31199 | 31302 | 29500 | 27800 | 26001 | 24600 | 23490 | 22357 | 21199 | 20016 | 18863 | 17629 | 16368 | 15078 | 13756 | 12456 | 11035 | 9625 | 8188 | 6718 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| RRD-02 | 658 | 14229 | 7115 | 4538 | 4469 | 4485 | 4506 | 4524 | 4540 | 4557 | 4574 | 4591 | 4608 | 4626 | 4644 | 4662 | 4681 | 4698 | 4715 | 4732 | 4750 | 4767 | 4786 |
| RRD-03 | 462 | 9991 | 4995 | 3174 | 6105 | 3121 | 3142 | 3161 | 3179 | 3193 | 3210 | 3227 | 3244 | 3262 | 3280 | 3298 | 3317 | 3334 | 3351 | 3368 | 3386 | 3403 | 3422 |
| RRD-04 | 658 | 14229 | 7115 | 5570 | 4886 | 5044 | 5254 | 5439 | 5596 | 5762 | 5930 | 6101 | 6275 | 6452 | 6632 | 6815 | 7001 | 5168 | 5338 | 5511 | 5687 | 5866 | 6048 |
| RRD-05 | 708 | 15311 | 7655 | 4197 | 4128 | 4144 | 4165 | 4183 | 4199 | 4216 | 4233 | 4250 | 4267 | 4285 | 4303 | 4321 | 4340 | 4357 | 4374 | 4391 | 4409 | 4426 | 4445 |
| RRD-07 | 658 | 14229 | 7115 | 4277 | 3935 | 4014 | 4119 | 4211 | 4290 | 4373 | 4457 | 4543 | 4629 | 4718 | 4808 | 4899 | 4992 | 5076 | 5161 | 5247 | 5335 | 5424 | 5515 |
| RRD-08 | 708 | 15311 | 7655 | 4413 | 4071 | 4150 | 4255 | 4347 | 4426 | 4509 | 4593 | 4679 | 4765 | 4854 | 4844 | 5035 | 5128 | 5212 | 5297 | 5383 | 5471 | 5560 | 5651 |
| RRD-09 | 708 | 15311 | 7655 | 6423 | 5188 | 6646 | 6857 | 7041 | 7199 | 7364 | 7532 | 6703 | 6877 | 7054 | 7234 | 7417 | 7603 | 5270 | 5440 | 5613 | 5789 | 5968 | 6150 |
| RRD-10 | 708 | 15311 | 7655 | 3510 | 3167 | 3246 | 3352 | 3444 | 3523 | 3605 | 3689 | 4775 | 4861 | 4950 | 5040 | 5131 | 5224 | 5308 | 5393 | 5479 | 5567 | 5656 | 5747 |
| RRD-11 | 708 | 15311 | 7655 | | | | | | | | | | | | | | | 4584 | 4669 | 4755 | 4843 | 4932 | 5023 |
| Sub Total | | | | 36102 | 35949 | 34850 | 35650 | 36350 | 36952 | 37579 | 38218 | 38869 | 39526 | 40201 | 40785 | 41578 | 42286 | 43005 | 43736 | 44479 | 45236 | 46005 | 46787 |
| RRD T1, T2 (&T3) | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 40000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 | 65000 |
| TFMR Requirements | | | | 36102 | 35949 | 34850 | 35650 | 36350 | 36952 | 37579 | 38218 | 38869 | 39526 | 40201 | 40785 | 41578 | 42286 | 43005 | 43736 | 44479 | 45236 | 46005 | 46787 |
| Capacity | | | | 3898 | 4051 | 5150 | 4350 | 3650 | 3048 | 2421 | 1782 | 1131 | 474 | 24799 | 24215 | 23422 | 22714 | 21995 | 21264 | 20521 | 19764 | 18995 | 18213 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| BCV-01 | 474 | 10250 | 6406 | 5691 | 5691 | 5791 | 5666 | 5816 | 5891 | 5968 | 6046 | 6125 | 6206 | 6287 | 4842 | 4898 | 4954 | 5011 | 5069 | 5127 | 5187 | 5247 | 5308 |
| BCV-02 | 474 | 10250 | 7707 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 | 6654 |
| BCV-03 | 474 | 10250 | 6406 | 5691 | 5441 | 5541 | 5416 | 5566 | 5641 | 5718 | 5796 | 5875 | 5956 | 6037 | 5092 | 5148 | 5204 | 5261 | 5319 | 5377 | 5437 | 5497 | 5558 |
| BCV-04 | 474 | 10250 | 6406 | 5165 | 5165 | 5365 | 5115 | 5415 | 5565 | 5719 | 5875 | 6034 | 6194 | 6357 | 4967 | 5078 | 5191 | 5305 | 5421 | 5538 | 5656 | 5776 | 5898 |
| BCV-05 | 474 | 10250 | 6406 | | | | | | | | | | | | 4110 | 4221 | 4334 | 4448 | 4564 | 4681 | 4799 | 4919 | 5041 |
| Sub Total | | | | 23201 | 22951 | 23351 | 22851 | 23451 | 23751 | 24059 | 24371 | 24688 | 25010 | 25335 | 25665 | 25998 | 26336 | 26679 | 27026 | 27377 | 27733 | 28093 | 28459 |
| BCV T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 23201 | 22951 | 23351 | 22851 | 23451 | 23751 | 24059 | 24371 | 24688 | 25010 | 25335 | 25665 | 25998 | 26336 | 26679 | 27026 | 27377 | 27733 | 28093 | 28459 |
| Capacity | | | | 1799 | 2049 | 1649 | 2149 | 1549 | 1249 | 941 | 629 | 312 | 24990 | 24665 | 24335 | 24002 | 23664 | 23321 | 22974 | 22623 | 22267 | 21907 | 21541 |
| | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | |
| PUL-01 | 630 | 13624 | 8515 | 5718 | 5274 | 5358 | 5470 | 5610 | 5722 | 5861 | 6003 | 6147 | 6294 | 6444 | 6597 | 6753 | 6912 | 7073 | 7238 | 7406 | 7577 | 7751 | 7929 |
| PUL-02 | 474 | 10250 | 6406 | 5741 | 4273 | 4321 | 4385 | 4465 | 4529 | 4608 | 4689 | 4772 | 4856 | 4942 | 5029 | 5118 | 5209 | 5301 | 5395 | 5491 | 5589 | 5689 | 5790 |
| PUL-03 | 785 | 16976 | 10610 | 8441 | 7497 | 7581 | 7693 | 7833 | 7945 | 8084 | 8226 | 8370 | 8517 | 8667 | 8820 | 8976 | 9135 | 9296 | 9461 | 9629 | 9800 | 9974 | 10152 |
| PUL-04 | 786 | 16997 | 10623 | | 7500 | 7584 | 7696 | 7836 | 7948 | 8087 | 8229 | 8373 | 8520 | 8670 | 8823 | 8979 | 9138 | 9299 | 9464 | 9632 | 9803 | 9977 | 10155 |
| Sub Total | | | | 19900 | 24544 | 24844 | 25244 | 25744 | 26144 | 26641 | 27147 | 27663 | 28188 | 28724 | 29270 | 29826 | 30392 | 30970 | 31558 | 32158 | 32769 | 33392 | 34026 |
| PUL T1 | | | | | | | | | | | | | | | | | | | | | | | |
| Available | | | | 25000 | 25000 | 25000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 | 50000 |
| TFMR Requirements | | | | 19900 | 24544 | 24844 | 25244 | 26144 | 26641 | 27147 | 27663 | 28188 | 28724 | 29270 | 29826 | 30392 | 30970 | 31558 | 32158 | 32769 | 33392 | 34026 | |
| Capacity | | | | 5100 | 456 | 156 | 24756 | 24256 | 23856 | 23359 | 22853 | 22337 | 21812 | 21276 | 20730 | 20174 | 19608 | 19030 | 18442 | 17842 | 17231 | 16608 | 15974 |
| | | | | | | | | | | | | | | | | | | | | | | | |

VIR Substation Growth 2.20% RRD Substation Growth 1.70% BCV Substation Growth 1.30% PUL Substation Growth = 1.9%

Project Title: Tools and Equipment
Location: Company Offices, Service Buildings and Vehicles
Classification: General Property
Project Cost: \$691,000

This project consists of a number of items as noted.

(a) Regional Tools and Equipment

Cost: \$290,000

Description: Replacement of tools and equipment utilized by line and support staff in the day-to-day operations of the Company.

Operating Experience: Line tools and equipment include those used by line staff, electrical maintenance staff, and engineering and field technical staff. These tools are maintained on a regular basis, however, over time they degrade and wear out, especially hot line equipment which must meet rigorous safety requirements. Concerns have also been expressed by linepersons related to the difficulty of using certain types of cutting & compression hand tools. Where feasible, such tools will be replaced with battery and hydraulic alternatives to improve productivity and working conditions.

Justification: Proper tools and equipment are required for the efficient and effective management of the electrical system as well as the safety of line workers and the public.

(b) Head Office Tools and Equipment

Cost: \$341,000

Description: This project includes engineering test equipment, tools used by electrical and mechanical maintenance personnel and tools used for the handling and shipping of printed material including customer bills.

Engineering test equipment includes items to perform systems calibration, commissioning and testing of protection equipment and data communications testing and analysis. The 2005 equipment requirements involve the purchase of one Relay Test Set.

Equipment for the electrical maintenance personnel is required for staff involved in the maintenance of substation equipment and generation. The following are the items required for 2005:

- 1 – Transformer Turns Ratio Tester
- 1 – 10 A Ductor (c/w long leads)
- 2 – 5 kV Megger
- 2 – Oil Test Set
- 2 – Thermocal
- 1 – Transformer Winding Resistance Meter
- 2 – Air Quality Gas Monitor
- 1 – Battery Ground Fault Locator

Equipment for mechanical maintenance personnel is required for staff involved in generation maintenance. The following are items required for 2005:

- 1 – Process Calibrator
- 1 – Boroscope
- 1 – Laser Shaft Alignment Equipment
- 1 – Generator grounding studs and cables
- 1 – Vibration Detector Calibration Equipment
- 1 – Process Meter
- 1 – Filter Press

Equipment for printed material handling and shipping for 2005 include the following:

- 1 – Punch and Binding Machine
- 1 – Numbering, Perforating and Scoring Unit
- 1 – Shrink Wrap Machine

Operating Experience: Engineering test equipment is used to verify the operation of the protection and remote control systems. The relay test equipment is used to verify a protection system's operation prior to its going into service and to diagnose problems once the protection equipment is in operation.

The electrical maintenance group is responsible for the integrity and reliability of the equipment located in 137 substations across the Company's service territory. The electrical maintenance equipment includes power transformers, breakers, reclosers, voltage regulators, metering tanks, three phase pad mount transformers and step down transformers. Diagnostic testing and repair of the various types of equipment requires specialized tools and test equipment such as circuit breaker motion analyzers, insulation resistance testers (meggers), oil dielectric testers, recloser testers, transformer ratio testers, low resistance ohmmeters (ductors), SF6 gas reclaimers, vacuum pumps, oil filters, hand held gas monitors, potential indicators, fault locators, battery testers, etc. Innovations in

tools and test equipment often lead to better diagnostic tools that result in less equipment failures. As well, normal deterioration and the inability to maintain obsolete test equipment require that some of these items be replaced every year.

The mechanical maintenance group is responsible for the integrity and reliability of a variety of mechanical equipment located in numerous generation facilities located throughout the Company's operating area. Diagnostic testing, calibration and repair of these various types of equipment require numerous types of specialized tools and test equipment. Innovations in tools and test equipment often lead to better diagnostic tools that result in less equipment failures. As well, normal deterioration and an inability to maintain obsolete technology require that some of this equipment be replaced at regular intervals.

Justification: The test equipment noted above are the base tools required to design, verify and maintain reliable operation of the electric power system and associated equipment.

The relay test set is required to design, verify and maintain a reliable protection system that properly isolates power system faults and maintains safety.

The electrical and mechanical maintenance test equipment is required to ensure the integrity and reliability of the equipment located in the Company's substations and generation plants across its service territory.

(c) Furniture

Cost: \$60,000

Description: Replacement of chairs and furniture that have deteriorated.

Operating Experience: The Company has approximately 660 full time employee equivalents. The office furniture utilized by these employees deteriorates through normal use and needs to be replaced.

Justification: Proper furniture is necessary for a safe and productive work environment.

Project Title: Additions to Real Property

Location: Electrical Maintenance Facility, Duffy Place Building, Kenmount Road Building and Corner Brook West Street Building

Classification: General Property

Project Cost: \$325,000

This project consists of 2 items greater than \$50,000 and several items estimated at less than \$50,000 each.

(a) Duffy Place – Renovate Maintenance Center

Cost: \$100,000

Description: Renovate maintenance center to accommodate generation/mechanical maintenance personnel.

Operating Experience: Prior to the retirement of the steam plant facility on the south side of St. John's, the mechanical maintenance staff worked from that location. Subsequent to that they worked from leased space on Topsail Road. A review of the Duffy Place facilities identified that space previously used as a vehicle garage could be renovated and made available to this group.

Justification: This project will provide office space with appropriate climate control and adjustable workstations for this group similar to facilities provided other company personnel engaged in similar activities. It will also provide for organized storage of spare parts and equipment that are critical to the Company's asset management strategy.

(b) Duffy Place – Upgrade UPS (Uninterruptible Power Supply)

Cost: \$80,000

Description: This project involves the addition of a Maintenance Bypass Module (MBM) to the UPS at the Duffy Place Building. The UPS ensures that power to critical operations and equipment is not interrupted in the event of a failure on the regular utility power supply.

Operating Experience: The UPS at the St. John's Regional Office (Duffy Place Building) was originally installed in 1999. It was recently determined that the UPS has no maintenance bypass switch. Without a bypass switch, the UPS cannot be electrically isolated from the building without interrupting the electrical supply to its circuits. This means that, if the unit should fail, all services powered by the UPS, which include the Customer Contact Center, St. John's Area Operations, Disaster Recovery IS Computer Room, SCADA Disaster Recovery Site, and Outage Management would be shut down for an extended period of time.

Justification: This project is justified based on the need to reduce the risk of losing critical services, such as SCADA, the Customer Call Center and St. John's Area Operations, for extended periods of time as a result of failure or malfunction of UPS equipment at the St. John's Regional Office.

(c) Projects < \$50,000.

Cost: \$145,000

Description: Listed are projects estimated at less than \$50,000.

1. Duffy Place – Upgrade Telecommunication & Meter Shops
2. Electrical Maintenance Facility – Storage Ramp Upgrade
3. Corner Brook – Renovate West Street Building
4. Kenmount Road Building – Replace Steps and Doors at Front Entrance
5. Kenmount Road Building – Upgrade Security Systems and Deteriorated Fixtures

Project Title: Purchase Vehicles and Aerial Devices

Location: Various

Classification: Transportation

Project Cost: \$2,642,000

Operating Experience: See Transportation, Appendix 1, Attachment A for details on the vehicles being replaced in 2005.

**Appendix 1
Attachment A**

Details – 2005 Capital Vehicle Budget

| SUMMARY 5YR CAPITAL VEHICLE BUDGET (2005 - 2009) | | | | | | | | | |
|--|---|---------------------------|----------------------------|---|-------------------------|--------------------------|---------------------|-------------------------|-------------------|
| Year | Proposed Yrs to be Replaced Heavy Fleet | # Units/Yr Heavy Fleet | Budget \$\$ Heavy Fleet | Proposed Yrs to be Replaced Passenger Fleet | # Units/Yr Passenger | Budget \$\$ Passenger | # Units Off Road | Budget \$\$ Off Road | Overall Totals |
| 2005 | 1992 | 1 | \$1,004,489 | 1996 | 1 | \$1,339,402 | 8 | \$299,434 | \$2,643,325 |
| | 1993 | 2 | | 1997 | 1 | | | | |
| | 1994 | 3 | | 1998 | 1 | | | | |
| | 1995 | 1 | | 1999 | 43 | | | | |
| | | | | | | | | | |
| 2006 | 1995 | 10 | \$1,959,323 | 2000 | 27 | \$800,991 | 9 | \$227,433 | \$2,987,747 |
| | 1996 | 1 | | | | | | | |
| | | | | | | | | | |
| 2007 | 1996 | 2 | \$897,556 | 2001 | 30 | \$1,448,433 | 8 | \$303,577 | \$2,649,566 |
| | 1997 | 5 | | 2002 | 18 | | | | |
| | | | | | | | | | |
| 2008 | 1997 | 1 | \$1,042,870 | 2002 | 18 | \$1,534,743 | 9 | \$231,685 | \$2,809,299 |
| | 1998 | 4 | | 2003 | 32 | | | | |
| | | | | | | | | | |
| 2009 | 1998 | 1 | \$1,924,721 | 2004 | 14 | \$437,125 | 6 | \$48,823 | \$2,410,669 |
| | 1999 | 1 | | | | | | | |
| | 2000 | 6 | | | | | | | |

DETAILS 2005 CAPITAL VEHICLE BUDGET

Heavy Fleet

| | | | | | | Odom | Last Odom | Maint Hist |
|--------|---------------------|------|-------------------------------|--------------------|--|--------------|-----------|---------------|
| Unit # | Dept Name | Year | Make/Model | Vehicle Type | Aerial Info | Reading Date | Reading | May 03-Apr 04 |
| 033C | WESTERN GANDER | 1992 | INTERNATIONAL C&C | Medium Duty Aerial | Altec AM438H Material Handler | 30-Apr-04 | 310000 | \$8,638.76 |
| 218B | WESTERN GRAND FALLS | 1993 | FREIGHTLINER | Medium Duty Aerial | Altec Am438H Material Handler | 30-Apr-04 | 247000 | \$12,703.17 |
| 091B | WESTERN GANDER | 1993 | INTERNATIONAL C&C | Medium Duty Aerial | Altec AM550H DBL Bucket Material Handler | 30-Apr-04 | 220000 | \$38,145.88 |
| 124C | OPERATIONS | 1994 | FORD F450 4X2 DRW CHASSIS CAB | Other Heavy Equip | Cube Van Body (No Aerial) | 30-Apr-04 | 221000 | \$3,465.83 |
| 327C | WESTERN CLARENVILLE | 1994 | FORD F450 4X2 DRW CHASSIS CAB | Other Heavy Equip | Stake Body (No Aerial) | 30-Apr-04 | 134918 | \$5,712.49 |
| 711A | OPERATIONS | 1994 | GMC | Other Heavy Equip | Cube Van (No Aerial) | 30-Apr-04 | 63000 | \$5,911.35 |
| 031D | WESTERN GRAND FALLS | 1995 | FORD F450 4X2 DRW CHASSIS CAB | Light Duty Aerial | Altec AT2506 Light Duty Aerial Device | 30-Apr-04 | 210000 | \$6,039.68 |
| Totals | 7 | | | | | | | |

Passenger

| | | | | | | Odom | Last Odom | Maint Hist |
|--------|-----------------------------|------|-------------|-------------|------------------|--------------|-----------|---------------|
| Unit # | Dept Name | Year | Make | Model | Vehicle Type | Reading Date | Reading | May 03-Apr 04 |
| 117D | EASTERN ST. JOHN'S | 1996 | FORD TRUCK | RANGER P/UP | LIGHT DUTY TRUCK | 6/3/2004 | 174091 | \$911.56 |
| 714A | MATERIALS MANAGEMENT | 1997 | PONTIAC | TRANSPORT | VAN | 4/2/2004 | 131225 | \$3,099.71 |
| 028D | WESTERN CORNER BROOK | 1998 | TOYOTA | RAV4 | FOUR WHEEL DRIVE | 3/29/2004 | 133230 | \$4,055.58 |
| 185D | EASTERN BURIN | 1999 | DODGE TRUCK | RAM 1500 | LIGHT DUTY TRUCK | 4/13/2004 | 207287 | \$4,031.92 |
| 366D | WESTERN STEPHENVILLE | 1999 | FORD TRUCK | F150 P/UP | LIGHT DUTY TRUCK | 5/3/2004 | 177530 | \$2,843.24 |
| 705B | EASTERN CARBONEAR | 1999 | FORD TRUCK | RANGER P/ | LIGHT DUTY TRUCK | 3/19/2004 | 214530 | \$3,681.19 |
| 367C | WESTERN CLARENVILLE | 1999 | DODGE TRUCK | RAM 1500 | LIGHT DUTY TRUCK | 3/19/2004 | 227638 | \$4,686.42 |
| 391C | ENGINEERING & ENERGY SUPPLY | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/16/2004 | 59011 | \$1,551.38 |
| 223C | OPERATIONS | 1999 | CHEVROLET | CHEV VAN | VAN | 5/19/2004 | 64548 | \$1,274.75 |
| 287D | OPERATIONS | 1999 | CHEVROLET | CHEV S10 | LIGHT DUTY TRUCK | 2/16/2004 | 72155 | \$3,454.61 |
| 358D | CUSTOMER SERVICE/MR | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 3/18/2004 | 76590 | \$2,834.52 |
| 332D | CUSTOMER SERVICE/MR | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/5/2004 | 85631 | \$6,317.51 |
| 069D | CUSTOMER SERVICE/MR | 1999 | TOYOTA | RAV4 | FOUR WHEEL DRIVE | 6/3/2004 | 98716 | \$1,733.05 |
| 035D | ENGINEERING & ENERGY SUPPLY | 1999 | DODGE TRUCK | DODGE P/U | PICKUP | 6/3/2004 | 94520 | \$3,340.16 |
| 209E | WESTERN GRAND FALLS | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 3/30/2004 | 108621 | \$721.52 |
| 194D | CUSTOMER SERVICE/MR | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 3/30/2004 | 121203 | \$3,823.88 |
| 039C | CUSTOMER SERVICE/MR | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/2/2004 | 123234 | \$2,214.05 |
| 079D | ENGINEERING & ENERGY SUPPLY | 1999 | JEEP | CHEROKEE | FOUR WHEEL DRIVE | 4/30/2004 | 140845 | \$3,066.34 |
| 198E | WESTERN STEPHENVILLE | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 5/25/2004 | 127236 | \$1,140.51 |
| 041E | WESTERN GRAND FALLS | 1999 | FORD TRUC | F150 P/UP | LIGHT DUTY TRUCK | 4/15/2004 | 126652 | \$5,982.02 |
| 341D | WESTERN CLARENVILLE | 1999 | DODGE TRU | RAM 2500 | LIGHT DUTY TRUCK | 3/10/2004 | 135697 | \$4,249.85 |
| 093D | EASTERN ST. JOHN'S | 1999 | JEEP | CHEROKEE | FOUR WHEEL DRIVE | 6/3/2004 | 122205 | \$791.85 |
| 286D | MATERIALS MANAGEMENT | 1999 | FORD TRUC | WINDSTAR | VAN | 4/16/2004 | 137853 | \$1,296.23 |
| 276D | WESTERN GRAND FALLS | 1999 | DODGE TRU | DODGE P/U | PICKUP | 6/3/2004 | 129741 | \$1,688.91 |
| 067E | WESTERN GRAND FALLS | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/16/2004 | 138122 | \$4,004.14 |
| 376C | OPERATIONS | 1999 | DODGE TRUCK | DODGE B35 | VAN | 3/16/2004 | 130042 | \$3,194.71 |
| 141E | WESTERN STEPHENVILLE | 1999 | DODGE | STRATUS | CAR | 4/26/2004 | 141361 | \$1,586.32 |
| 042E | WESTERN CORNER BROOK | 1999 | CHEVROLET | ASTRO C/V | VAN | 5/28/2004 | 139863 | \$3,529.70 |
| 221C | CUSTOMER SERVICE/SAFETY | 1999 | CHEVROLET | ASTRO C/V | VAN | 5/12/2004 | 130708 | \$1,445.43 |
| 164D | WESTERN GANDER | 1999 | FORD TRUC | RANGER P/U | LIGHT DUTY TRUCK | 4/5/2004 | 147653 | \$2,010.44 |
| 313D | WESTERN STEPHENVILLE | 1999 | DODGE TRU | DODGE P/U | PICKUP | 3/10/2004 | 161248 | \$1,413.02 |
| 011D | ENGINEERING & ENERGY SUPPLY | 1999 | CHEVROLET | CHEV S10 | LIGHT DUTY TRUCK | 5/13/2004 | 155171 | \$3,606.86 |
| 165C | EASTERN BURIN | 1999 | DODGE TRU | RAM P/UP | LIGHT DUTY TRUCK | 4/13/2004 | 150840 | \$4,940.44 |
| 244E | CUSTOMER SERVICE/MR | 1999 | TOYOTA | RAV4 | FOUR WHEEL DRIVE | 4/30/2004 | 168144 | \$1,036.60 |
| 148C | ENGINEERING & ENERGY SUPPLY | 1999 | CHEVROLET | ASTRO C/V | VAN | 4/27/2004 | 167871 | \$5,830.70 |
| 349D | EASTERN CARBONEAR | 1999 | FORD TRUC | RANGER P/ | LIGHT DUTY TRUCK | 6/3/2004 | 156811 | \$2,386.14 |
| 015D | TRANSPORTATION & LANDS | 1999 | CHEVROLET | ASTRO C/V | VAN | 4/6/2004 | 155011 | \$6,211.19 |
| 281D | ENGINEERING & ENERGY SUPPLY | 1999 | DODGE TRUCK | DODGE B35 | VAN | 4/8/2004 | 159227 | \$4,483.77 |
| 182D | EASTERN BURIN | 1999 | DODGE TRU | DODGE P/U | LIGHT DUTY TRUCK | 4/15/2004 | 162585 | \$4,196.73 |
| 399C | WESTERN GRAND FALLS | 1999 | TOYOTA | RAV4 | FOUR WHEEL DRIVE | 6/1/2004 | 164921 | \$770.11 |
| 181D | WESTERN GANDER | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/30/2004 | 170909 | \$10,566.54 |
| 335D | WESTERN CLARENVILLE | 1999 | FORD TRUC | F150 P/UP | LIGHT DUTY TRUCK | 5/11/2004 | 171799 | \$5,566.43 |
| 183E | WESTERN CLARENVILLE | 1999 | SUZUKI | VITARA 4X | FOUR WHEEL DRIVE | 4/7/2004 | 174775 | \$2,750.45 |
| 363E | WESTERN GANDER | 1999 | CHEVROLET | CHEV S10 | LIGHT DUTY TRUCK | 4/12/2004 | 172699 | \$6,385.30 |
| 096C | WESTERN CLARENVILLE | 1999 | DODGE TRU | RAM P/UP | LIGHT DUTY TRUCK | 5/25/2004 | 175877 | \$2,479.58 |
| 333D | CUSTOMER SERVICE/MR | 1999 | TOYOTA | RAV4 | FOUR WHEEL DRIVE | 5/4/2004 | 184716 | \$3,345.94 |
| Totals | 46 | | | | | | | |

DETAILS 2005 CAPITAL VEHICLE BUDGET

| Off Road | | | | | |
|----------|-----------|-----------------|------|--|----------|
| Unit # | Dept Code | Dept Name | Year | Unit Type | Comments |
| | | EASTERN/WESTERN | | ATV ATV Snowmobile Snowmobile Reel Trailer Snowmobile Tension Stringer Tension Stringer | |
| Totals | 8 | | | | |

Project Title: **Application Enhancements**

Location: **All Service Areas**

Classification: **Information Systems**

Project Cost: **\$1,087,000**

This project consists of a number of items as noted.

(a) Business Support Systems

Cost: \$115,000

Description: The purpose of this project is to enhance the processes related to the Company's financial, materials management and human resources applications. For 2005, the proposed enhancements include:

1. **Fixed Assets - \$34,000**

Plant information is used to determine the Company's depreciation expenses, provide information for the financial reports and to determine the net book value of assets.

Approximately 40,000 plant records are stored in a Microsoft Access database to which access is limited to a small number of employees in the Finance department. This project will enhance processes related to the capturing, tracking and reporting of the Company's plant records by providing employees outside of the Finance department (such as engineering technicians) with access to plant information. This is regularly needed to determine the original cost of plant, installation dates, and age of plant assets.

2. **Bank Reconciliation - \$44,000**

Today each area office keys bank deposits into a Microsoft Access database. Every month this information is compiled and re-keyed into the Company's financial system, Great Plains. Benefits of this project include:

- The elimination of re-keying as area offices will key bank deposits directly into Great Plains on a daily basis.
- The automatic matching of deposits and cheques by date and amount, reducing the time Finance employees have to spend reconciling these items (including the reliance on specific individuals).

- The creation of standard reports including cheque book list, cheque book register report, and bank distribution history within Great Plains.
- 3. **Contract Management System – \$37,000**
This project involves enhancing the current contract management system. Benefits of this project include:
 - The ability to view current and previous performance issues with a contractor which may affect the decision to award a contract to them.
 - The ability to foresee potential contractor capacity challenges by knowing the number of other contracts already awarded to the same contractor.
 - The ability to view the status of insurances and Workplace Health and Safety forms to ensure the appropriate documentation is in place.
 - The automatic generation of a Contractor Standing Agreement with a contract number assigned would eliminate the need for the Purchasing group to re-key data into the system.
 - The ability of staff outside the Purchasing group to view Contractor Standing Agreements.

(b) Intranet/Internet Enhancements

Cost: \$101,000

Description: The purpose of this item is to enhance the Company's internal web site (Intranet) used by employees, as well as the Company's Internet website used by the Company's customers and other interested parties. For 2005, the proposed enhancements include:

1. **Changes to the Intranet - \$50,000**
Make improvements to the Company's Intranet to increase the availability of information by providing quicker access to data, applications and reports that employees need to respond to customer inquiries and perform other work responsibilities. Benefits include:
 - Improved access to information making it easier to retrieve, enabling faster response to customer queries.
 - Improved access and management of documentation to reduce the need to prepare, consolidate, and distribute information to various stakeholders. The information is

available from a single location when needed. For example, Company targets can be posted on the Intranet for viewing by all employees instead of emailing the information to each employee. This ensures employees are always using the most current information.

- Improved communication and collaboration through the sharing of information.
- A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

2. **Changes to the Company's Internet site - \$51,000**

Make enhancements to customer self-service options on the Company's Internet site. Benefits include:

- Providing customers with the ability to view their electric bill for the previous 12 months.
- More efficient responses to customer requests by ensuring the most appropriate staff respond to the internet query based on the category selected by the customer.

(c) Operations and Engineering Enhancements

Cost: \$368,000

Description: The purpose of this item is to implement improvements in the Company's operations and engineering applications in the areas of asset management, work order management and SCADA. The following are the individual initiatives within this item:

1. **Line Inspections - \$83,000**

This project involves improvements to the current line inspection systems. Currently, inspection findings are recorded on paper forms in the field and the deficiencies are later entered into the system. With the current system there is no efficient method to track, schedule or follow-up on these deficiencies. An improved system will provide the following benefits:

- Make the planning, scheduling, completion, and follow-up of both inspections and deficiencies more efficient and manageable.
- Capture more information on the history of inspections and maintenance of all lines.
- Improve the planning processes to ensure that the required tools and equipment are available to perform maintenance work.

- A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

2. **MRO Inventory – \$108,000**

This project involves improvements to the MRO inventory processes. MRO inventory is the inventory necessary for the maintenance, repair and overhaul work performed in substations and plants. Currently there is limited inventory tracked or reserved for maintenance work. The integration between the Asset Management System and the Great Plains Inventory System will be enhanced in order to ensure inventory is available when the maintenance job is scheduled. Benefits include:

- Placing the procurement of inventory for MRO with the Purchasing group will allow for materials to be purchased using established procurement processes such as purchasing in bulk rather than “just in time” purchasing.
- Reducing the amount of time spent by planners, supervisors, engineers, and trades people on the ad-hoc purchase of materials.
- A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

3. **SCADA Enhancements - \$177,000**

This project consists of the following improvements to the Company’s System Control and Data Acquisition (SCADA) system. The SCADA system provides the capability and capacity for the Company to remotely monitor and control sections of the electrical distribution system. The proposed enhancements include improving the Company’s information exchange with Newfoundland and Labrador Hydro (“Hydro”) and adding electronic tagging capabilities to the SCADA system for the System Control Centre (SCC).

(i) With the implementation of Hydro’s new Energy Management System, the sharing of SCADA-related data between the two companies can be improved. This project involves upgrading the Company’s communications protocol to the same protocol to be used by Hydro. Benefits include:

- Sharing of a greater range of data between Newfoundland Power and Hydro related to the respective electrical systems.
- Improvements in the accuracy of SCADA-related information transferred between the two utilities.

(ii) The SCADA system will be enhanced to include the ability for the SCC to confirm and tag normally open devices on distribution feeders and tag mechanical components of the Company’s hydro generating plants. Tagging indicates a component’s status, such as whether a cutout is open or closed. Benefits include:

- Eliminating the time it takes for crews to travel to, and physically tag, normally open devices before beginning any work. This will help to improve the responsiveness of crews to customer trouble calls.
- Improved compliance with safety rules and standards. The Standard Protection Code states *Normally Open cutouts permanently identified with yellow signs must be confirmed open by the Control Authority or tagged*. Currently, the Control Authority (i.e. the SCC) has no ability to confirm normally open cutouts for line crews. Therefore, the crews must physically locate and tag them before beginning their work.
- Improved communications between the SCC and field personnel when conducting work on the electrical system related to switching orders and safety procedures.

(d) Customer Service System Enhancements

Cost: \$353,000

Description: The purpose of this item is to implement improvements in the customer service area. The following are the individual initiatives within this item:

1. **Service Order Improvements - \$54,000**

When field work, such as the installation of a streetlight, is required, a service order request is generated through the Customer Service System and a paper copy of the request is printed and forwarded manually to area office personnel for scheduling and completion. Because this process is paper based, Customer Contact Centre agents have limited access to information about the current status of service orders. Further, misplaced or misdirected paper can delay service order completion. Benefits include:

- Enabling the Customer Contact Centre to respond to customer inquiries regarding their service orders more accurately and efficiently by monitoring the status of each service order electronically.
- Completion of service orders in a timelier manner.
- Improving the tracking and scheduling of service orders and reducing the risk of lost or misplaced service orders.
- Better control over service orders will reduce the number of accounts that are billed incorrectly due to delays caused by the manual process.

2. Interactive Voice Response - \$156,000

The improved self-service application will offer customers the ability to make mailing address changes, requests for brochures, and submit self-read meter readings without having to talk to an agent. Benefits include:

- Allowing the company to provide better response to customers during peak usage times by having the IVR handle calls for routine items such as name changes or final read requests through system prompted messages. The agents can then complete these requests during times when call volumes are reduced.
- An additional 15,000 to 20,000 calls per year would be completed through the self-service functions.
- A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

3. Customer Service Reporting - \$143,000

This project involves collecting information regarding customer contacts and recording this information in a database to support more efficient routing of customer calls to Contact Centre agents and to allow reporting which will support new and revised customer service programs.

Examples of the information demographics which will be recorded and tracked include frequency of repeat calls by customers and the nature of calls. Benefits include:

- An integrated contact tracking and reporting environment will allow incoming calls to be routed to agents with the appropriate experience and skill level based on information gathered about the call and the customer. This will improve customer service and introduce efficiencies by reducing both the length of calls and the incidence of multiple contacts for the same issue.
- A better understanding of the nature of contacts will help identify where service improvements are required, support agent training and coaching activities, and identify where existing programs might be improved to provide better service to customers.
- A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

(e) Various Minor Enhancements:

Cost: \$150,000

Description: The purpose of this item is to complete enhancements to the Company's computer applications in response to unforeseen requirements such as legislative and compliance changes, vendor driven changes and employee driven enhancements designed to improve customer service or staff productivity. Examples of previous changes include adding criteria to the Customer Service System to flag accounts that are outside of a normal consumption range for manual review before billing, and government driven changes to income tax calculations in the payroll applications.

Project Title: **Application Environment**

Location: **All Service Areas**

Classification: **Information Systems**

Project Cost: **\$710,000**

Description: This project consists of upgrades to software components and processes related to the operation of the Company's business applications. For 2005, the proposed upgrades include:

1. **The Microsoft Enterprise Agreement – \$210,000**

This Agreement covers the purchase of Microsoft software and provides access to the latest versions of each software product purchased under this agreement.

Through the Microsoft Enterprise Agreement, Newfoundland Power achieves an overall cost savings. This is a fixed, annual price agreement based on the number of eligible desktops. Under this agreement, the Company distributes its purchasing costs for these licenses over three years.

In June 2004, the Company investigated the three options for the purchase of the following Microsoft licenses: Windows Professional, Office Professional and Client Access Licenses for Exchange Server, SQL Server, Windows Server, and System Management Server. The three options identified by the Company were:

- Do nothing now, and pay for new licenses to upgrade in the future. The expected cost per personal computer is \$1,117 over three years.
- Renew the existing Microsoft Enterprise Agreement at the proposed discount. This provides the Company with ownership of the latest releases of the identified software. These licenses are paid for annually following a count of the personal computers within the Company. Costs are spread out over the three-year period. The annual cost per personal computer is \$263, or \$789 over three years.
- Purchase a Microsoft Select Agreement for each installation of the software. This provides the Company with ownership of the latest releases of the identified software. These licenses have to be purchased individually as they are needed. The annual cost per personal computer is \$311, or \$933 over three years.

The Enterprise Agreement is the least expensive and least administratively burdensome option for Newfoundland Power at this time.

2. Database and Development software – \$270,000

This item involves upgrades to the underlying software components used by the Company's application systems. These components include database management software and software used to develop, modify and operate business applications. These upgrades will ensure the Company's business applications continue to function in a stable and reliable manner and ensure an appropriate level of vendor support is sustained. For 2005, proposed upgrades include:

- **Oracle Database Upgrade - \$48,000**
Customer self service data, used by customers who access their account information over the Internet, uses Oracle database software. The version currently in use is no longer supported by Oracle. An upgrade is required to ensure an appropriate level of support from Oracle.
- **Internet Website Environment Upgrade - \$53,000**
The Company's Internet website environment resides on a server running Microsoft Windows NT version 4.0 operating system. This operating system will not be supported by Microsoft beyond 2004. The Company's Internet website receives in excess of 17,000 visits per month. Customers who use the eBills option access the website to view an electronic copy of their electric bill. Upgrading the Internet website environment will ensure the availability, integrity, and security of the website for customers.
- **Cognos Powerhouse and Axiant Upgrade - \$169,000**
Powerhouse and Axiant software, which are used by Contact Centre Agents to access the Customer Service System to respond to customer requests for service, will not be supported by Cognos beyond February 2005. This upgrade will ensure continued vendor support for this critical software component.

3. Environment Management software – \$230,000

Environment Management, from an Information Technology perspective, refers to the technology and processes used to develop, configure, test, implement, and maintain applications and infrastructure throughout the Company. For 2005 this includes:

- **Help Desk Software Upgrade - \$62,000**
This project involves upgrades to the Company's Information Services Help Desk software to support asset configuration and change management business processes. Asset configuration is used to track PCs and shared servers and the installed software. Change management is used to track changes made to applications and technology infrastructure.
- **Password Management Software - \$55,000**
This project involves the purchase and deployment of password management software. Password management software will allow Company employees to efficiently change and control their passwords on the Company's computing systems,

eliminating calls to the Information Services Help Desk for assistance when passwords are forgotten.

- **Automated Software Test Tools - \$66,000**
This project involves the purchase and deployment of automated software test tools used in maintaining and enhancing the Company's corporate applications such as the Customer Service System and the Outage Management System. By utilizing automated testing tools the Company will reduce overall testing time, increase the speed to implement enhancements, and decrease the possibility of human error.
- **Development and Test Systems Improvements - \$47,000**
This project involves improvements to the Company's development and test systems that will allow employees to develop and test multiple versions and configurations of its applications simultaneously. An improved testing environment will reduce start-up and preparation time and allow employees to effectively analyze the full impact of changes prior to implementing them in the production environment.

Justification: Investment in the Application Environment is necessary to upgrade outdated technology that is no longer supported by vendors and to take advantage of newly developed capabilities. The Application Environment is essential to ensuring that changes made to software applications are sufficiently tested and stable before deployment into the production environment, thereby reducing the risk of downtime. Unstable and unsupported software applications can negatively impact operating efficiencies and customer service.

Project Title: Customer Systems Replacement

Location: All Service Areas

Classification: Information Systems

Project Cost: \$ 144,000

Description: This project consists of enhancing the nightly Customer Service System (CSS) batch processing (e.g. posting meter readings, posting cash payments, billing, etc.) to reduce the amount of time it takes to execute the programs, reduce the amount of manual intervention currently required, and to reduce the Company's dependence on the OpenVMS operating system. This will be achieved by enhancing the existing batch processing programs to run more efficiently and by the automatic scheduling of batch processing programs to run during the night.

Operating Experience: The CSS batch processing typically occurs from 6:00pm to 3:00am each weeknight. Computer Operators are required to submit new batch programs as other batch programs complete in a pre-defined sequence. The process of monitoring the completion of batch programs and subsequently running the next program in sequence is very manual, requiring the Computer Operator to be present throughout the night.

Justification: A financial analysis of the costs and benefits associated with this project results in a positive net present value over the next 5 years.

Benefits include:

- Reducing the amount of Computer Operator intervention will allow them to focus on more meaningful tasks;
- Reduced reliance on the OpenVMS system, in keeping with the findings of the *Customer Service System Replacement Analysis* report filed with the Public Utilities Board as part of the Company's 2004 Capital Budget Application (Volume IV, Information Systems, Appendix 3, Attachment A);
- Increased effectiveness of the Computer Operators by reducing the risk of human error associated with manual intervention.

Project Title: Network Infrastructure

Location: All Service Areas

Classification: Information Systems

Project Cost: \$276,000

Description: This project involves the upgrade and replacement of hardware components of the Company's network infrastructure to enhance the connectivity and reliability at the data centers located at Kenmount Road, Duffy Place, and Topsail Road.

Operating Experience: The network infrastructure is comprised of technical components such as routers and switches that interconnect computers and applications across the Company. These components all work together to enable the transport and sharing of SCADA data, VHF radio signals, and corporate data between the Company's computers across the province. For example, serving customers in Corner Brook requires Customer Service System information to be transmitted from St. John's over the network infrastructure to a cashier's personal computer in Corner Brook. Monitoring the current operating status of the electrical system on the west coast by employees at the System Control Centre ("SCC") in St. John's is also done via the network infrastructure.

Justification: The reliability and availability of the network infrastructure is critical to enabling the Company to continue to provide least cost reliable electric service to customers. The corporate network is the foundation for such critical applications as the Customer Service System, the SCADA System, and the Outage Management System. The replacement or upgrade of the network components will ensure the continued stability of the corporate network, thereby avoiding disruptions to customer service and the interruption of critical communications.

The components of the network infrastructure to be purchased in 2005 include:

- Fibre optic cables and software to interconnect the existing data storage systems located in the Kenmount Road computer room to a backup data storage system located in the computer room at Duffy Place. In the event of a major system failure at Kenmount Road, data stored in the Customer Service System can be recovered within 3 hours rather than twenty-four hours, which is the current recovery time. The budget for this item is \$147,000.
- A high availability network switch for the network at the SCC on Topsail Road. The network switch allows the SCC to access outage information stored in the Outage Management System, as well as information about the electrical system stored in the

SCADA system. The network at the System Control Centre is required twenty four hours per day every day in order to ensure that customer service and employee and public safety are not jeopardized. The high availability switch will have built-in redundancy to ensure network availability at all times. The budget for this item is \$129,000.

Project Title: **Personal Computer Infrastructure**

Location: **All Service Areas**

Classification: **Information Systems**

Project Cost: **\$455,000**

Description: This project involves the addition, upgrade, and replacement of computer hardware and related technology associated with the Company's personal computing infrastructure to ensure that the Company continues to provide effective customer service and to operate efficiently.

Operating Experience: The Personal Computer Infrastructure project includes the procurement, implementation and management of the hardware relating to the operation of personal computing facilities. Management of these computers and their components (i.e. PDAs, printers, scanners, etc) is vital to ensuring that computer applications are available and operating effectively at all times.

Minimum specifications for replacement personal computers ("PCs") are reviewed annually to ensure the personal computing infrastructure continues to remain effective. Industry best practices, technology trends, and the Company's experience are considered when establishing minimum specifications.

The Company's research and experience indicates that an average of four to six years of useful life is attainable before PCs require replacement. This is achieved through the Company's practice of cascading PCs to employees who do not require the computing power of newer PCs, thereby maximizing the asset life of the PC.

The following table outlines the plan for PC additions and retirements:

| | 2003 | | | 2004 Plan | | | 2005 Plan | | |
|--------------|-------------|---------------|--------------|------------------|---------------|--------------|------------------|---------------|--------------|
| | Add | Retire | Total | Add | Retire | Total | Add | Retire | Total |
| Desktop | 94 | 104 | 490 | 73 | 73 | 490 | 88 | 88 | 490 |
| Laptop | 30 | 26 | 122 | 35 | 35 | 122 | 25 | 25 | 122 |
| Total | 124 | 130 | 612 | 108 | 108 | 612 | 113 | 113 | 612 |

Justification: Personal Computers and associated peripheral equipment are used by employees throughout the Company to access applications to respond to customer requests for service, and to allow employees to be more efficient in their work activities.

The on-going replacement of the personal computer infrastructure ensures that the gains already attained in customer service and operating efficiencies are maintained.

Project Title: **Shared Server Infrastructure**

Location: **All Service Areas**

Classification: **Information Systems**

Project Cost: **\$571,000**

Description: This project involves the addition, upgrade and replacement of computer hardware components and related technology associated with the Company's shared server infrastructure to ensure that the Company continues to provide effective customer service and to operate efficiently. For 2005, this project includes:

- a) Purchase and implementation of five replacement servers. The budget for this item is \$197,000 and includes:
 - Two servers to improve the Company's capabilities to recover its applications and associated infrastructure in the event of a failure at its primary computing facility.
 - Two servers to upgrade the Company's Internet Website. Currently, the website resides on server infrastructure that will be replaced as part of the Application Environment project. This upgrade will also enhance the overall security of the website.
 - One server to improve the Company's access to the Internet. The proxy software that acts as the Company's gateway to the Internet and maintains security controls on data transferred to and from the corporate network is no longer supported by the vendor and security patches are no longer available. Replacement of the software, and the aged server on which it runs, will ensure that the integrity of Internet access is maintained and supported by the vendor.
- b) Purchase and implementation of additional disk storage, memory, and CPU upgrades for servers which are currently used to run corporate applications. Upgrades of shared servers are required in order to maintain adequate performance and availability of corporate applications that are used to provide service to customers and enable operating efficiencies. The budget for this item is \$49,000.
- c) Enhancements to security infrastructure and monitoring capabilities in order to provide adequate protection of customer data, improve operating efficiencies, and improve protection of the Company's information technology investment. Enhancements will be made to the SCADA Infrastructure, Internet Firewalls, Internet Intrusion Detection System, and software used to deploy upgrades to PCs. The budget for this item is \$290,000.

- d) Purchase of additional Citrix software licenses to provide secure remote access to the Company's applications. This will allow additional employees to access applications and data files stored on the Company's shared server infrastructure from a remote location such as a hotel room or from home. The budget for this item is \$35,000.

Operating Experience: The Shared Server Infrastructure project includes the procurement, implementation and management of the hardware and software relating to the operation of shared servers. Shared servers are computers that support applications used by multiple employees. Management of these shared servers, and their components, is critical to ensuring that these applications operate effectively at all times.

Technology components such as servers and disks require on-going investment to ensure that they continue to operate effectively. To maintain this effectiveness, investment in additions, upgrades, monitoring and security is essential.

An upgrade is a modification that extends the useful life of a technology component by fixing known problems, improving usability, and providing additional features and functionality. Hardware upgrades are also necessary to accommodate software enhancements, and include such things as adding extra disk storage or tape backup units.

In order to ensure high availability of applications and minimize the vulnerability of its computer systems to external interference, the Company invests in availability monitoring and proactive security monitoring tools. These tools allow the Company to monitor and respond to problems that could impede the normal operation of applications or damage or destroy information.

Eventually the individual components of technology (servers, disk drives, tape drives, processors and memory chips, etc) will require complete replacement as they become obsolete; the challenge is to make appropriate judgments as to when it is more cost effective to add or replace technology components rather than invest in further upgrades.

Factors considered in determining when to upgrade, replace or add server components include the current performance of the components, the level of support provided by the vendor, the criticality of the applications running on the shared server components, the ability of the components to meet future growth, the cost of maintaining and operating the components using internal staff and the business or customer impact if the component fails. Gartner states that computer servers have a useful life of approximately 5 years.¹ By making appropriate investments in its shared server infrastructure, Newfoundland Power's experience is that the useful life of its corporate servers has exceeded Gartner's findings.

¹ Gartner Group is a research and advisory firm that helps more than 10,000 businesses understand information technology. Founded in 1979, Gartner is headquartered in Stamford, Connecticut and consists of 4,600 associates, including 1,400 research analysts and consultants, in more than 83 locations worldwide.

Justification: The Shared Server Infrastructure is vital to the provision of low cost, efficient and reliable service to customers. The need to replace and modernize information technology infrastructure is fundamentally the same as the need to replace and modernize the components of the Company's electrical system infrastructure as it deteriorates or becomes obsolete. Instability within the Shared Server Infrastructure has the potential to impact high numbers of employees and customers and therefore is critical to the Company's overall operations and to the provision of overall customer service.