Q. Why is there excessive vegetation on the downstream face of Rattling Lake Dam? Is control of such growth part of Newfoundland Power Inc.'s normal maintenance practices (Figure 4, Attachment A, Appendix D, Volume II)?

A. The dams within the Rattling Lake system are located in an area of the province that is susceptible to rapid vegetation growth. As a result, frequent and excessive re-growth is common.

As part of its vegetation management program, Newfoundland Power selects a number of dams on a priority basis for vegetation clearing each year. With the current level of root material in the Rattling Lake Dam slope, vegetation clearing is required approximately every 5 years.

The photograph in Figure 4 as referenced was taken in September 2005, just prior to the execution of the Company's 2005 vegetation management program. The vegetation along the downstream slope of Rattling Lake Dam was cleared in October 2005.

It is important to control vegetation growth on engineered earth filled dams, such as Rattling Lake Dam. Dam safety can be compromised if vegetation such as trees or other deep rooted plants become established.

Trees and woody vegetation can make a dam susceptible to internal erosion. Decaying roots of dying vegetation can create a seepage path in the dam, leading to internal erosion, which is commonly known as "piping". Roots can also penetrate existing cracks and joints in the foundation rock and embankment, potentially leading to internal erosion and seepage. Furthermore, excessive vegetation growth makes it difficult to properly conduct dam safety inspections and monitoring.

As part of the capital improvements planned for Rattling Lake Dam in 2008, the downstream slope will be re-graded. The work will involve scarifying the downstream face by mechanical means to remove the root system, followed by placement of rock fill material. This will significantly reduce the extent of re-vegetation, reducing costs associated with future vegetation clearing efforts and ensuring that the integrity of the dam is maintained.