1	Q.	Re: 2013 Capital Projects 200,000 and Over but less than 500,000:
2		Explanations, pages D-142 through D-147 Replace Insulators:
3		Please provide the manufacturer's recommendations to replace older insulators
4		manufactured before the mid 1970's.
5		
6		
7	A.	The background information and recommendation concerning insulators
8		manufactured before the mid 1970s was provided by Shigeru Toyama, Executive
9		Vice President and General Manager for NGK Insulators of Canada, Ltd.
10		
11		It reads:
12		
13		"Back in those early days, COB and some other insulator manufacturers applied
14		Portland cement based on construction/building standards as it is to insulators.
15		After time, porcelain cracks have developed and been found on those insulators, and
16		investigation concluded those were due to expansion of cement. ANSI, CSA
17		standards have specified to limit the expansion coefficient rate to less than 0.12% to
18		countermeasure this issue.
19		
20		It is important to avoid cracks on insulator because it is critical factor to failure of
21		loss of insulation and mechanical strength. Therefore, it is important to replace
22		such insulators using high expansion rate cement.
23		
24		NGK have originally applied cement with low expansion rate from the beginning and
25		never had been an issue to our insulators."
26		
27		Source: S. Toyama (email communication, September 6, 2012)