

1 Q. Hydro's response to PR-PUB-NLH-127 dismisses the erroneous resistor setting as a
2 "major contributor" to the event. As "the resistor setting is meant to fine-tune the
3 motor speed to deliver target lube oil pump discharge", would not an operator,
4 when making the setting, discover that the required pump discharge could not be
5 achieved? Please clarify Hydro's response in this regard and why Hydro concludes
6 this is not a major contributor.

7
8
9 A. Any adjustments to the resistor located in the DC motor starter cabinet would be
10 executed by an industrial electrician, as an operator is not qualified to work in
11 energized cabinets. Motor speed has a major impact on discharge volume and
12 relatively negligible impact on discharge pressure. The controls that trigger the start
13 of standby and/or emergency pumps are based on pressure, not flow rate. The
14 standard set of return to service tests involve validating that each pump will start
15 and recover pressure with the primary pump left running in all cases. In other
16 words, there is no test that would see the DC pump running alone with the turbine
17 at speed. Therefore, an operator validating these tests as part of any return to
18 service will not be aware of the presence of an inadequate flow situation.

19
20 A normal return to service activity after an annual overhaul or a maintenance
21 intervention on the lube oil pumping system would include validating that the
22 standby and emergency pumps will successfully start in an emergency situation,
23 such as loss of pressure or power supply to the primary pump. This activity is
24 executed by the operator through the test logic provided on the unit control board.
25 Both a loss of pressure and loss of power scenarios are monitored such that these
26 will trigger first the standby and then the emergency systems. These tests are
27 completed without any intervention into the DC starter cabinet. If a test fails to

1 complete, then and only then would additional investigation be triggered that may
2 result in work inside the energized electrical cabinet by a qualified industrial
3 electrician.
4

5 The pass/fail for each of these tests is determined by achieving a minimum
6 threshold pressure not flow rate. Following the 2012 maintenance outage and for
7 each of the on-line weekly tests thereafter, the unit continued to test successfully
8 and the operator was unaware that insufficient flow was to be afforded by the DC
9 pump alone if both the primary and standby pumps were not available as was the
10 case on January 11, 2013. Upon investigation, it was determined that the DC motor
11 speed was improperly adjusted by a motor service provider. This had the result of
12 limiting the pumping capacity in terms of flow-rate (not pressure) to support
13 adequate lubrication and cooling to each of the five journal bearings supporting the
14 turbine generator set. The as found motor speed was approximately 80% of
15 expected/rated speed, which is well beyond the adjustment provided by the
16 resistor set-up in the motor starter cabinet. [] The position of the resistor had a
17 lesser impact than the condition of the motor on the pump speed and flow rate.
18 Therefore, Hydro considered the motor condition to be the major contributor to
19 the January 11, 2013 event.