

1 Q. On page 9 of Hydro's *Insulator Replacement TL-201 and TL-203* report, Hydro
2 states:
3 "The testing is currently ongoing and a report will be provided from Kinectrics by
4 the second quarter of 2014."

5 Please provide a copy of the Kinectrics report.
6
7

8 A. The Kinectrics report is attached as NP-NLH-1 Attachment 1.



To: Dr. Asim Haldar
Newfoundland and Labrador Hydro (Nalcor)
Hydro Place, 500 Columbus Drive
St. John's, NL
A1B 4K7
Canada

CONDITION ASSESSMENT TESTS OF PORCELAIN INSULATORS REMOVED FROM NALCOR'S CIRCUITS

Kinectrics Inc. Report No.: K-419614-RC-0001-R00

July 18, 2014

Dmitry Ladin, Michael Kastelein, Prasanna Ravinuthala
Transmission and Distribution Technologies Business

1.0 INTRODUCTION

At the request of Mr. Dr. Asim Haldar of Newfoundland and Labrador Hydro (Nalcor), Visual Examination and Mechanical Strength Tests were performed on aged 25,000 lbf rated glass insulator bells removed from Nalcor's Circuits and shipped to Kinectrics in order to assess the existing insulator condition. A total of thirty-two (32) insulator samples were received. Several of these had severely corroded and bent pins, which precluded the performance of mechanical tests therefore those insulators were only examined visually. Visual Examination and Mechanical Strength Tests were performed on all the other insulator samples.

The tests were carried out between May 6-8, 2014 in accordance with Kinectrics ISO 9001 Quality Management System by Kinectrics Inc. personnel at 800 Kipling Avenue, Toronto, Ontario, M8Z 5G5, Canada, under Nalcor Purchase Order No. 20972-000 OB, dated May 5, 2014.

A copy of Kinectrics ISO 9001 Accreditation Certificate is included in Appendix B.

2.0 TEST OBJECTIVE

The purpose of the tests on the glass insulator samples was to assess the condition of the insulators with regards to the possibility of mechanical line drops involving insulators from the same batch which is still in service. Visual Examination and Mechanical Strength Tests were suggested to analyze insulator degradation mechanisms.

PRIVATE INFORMATION

**Contents of this report shall not be disclosed without authority of the client.
Kinectrics Inc., 800 Kipling Avenue, Toronto, Ontario, M8Z 5G5**

3.0 TEST SETUP FOR MECHANICAL STRENGTH TEST

Figures 1 and 2 show photos of the general setup for performing the Mechanical Strength Test. The top (cap) of the insulator under test was connected to the upper plate of a tensile testing machine using an appropriate fixture. The insulator pin was connected directly to the test machine's lower plate. A wooden box completely enclosed the insulator to contain fragments of the insulator during failure.

4.0 SAMPLE IDENTIFICATION AND VISUAL EXAMINATION

The insulator samples were numbered S1 through S32 by Kinectrics personnel. Each sample was also marked with line phase identifier (e.g., A-phase) by Nalcor. Kinectrics maintained this identification system for consistency. Mechanical Strength Testing was conducted on eighteen (18) test samples. Fourteen (14) remaining untested samples with damaged and/or bent pin on the underside section were not suitable for tensile testing since the insulator's original strength was obviously seriously compromised. Photographs of the insulators prior to and after the testing are shown in Figures 3 through 8. Each insulator was visually examined. The visual examinations of the insulators are summarized in Table 1.

5.0 TEST PROCEDURE FOR MECHANICAL STRENGTH TEST

The procedures used to perform the Mechanical Strength Test followed the most recent version of CSA 411.1. These procedures are equivalent to ANSI C29.2 for suspension insulators. The rate of tensile loading was 11,250 lbf/min for all tested insulators (25,000 lbf rated insulators). The tensile load was increased until the insulator failed mechanically.

6.0 TEST RESULTS FOR MECHANICAL STRENGTH TEST

The results of the tests are shown in Table 1. Almost all 25,000 lbf insulators failed at a load below their rated strength of 25,000 lbf. Only one insulator (Sample # 28) failed at a tensile load exceeding its rating. The mode of failure for all tested insulators involved necking of the pin which lead to eventual failure of the pin. This is illustrated in Figure 6.

Table 1 Summary of Results of Visual Examination and Mechanical Tests

Sample No.	Insulator Identifier	Tensile Capacity, lbf	Visual Examination	Mechanical Failure Load, lbf	Ultimate Failure Mode	
S1	B-phase, Centre	25,000	Cracks on grouting and pin base corrosion	23,702	Tensile failure: insulator pin failed at the base	
S2				18,490		
S3				22,498		
S4			Pin is bent, no mechanical testing performed			
S5						
S6			Pin corrosion	16,677	Failed pin	
S7			Pin is bent, no mechanical testing performed			
S8						
S9			C-phase, back to source	Cracks on grouting and pin base penetrating corrosion (on underside)	18,410	Tensile failure: insulator pin failed at the base
S10					23,236	
S11					23,729	
S12	22,248					
S13	24,247					
S14	16,924					
S15	17,803					
S16	22,538					
S17	19,824					
S18	A-phase, left phase		11,556			
S19			Pin is bent, no mechanical testing performed			
S20						
S21						
S22						
S23						
S24						
S25						
S26						
S27						
S28			Pin corrosion	25,208	Failed pin	
S29	Pin is bent, no mechanical testing performed					
S30	C-phase, back to source		Cracks on grouting and pin base corrosion	16,732	Tensile failure: insulator pin failed at the base	
S31				20,479		
S32				14,250		

7.0 VISUAL EXAMINATION DISCUSSION

All test samples exhibited visible cracks in the surface of the grouting for the pin on the underside of the insulators (see Figure 5). The grouting surface cracks may be a result of thermal cycling and temperature excursions the insulators experience during their lifetime.

With varying degrees, all test samples showed advanced pin corrosion as shown in Figure 7. There is an obvious complete loss of Zinc (galvanizing) which normally protects the steel parts from the environment. Due to severe weathering and probable extended service life, the pin base in many samples experienced significant loss of material as a result of penetrating metal corrosion. The reduced cross-section de-rates the insulators' mechanical strength, which is evident from the mechanical test data.

8.0 CONCLUSIONS AND RECOMMENDATIONS

Based on the Visual Examination and Mechanical Strength Tests performed on the Nalcor glass insulator bells, removed from Nalcor's Circuits, the following conclusions are made:

- Only one of the tested insulators met the tensile strength requirement given in the standard specification. All of the remaining insulators failed to meet the standard tensile test requirements.
- The failure of the insulators to meet the standard tensile strength requirements is due to advanced corrosion of the pin which leads to significant reduction of the pin cross-section.
- Visible cracks on grouting surface of the insulator underside most likely display advanced weathering effects.

Based on the test results, we would strongly recommend that the insulators of which the tested units are representative be removed from service as soon as possible. Failure to do so will lead to a continually increasing probability of line drops due to mechanical failure of the insulator pins.


Prepared by:



D. Ladin
Engineer/Scientist
Transmission and Distribution Technologies Business



M. Kastelein
Lead Technologist
Transmission and Distribution Technologies Business



P. Ravinuthala
Technologist
Transmission and Distribution Technologies Business



Reviewed by:

J. Kuffel
Senior Engineer
Transmission and Distribution Technologies Business



Approved by:

Zs. Peter
Department Manager
Transmission and Distribution Technologies Business

DL:MK:PR:JK:ZsP:JC

DISCLAIMER

Kinectrics, Inc (KI) has taken reasonable steps to ensure that all work performed meets industry standards as set out in Kinectrics Quality Manual, and that, for the intended purpose of this report, is reasonably free of errors, inaccuracies or omissions. KI DOES NOT MAKE ANY WARRANTY OR REPRESENTATION WHATSOEVER, EXPRESS OR IMPLIED, WITH RESPECT TO THE MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE OF ANY INFORMATION CONTAINED IN THIS REPORT OR THE RESPECTIVE WORKS OR SERVICES SUPPLIED OR PERFORMED BY KI. KI does not accept any liability for any damages, either directly, consequentially or otherwise resulting from the use of this report.




Figure 1 Typical Test Setup for Mechanical Testing on Glass Insulators



Figure 2 Insulator Sample Prepared for Mechanical Testing



Figure 3 Typical Insulator Sample as received, Side View




Figure 4 Typical Insulator Sample as received, Bottom View




Figure 5 Typical Insulator Sample as received, Bottom View, Magnified View of Cement Grouting near Pin



Figure 6 Typical Insulator Sample after Mechanical Test (failed at Pin Base)



Figure 7 Typical Insulator Sample as received, Bottom View, Magnified View of Pin with Severe Corrosion



Figure 8 Typical Insulator Sample as received, Bottom View, with Bent Pin (not suitable for Mechanical Testing)

ISO-9001 Form: QF11-1 Rev 0, 97-10	APPENDIX A INSTRUMENT SHEET
--	--

Test Description: CONDITION ASSESSMENT TESTS OF GLASS INSULATORS REMOVED FROM NALCOR'S CIRCUITS	Test Start Date: May 6, 2014
Project Number: K-419614	Test Finish Date: May 8, 2014

TEST DESCRIPTION	EQUIPMENT DESCRIPTION	MAKE	MODEL	ASSET # or SERIAL #	ACCURACY CLAIMED	CALIBRATION DATE	CALIBRATION DUE DATE	TEST USE
M&E Test	Universal Test Machine-Load	Interface	1232 AF	KIN-01288	±0.1% of reading	September 20, 2013	September 20, 2014	Load
	Universal Test Machine- Displacement	Celesco	DPT250-0025- X11-1230-8482A	KIN-01291	< 0.05% of Reading	September 20, 2013	September 20, 2014	Displacement
	Universal Test Machine- Speed	Celesco	DPT250-0025- X11-1230-8482A	KIN-01290	±1% of reading	September 20, 2013	September 20, 2014	Loading rate
	Digital Caliper	Mitutoyo	500-505 0-18 inches	6000288	±0.025 mm	September 5, 2013	September 5, 2014	Insulator dimensions

APPENDIX B

**KINECTRICS ISO 9001 QUALITY MANAGEMENT SYSTEM REGISTRATION
CERTIFICATE**



Registered by:
SAI Global Certification Services Pty Ltd, 200 Sussex Street, Sydney NSW 2000 Australia with QMI-SAI Canada Limited, 20 Carlton Court, Suite 200,
Toronto, Ontario M5V 1V6 Canada (SAI GLOBAL). This registration is subject to the SAI Global Terms and Conditions for Certification. While all due care
and skill was exercised in carrying out this assessment, SAI Global accepts responsibility only for proven negligence. This certificate remains the property
of SAI Global and must be returned to them upon request.
To verify that this certificate is current, please refer to the SAI Global On-Line Certification Register: www.sai-global.com/certification-register

DISTRIBUTION

Dr. Asim Haldar (3) Newfoundland and Labrador Hydro (Nalcor)
Hydro Place, 500 Columbus Drive
St. John's, NL
A1B 4K7
Canada

Dmitry Ladin (1) Kinectrics Inc., Unit 2
800 Kipling Ave, KB 223
Toronto, Ontario
M8Z 5G5
Canada