

1 Q. With reference to Hydro's response to IC-27 NLH, page 7, line 10, the
2 Inspection Reports for each line inspected in the 2005 inspection year were
3 requested. Why has only the Inspection Report for TL 201 been provided in
4 the response (reports provided for other lines are WPLM Recommended
5 Action Report, Not Inspection Reports)?

6

7

8 A. Recommended Action reports were mistakenly provided. Inspection Reports
9 are attached.

Inspection Report – TL 201

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 230kV
- Geographic Location: Western Avalon Substation (Chapel Arm) to Hardwoods Substation (St. John's)
- Year of Construction: 1966
- Line Length: 80.6km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 811
- Pole Size: CL2 (85%), CL4 (15%)
- Suspension: 85%
- Angles and Deadends: 15%
- Species (based on inspection data)
 - Douglas Fir 36%
 - Southern Pine 32%
 - Western Red Cedar 32%

Pole Length Breakdown (Percent):

30'	50'	55'	60'	65'	70'	75'	80'
0.5%	7%	18%	18%	27%	18%	11%	0.5%

Past Performance:

- Significant Line Failures:
 - 1984 – Section from Structure 115 to Structure 151 collapsed under estimated 50mm glaze ice and 50kph wind
 - 1994 – Collapse of 7 structure just outside Western Avalon station
- Line Upgrades:
 - 1988 – Sections of the line were upgraded to 3" radial glaze ice by the addition of mid span structures, and reconductoring using 795ACSR
 - 1994 – Replacement of the section that collapsed was upgraded using 1192 ACSR 54/19 conductor
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002. No major pole replacements. Many worn eyebolts on suspension structures replaced. COB insulator periodically replaced.
 - 1985 – Entire line inspected. No poles rejected, signs of decay and poor pole preservative retention noted. No retreatment applied.
 - 1998 – Entire line inspected. 45 poles rejected and replaced in 1998. Preservative levels very low. No retreatment applied.
 - 2003/2004 – 597 poles inspected. 9 poles replaced in spring 2006.

Current Inspection (covered by this report)

- 214 poles (26% of total) inspected – Note: Line inspection now complete
- 64 poles (8.2%) recorded as possible rejections by field crew
- 27 poles (3.5%) scheduled for replacement after analysis
- Major pole issue: rot at pole tops and groundline
- Minor pole issues: some carpenter ants and woodpeckers
- 99 poles after 2006 replacement program (including 62 from 2003/2004 inspection) will require periodic monitoring
- Eyebolt wear on suspension structures continues to be an issue
- Preservative retention: average 0.08pcf (minimum required 0.18pcf)

Future Work

- 2006
 - Replace 27 poles, remaining COB insulators, and other noted defects in 2006 using existing WPLM CJC
 - Scheduled inspection complete
- After 2006
 - Periodically monitor 99 poles, numerous other wood items, and eye bolts
 - Schedule next major inspection for 2014

Inspection Report – TL 210

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Stony Brook Substation to Cobbs Pond Substation
- Year of Construction: 1969
- Line Length: 85.4km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 606
- Pole Size: CL2 (100%)
- Suspension: 89%
- Angles and Deadends: 11%
- Species (based on inspection data)
 - Douglas Fir 43%
 - Southern Pine 53%
 - Western Red Cedar 4%

Pole Length Breakdown (Percent):

40'	45'	50'	55'	60'	65'	70'	75'
3%	3%	12%	11%	19%	26%	24%	2%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.

Current Inspection (covered by this report)

- 468 poles (77% of total) inspected
- 56 poles (12%) recorded as possible rejections by field crew
- 31 pole (7%) scheduled for replacement after analysis
- Major pole issue: Carpenter Ants
- Minor pole issues: Decay and Shell Separation
- 115 poles after 2006 replacement program will require periodic monitoring
- Pole problems are increasing in frequency on this line
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - 31 pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - 156 poles to be inspected in 2006
- After 2006
 - Periodically monitor 115 poles
 - Schedule next major inspection for 2015

Inspection Report – TL 218

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 230kV
- Geographic Location: Holyrood Substation to Oxen Pond Substation
- Year of Construction: 1966/1983 – Lines joined in 2002 - Mix of TL 236 (10.5km) and TL 242 (27.2 km)
- Line Length: 37.7km
- Basic Line Loading, Original Design:
 - TL 236 Section
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind
 - TL 242 Section
 - 1.5" Radial Glaze

Construction Summary:

- Total Wood Poles: 445
- Pole Size: CL1 (6%), CL2 (94%)
- Suspension: 83%
- Angles and Deadends: 17%
- Species (based on inspection data)
 - Douglas Fir 31%
 - Southern Pine 58%
 - Western Red Cedar 11%

Pole Length Breakdown (Percent):

30'	45'	50'	55'	60'	65'	70'	75'	80'
1%	1%	4%	3%	11%	20%	24%	35%	1

Past Performance:

- Significant Line Failures:
 - 1984 – 2.4km failed near Oxen Pond Station
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.

Current Inspection (covered by this report)

- 221 poles (50% of total) inspected
- 26 poles (12%) recorded as possible rejections by field crew
- 4 pole (2%) scheduled for replacement after analysis
- Major pole issue: Shell Separation
- Minor pole issues: Carpenter Ants
- 32 poles after 2006 replacement program will require periodic monitoring
- Rotten cross brace blocking on entire line
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - 4 pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - 75 poles to be inspected in 2006
- After 2006
 - Periodically monitor 32 poles
 - Schedule next major inspection for 2015

Inspection Report – TL 223

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Springdale Substation to Indian River Substation
- Year of Construction: 1966
- Line Length: 29.8km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 351
- Pole Size: CL3 (100%)
- Suspension: 92%
- Angles and Deadends: 8%
- Species (based on inspection data)
 - Douglas Fir 0%
 - Southern Pine 98%
 - Western Red Cedar 2%

Pole Length Breakdown (Percent):

45'	50'	55'
45	46	9

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002. No major pole replacements. Cross arm replacement has been an issue over the last few years with approximately 35 replaced in 2002/2003.
 - WPLM – 175 poles inspected in 2004, 10 crossarms replaced

Current Inspection (covered by this report)

- 95 poles (25% of total) inspected
- 15 poles (16%) recorded as possible rejections by field crew
- 1 pole (3%) scheduled for replacement after analysis
- Major pole issue: checking
- Minor pole issues: shell separation
- Rotten cross arms are prominent on this line with 13 replacements in 2006, and 50 to monitor
- 12 poles after 2006 replacement program will require periodic monitoring
- Preservative retention: average 0.133pcf (minimum required 0.18pcf)

Future Work

- 2006
 - Replace 3 pole, 13 cross arms, and other noted defects in 2006 using existing WPLM CJC
 - Inspect another 81 poles in 2006
- After 2006
 - Periodically monitor 24 poles, cross arms and numerous other wood items
 - Schedule next major inspection for 2015

Inspection Report – TL 226

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Single Wood Pole
- Operating Line Voltage: 69kV
- Geographic Location: Deer Lake Substation to Berry Hill Substation
- Year of Construction: 1970
- Line Length: 77.9km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 893
- Pole Size: CL2 (100%)
- Suspension: 77%
- Angles and Deadends: 23%
- Species (based on inspection data)
 - Douglas Fir 1%
 - Southern Pine 98%
 - Western Red Cedar 1%

Pole Length Breakdown (Percent):

30'	35'	40'	45'	50'	55'	60'	65'	70'	75'
1%	28%	41%	13%	7%	5%	3%	1%	0%	1%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.
 - WPLM – 433 poles inspected in 2003/2004, 7 replaced

Current Inspection (covered by this report)

- 271 poles (30% of total) inspected
- 0 poles (0%) recorded as possible rejections by field crew
- 0 poles (0%) scheduled for replacement after analysis
- Major pole issue: none
- Minor pole issues: none
- 3 poles after 2006 replacement program will require periodic monitoring
- Many structures on this line are not plumb. This condition has existed for many years without incident
- Preservative retention: average 0.088pcf (minimum required 0.18pcf)

Future Work

- 2006
 - No poles to be replaced in 2006. Several insulators and guy guards to be replaced, in addition to other noted defects in 2006 using existing WPLM CJC
 - Inspect another 179 poles in 2006
- After 2006
 - Periodically monitor 8 poles, and rusty guy wires and guy grips
 - Schedule next major inspection for 2015

Inspection Report – TL 227

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Single Wood Pole
- Operating Line Voltage: 69kV
- Geographic Location: Berry Hill Substation to Daniel's Harbour Substation
- Year of Construction: 1970
- Line Length: 83.9km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 972
- Pole Size: CL1 (0.5%), CL2 (99.5%)
- Suspension: 87%
- Angles and Deadends: 13%
- Species (based on inspection data)
 - Douglas Fir 0%
 - Southern Pine 100%
 - Western Red Cedar 0%

Pole Length Breakdown (Percent):

35'	40'	45'	50'	55'	60'	65'	70'	75'
58%	25%	1%	7%	3%	4%	1%	0%	1%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.
 - WPLM – 311 poles in 2004

Current Inspection (covered by this report)

- 332 poles (34% of total) inspected
- 4 poles (1%) recorded as possible rejections by field crew
- 1 pole (0.3%) scheduled for replacement after analysis
- Major pole issue: shell separation
- Minor pole issues: some rot
- 3 poles after 2006 replacement program will require periodic monitoring
- Many structures on this line are not plumb. This condition has existed for many years without incident
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - 1 pole replacement required. Repair other noted defects in 2006 using existing WPLM CJC
 - Inspection complete on this line. Remaining poles installed in 2002
- After 2006
 - Periodically monitor 11 poles
 - Schedule next major inspection for 2015
 - Poles installed in 2002 will be inspected in 2013

Inspection Report – TL 234

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 230kV
- Geographic Location: Upper Salmon Substation to Bay D’Espoir Substation
- Year of Construction: 1981
- Line Length: 51.3km
- Basic Line Loading, Original Design:
 - 1” Radial Glaze
 - 110MPH Gust Wind
 - 0.5” Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 515
- Pole Size: CL1 (8%), CL2 (92%)
- Suspension: 88%
- Angles and Deadends: 12%
- Species (based on inspection data)
 - Douglas Fir 95%
 - Southern Pine 5%
 - Western Red Cedar 0%

Pole Length Breakdown (Percent):

30	35'	40'	45'	50'	55'	60'	65'	70'	75'
3%	0%	0%	0%	2%	1%	8%	45%	31%	9%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.
 - WPLM Pilot Study – 243 poles in 2002

Current Inspection (covered by this report)

- 272 poles (53% of total) inspected
- 6 poles (2%) recorded as possible rejections by field crew
- 3 pole (1%) scheduled for replacement after analysis
- Major pole issue: Carpenter Ants
- Minor pole issues: Checking
- 18 poles after 2006 replacement program will require periodic monitoring
- Significant wood decay issues with all components other than poles (knee braces, cross arms, cross braces, blocking). Steps being taken to periodically monitor and replace as required
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - 3 pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - Inspection complete on this line. Remaining poles inspected during pilot study in 2002
- After 2006
 - Periodically monitor 18 poles
 - Schedule next major inspection for 2015
 - Poles installed in 2002 will be inspected in 2013

Inspection Report – TL 240

Report Coverage: 2005 inspection year

Report Issued April 20, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Churchill Falls Substation to Goose Bay Substation
- Year of Construction: 1976
- Line Length: 269.0km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 2640
- Pole Size: CL2 (14%), CL4 (86%)
- Suspension: 96%
- Angles and Deadends: 4%
- Species (based on inspection data)
 - Douglas Fir 0%
 - Southern Pine 100%
 - Western Red Cedar 0%

Pole Length Breakdown (Percent):

45°	50°	55°	60°	65°	70°
2%	15%	20%	41%	17%	4%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.

Current Inspection (covered by this report)

- 248 poles (9% of total) inspected
- 5 poles (2%) recorded as possible rejections by field crew
- 0 pole (0%) scheduled for replacement after analysis
- Major pole issue: Wood Peckers
- Minor pole issues: Internal decay
- 7 poles after 2006 replacement program will require periodic monitoring
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - No pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - 792 poles planned for inspection in 2006, however may be reduced based on results
- After 2006
 - Periodically monitor 7 poles
 - Schedule next major inspection for 2015
 - Line outage restrictions limit maintenance outages on this line.

Inspection Report – TL 241

Report Coverage: 2005 inspection year

Report Issued April 20, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Peter's Barren Substation to Plum Point Substation
- Year of Construction: 1983
- Line Length: 109.5km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 1082
- Pole Size: CL2 (58%), CL3 (37%), CL4 (5%)
- Suspension: 93%
- Angles and Deadends: 7%
- Species (based on inspection data)
 - Douglas Fir 2%
 - Southern Pine 93%
 - Western Red Cedar 5%

Pole Length Breakdown (Percent):

30'	40'	50'	55'	60'	65'	70'	75'
1%	1%	7%	28%	35%	18%	6%	3%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.

Current Inspection (covered by this report)

- 146 poles (13% of total) inspected
- 5 poles (3%) recorded as possible rejections by field crew
- 0 pole (0%) scheduled for replacement after analysis
- Major pole issue: Rot
- Minor pole issues: Shell Separation and Carpenter Ants
- 10 poles after 2006 replacement program will require periodic monitoring
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - No pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - 163 poles planned for inspection in 2006
- After 2006
 - Periodically monitor 10 poles
 - Schedule next major inspection for 2015

Inspection Report – TL 243

Report Coverage: 2005 inspection year

Report Issued April 20, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Hinds Lake Substation to Howley Substation
- Year of Construction: 1978
- Line Length: 15.0km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 175
- Pole Size: CL2 (78%), CL4 (22%)
- Suspension: 82%
- Angles and Deadends: 18%
- Species (based on inspection data)
 - Douglas Fir 34%
 - Southern Pine 66%
 - Western Red Cedar 0%

Pole Length Breakdown (Percent):

30'	45'	50'	55'	60'	65'	70'	75'
1%	5%	5%	9%	49%	14%	16%	1%

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002.

Current Inspection (covered by this report)

- 175 poles (100% of total) inspected
- 3 poles (2%) recorded as possible rejections by field crew
- 2 pole (1%) scheduled for replacement after analysis
- Major pole issue: Internal Decay
- Minor pole issues: Shell Separation
- 7 poles after 2006 replacement program will require periodic monitoring
- Preservative retention: unavailable at time of report (minimum required 0.18pcf)

Future Work

- 2006
 - 2 pole replacements required. Repair other noted defects in 2006 using existing WPLM CJC
 - Inspection complete on this line
- After 2006
 - Periodically monitor 7 poles
 - Schedule next major inspection for 2015

Inspection Report – TL 250

Report Coverage: 2005 inspection year

Report Issued April 19, 2006

General Line Description:

- Construction Type: Wood Pole H-Frame
- Operating Line Voltage: 138kV
- Geographic Location: Bottom Brook (Stephenville) Substation to Grandy Brook (near Burgeo) Substation
- Year of Construction: 1987
- Line Length: 123.3km
- Basic Line Loading, Original Design:
 - 1" Radial Glaze
 - 110MPH Gust Wind
 - 0.5" Ice / 55MPH Wind

Construction Summary:

- Total Wood Poles: 1283
- Pole Size: CL2 (58%), CL3 (7%), CL4 (35%)
- Suspension: 76%
- Angles and Deadends: 24%
- Species (based on inspection data)
 - Douglas Fir 12%
 - Southern Pine 80%
 - Western Red Cedar 8%

Pole Length Breakdown (Percent):

40'	45'	50'	55'	60'	65'	70'	75'
2	5	6	11	32	17	14	13

Past Performance:

- Significant Line Failures:
 - No significant line failures recorded
- Line Upgrades:
 - No line upgrades recorded
- Previous Inspections:
 - Standard preventive maintenance inspections (20% annually) until 2002. No major pole replacements.
 - WPLM – 108 poles inspected in 2004

Current Inspection (covered by this report)

- 245 poles (19% of total) inspected
- 11 poles (4%) recorded as possible rejections by field crew
- 8 poles (3%) scheduled for replacement after analysis.
- Major pole issue: rot
- Minor pole issues: shell separation and Wood Pecker holes
- 9 poles after 2005 inspection program will require periodic monitoring
- Preservative retention: average 0.083pcf (minimum required 0.18pcf)

Future Work

- 2006
 - 8 pole replacements and other noted defects to be replaced in 2006 using existing WPLM CJC
 - 321 poles to be inspected in 2006
- After 2006
 - Periodically monitor 13 poles, numerous other wood items
 - Schedule next major inspection for 2015