1 Q. Re p. B-6, clarify the statement that the average service life of the six exciters replaced was 27 years. Does this mean that each failed and the 2 3 average time to failure was 27 years? 4 5 6 A. None of these exciters failed in service. At the time of replacement, 27 years 7 was the average in-service life of the 6 exciters at Bay d'Espoir and the 2 8 exciters at Holyrood and was higher than the expected service life of 25 9 years. 10 11 The exciters were replaced at Bay d'Espoir and Holyrood due to age, limited 12 product support from the original equipment manufacturer and a limited 13 supply of critical spare parts in stores inventory.