

1 Tab H, Section 2- Wood Pole Management Program

2 Q. To what “outage restrictions” (page unnumbered, reference last page before
3 sample inspection sheet) is NLH referring?

4

5

6 A. The “outage restrictions” Hydro is referring to are due to Hydro’s Energy
7 Control Centre not being able to provide scheduled outages for
8 refurbishment and/or replacement work on TL 201 and TL 203. This
9 restriction was imposed because there was not enough generation available
10 on the east coast of the island to take both transmission lines out of service
11 without putting the entire system at risk in the event of another contingency.