

In reference to Schedule “B”, page 58 of 82 – Additions to Real Property, project cost \$140,000:

Q. Please provide an inspection report in reference to the roof at the Maple Valley Building in Corner Brook. Please specify what “other service building improvement” are and the costing of these.

A. No specific inspection report exists for the project to repair a portion of the roof over the office section of the Maple Valley Service Building. However, the work is necessary to eliminate the severe leaks that result from ice damming each winter. Remediation work includes reconstructing the eaves and the sealing of all seams.

“Other service building improvement” involves carrying out drainage improvements at the Carbonear Office Building at an estimated cost of \$40,000. This project is required to eliminate flooding problems being experienced at this building.