

**PORT UNION**  
**OPERATOR'S DAM SAFETY INSPECTION**  
**CHECKLIST**

Whirl Pond Dam

Date: Apr 04, 2000

Water Level:	<u>8.4' (spilling 8")</u>
Weather:	<u>Sunny</u>
Upstream Face:	<u>Needs repairs</u>
Dam Rockfill:	<u>OK</u>
Gate Opening:	<u>OK</u>
Gate Operation:	<u>Needs Repairs</u>
Gate cribbing and ballast (include picture):	<u>OK</u>
Fish Screen:	<u>OK</u>
Spillway concrete:	<u>Good</u>
Spillway leakage measurement:	<u>Some leakage</u>
Comments:	<u>Spillway newly constructed.</u>
	<u>Low sections in Whirl Pond - Temp dams in place.</u>