

PORT UNION  
OPERATOR'S DAM SAFETY INSPECTION  
CHECKLIST

Whirl Pond Dam

Date: Aug 08, 2000

Water Level:	<u>1'</u>
Weather:	<u>Rain – drizzle – fog</u>
Upstream Face:	<u>Needs repairs</u>
Dam Rockfill:	<u>OK</u>
Gate Opening:	<u>1"</u>
Gate Operation:	<u>Needs Repairs</u>
Gate cribbing and ballast (include picture):	<u>OK (top side 8"x8" replaced)</u>
Fish Screen:	<u>OK</u>
Spillway concrete:	<u>Good</u>
Spillway leakage measurement:	<u>Some leaks</u>
Comments:	<u>Low sections around Whirl Pond Dam.</u>
	<u>Temporary dams in place.</u>