

PORT UNION
OPERATOR'S DAM SAFETY INSPECTION
CHECKLIST

Whirl Pond Dam

Date: Nov 19, 2001

Water Level:	<u>7'</u>
Weather:	<u>Sunny</u>
Upstream Face:	<u>Needs repair</u>
Dam Rockfill:	<u>Needs repair</u>
Gate Opening:	<u>16"</u>
Gate Operation:	<u>Good</u>
Gate cribbing and ballast (include picture):	<u>Minor repairs needed</u>
Fish Screen:	<u>Removed for season</u>
Spillway concrete:	<u>OK</u>
Spillway leakage measurement:	<u>OK</u>
Comments:	<u></u>