

1 **Re Reconductor Section of GLD-01, Volume III, Distribution – Appendix 4,**
2 **page 2 (\$80,000)**

3
4 **Q. Please explain the exact nature of the “transformer loading issue at the Hardwoods**
5 **and Glendale substations” and identify how this project will mitigate this issue.**

6
7 **A. See response to NLH-63 NP.**