Q. <u>GENERATION HYDRO</u>

2 3 **PUB 36.0**

B-4 Plant Refurbishment – Petty Harbour

What items among those listed in Table B-1 of 1.2 Petty Harbour Hydro Plant Refurbishment are considered to be interdependent versus related?

6 7

1

4

5

A. Table 1 provides the requested information.

8

Table 1 Petty Harbour Hydro Plant Refurbishment Interdependent vs. Related Items

| Interdependent Items | Cost Estimate |
|---|---------------|
| Upgrade Controls G1 | \$ 80,000 |
| Replace Unit Control PLCs G2 | 372,000 |
| Replace Electronic Governor G2 | 86,000 |
| Upgrade Generator Protection and Control G2 | 184,000 |
| Replace Unit Control PLCs G3 | 372,000 |
| Replace Electronic Governor G3 | 86,000 |
| Upgrade Generator Protection and Control G3 | 191,000 |
| Upgrade Plant AC and DC Systems | 79,000 |
| Total Interdependent Items | 1,450,000 |
| Related Items | |
| Turbine Overhaul | 153,000 |
| Penstock Coating Replacement | 226,000 |
| Total Related Items | 379,000 |
| Total Interdependent and Related Items | \$1,829,000 |

10