

1 Q. **Reference: Schedule 1, page 5 of 10, lines 7-8**

2 Hydro states "The storage room and porch may require some sheathing repair; however, this
3 cannot be determined until shingles are removed". Are the estimated costs for sheathing repair,
4 if required, included in the \$634,500 expenditure request? If yes, please provide the estimated
5 sheathing repair costs included.

6

7

8 A. The estimated costs for sheathing repairs to the storage room and porch areas are included in
9 the \$634,500 expenditure request. The cost associated with these repairs is estimated to be
10 \$5,000.