

1 **Re: Replace Unit 2 Air Pre-heater Cold End:**

2 Q. Does this project include everything recommended in the 2005 Alstom
3 Report in connection with pre-heaters and, if not, why not?

4

5

6 A. No, this project does not include everything recommended in the 2005
7 Alstom Report in connection with the air pre-heaters because, with the
8 exception of replacing the corroded sections of the rotor and diaphragm and
9 installing rotor shaft seal covers, the other work recommended in the report
10 relating to the air pre-heaters was completed in 2006 and 2007.