

1 **Re Wood Pole Line Management (WPLM) Program, page B-13:**

2 Q. At page 10 of Hydro's 2009 Wood Pole Line Management report, Hydro
 3 identifies that Hydro crews replaced 97 poles, 31 crossarms, and 19 cross-
 4 braces and many other smaller components as identified in the spring of
 5 2007. Provide a breakdown of the number of poles which were replaced, or
 6 in respect of which a component was replaced, by individual line inspected in
 7 the spring of 2007.

8
 9

10 A. The following table provides the breakdown of poles and components that
 11 were replaced in 2007.

Item	TL 210	TL 223	TL 232	TL 251	TL 252	TL 254	TL 212	TL 218	TL 219	TL 250	TL 226	TL 229	TL 239	TL 241	TL 244	TL 240
Poles	10		29	5	4	2	29	1		4			13			
Crossarms	1	10	1	4	4	1				4	6					
Crossbracing	3		9	2			2							3		
Knee braces			11													
Insulators	11	1	2		1		2			7	3	1	1			
Miscellaneous Hardware	9		46	7	9		4	47		42	18		3	31	2	18
Foundations and Anchors	1			1	3				1		8		1	6	2	6
Leaning Structures	1				1		1	2		1			2			5