- Q. Re: Rocky Pond Plant Refurbishment (p. 2 of 81, Schedule B) Did NP undertake a follow-up report providing an evaluation of the actual condition of the penstock that it replaced at Rattling Brook which could be compared against the condition indicated by engineering inspections and assessments?
- 6 A. Newfoundland Power did not undertake a follow-up report with respect to the Rattling Brook penstock.