## 1 Q. Replace Light Duty Mobile Equipment - 2010; Vol II, Tab 21

With respect to the ATV's and snowmobiles to be replaced in 2010, what condition is each in?

5

6

7

8

A. Most units are in poor condition as a result of being operated on less than ideal terrain and high usage. The majority of maintenance issues are frame cracks and suspension wear. Some equipment in high salt areas has severe rusting.

Unit	2010 Mobile Equipment Type	Area	Age at retirement	Condition
V7001	ATV	Stephenville	5.2	Drive train rusty, body has extensive damage
V7022	ATV	Port Saunders	5.1	Frame damage, Drive train worn
V7023	ATV	Whitbourne	5.1	Frame damage, Drive train worn
V7027	ATV	Happy Valley	4.9	Severe rust on all mechanical components & electrical system
V7028	ATV	Happy Valley	4.9	Severe rust on all mechanical components & electrical system
V7029	ATV	Happy Valley	4.9	Severe rust on all mechanical components & electrical system
V7049	ATV	Stephenville	4.2	Suspension Bad
V7050	ATV	Bishop's Falls	4.2	Engine bad
V7051	ATV	Bay D'Espoir	9.9	Frame damage, Drive train worn
V7052	ATV	Bay D'Espoir	4.2	Suspension Bad
V7053	ATV	Bishop's Falls	4.5	Frame damage, Drive train worn
V7056	ATV	Bishop's Falls	4.2	Frame damage, Drive train worn
V7057	ATV	Stephenville	4.2	Engine bad
V7061	ATV	Port Saunders	4.5	Suspension Bad
V7062	ATV	Stephenville	4.5	Frame damage, Drive train worn
V7005	Snowmobile	St. Anthony	5.1	Frame Cracked engine runs poorly
V7006	Snowmobile	Bay D'Espoir	5.1	Track Bad
V7007	Snowmobile	Bishop's Falls	5.1	Engine bad
V7008	Snowmobile	Bay D'Espoir	4.6	Suspension Bad

## CA-NLH-21 NLH 2010 Capital Budget Application

## Page 2 of 2

V7009	Snowmobile	Bay D'Espoir	4.6	Suspension Bad
V7014	Snowmobile	Port Saunders	5.1	Body Bad
V7031	Snowmobile	Bishop's Falls	4.4	Frame Cracked engine runs poorly
V7033	Snowmobile	Bishop's Falls	4.4	Engine bad
V7034	Snowmobile	Stephenville	4.4	Engine bad
V7039	Snowmobile	Stephenville	4.4	Engine bad
V7041	Snowmobile	Stephenville	4.5	Frame Cracked engine runs poorly
V7043	Snowmobile	Stephenville	4.5	Engine bad
V7044	Snowmobile	Whitbourne	4.4	Frame Cracked engine runs poorly
V7045	Snowmobile	Whitbourne	4.4	Engine bad
V7047	Snowmobile	Whitbourne	4.4	Engine bad
V7639	Snowmobile	St. Anthony	6.1	Engine bad
V7654	Snowmobile	Springdale	6.1	Engine bad
V7655	Snowmobile	St. Anthony	6.1	Severe rust on all mechanical components & electrical system