

1 Q. **Re: Replace Pump House Motor Control Centers-Holyrood, Vol. I, p. B-12; Vol. II -**  
2 **Tab 6**

3 At page 4 of the report at Tab 6 of Vol. II it states:

4 "The motor control centers are located in the main open equipment area of the  
5 pumphouse and are exposed to a damp and corrosive environment. This  
6 environment has caused deterioration to the motor control centers such as  
7 moisture build up and rusting of contacts which results in an unreliable system and  
8 unplanned outages".

9 Does NLH have any records which show that the motor control center in either  
10 pumphouse 1 or pumphouse 2 has been unreliable and/or has caused unplanned  
11 outages to the generator units?

12

13

14 A. As stated in Section 3.5 of the report, outage statistics are only tracked at a unit  
15 level and are not specific to subsystems such as the pumphouse motor control  
16 centers. There are no records available to determine the percentage of unit failures  
17 or outages that have been caused by failures of the pumphouse motor control  
18 centers.