

1 Q. **Re: Plant Life Extension Upgrades, Vol. II, Tab 1.**

2 At page A2 it states in the Stantec Final Report: "Since HYDRO was unable to
3 provide any historical electrical testing data or visual inspection information on the
4 alternator at either site, it was not possible to assess the current condition of either
5 alternator and determine the extent of remedial work required...". Has Hydro
6 conducted a thorough inspection of the stator and rotor in order to determine
7 whether refurbishment or replacement is required?

8

9

10 A. A thorough inspection of the stator and rotor will be conducted in 2009. A contract
11 for this work has been awarded and will take place during the next available total
12 plant outage.