

1 Q. **Re Refurbish Fuel Storage Facility, page B- 8**

2 What evidence is there of the extent of continuing corrosion, if any, of the floor of
3 Tank 4 since and notwithstanding the installation of the patch plates in 2004?

4

5

6 A. No further inspection of the floor plates has been carried out due to the high cost of
7 cleaning required to carry out an inspection.