

1     Q.     Further to IC-NLH-188, please provide the capital cost that was incurred (if any)  
2             related to the referenced rotor pole failure, which resulted from vibration caused  
3             by “upgrade work on the rotor and stator”.

4

5

6     A.     There was no capital costs incurred related to the referenced rotor pole failure.  
7             Hydro's response to IC-NLH-188 references work that was completed in 2008 which  
8             was related to a rotor rewind and not a pole failure.