

1 Q. Reference: Page 2 – Hydro states that the test procedure lacked a check that would
2 have identified the “particular failure experienced within the pump set which made
3 the pump unable to deliver the required oil flow to the bearings.” Please explain:

4

5 (a) What was the “particular failure” experienced within the pump set that
6 would have been detected by the check that was lacking?; and

7

8 (b) What was the check that was lacking and how this check would have
9 detected the particular failure experienced?

10

11

12 A. (a) The particular failure experienced with the DC pump is an operational speed
13 and corresponding horsepower reduction with the DC motor driving the
14 pump.

15

16 (b) Please see the response to IC-NLH-5.