

1 Q. Please explain how Hydro eventually determined that the bus from breaker B1L37
2 feeding the T5 transformer was not being energized on one phase.

3

4

5 A. During the investigation of the Western Avalon T5 tap changer failure, the
6 investigation team reviewed detailed sequence of events and relay information
7 and discovered that during the outage on January 4, 2014, the breaker B1L37 had
8 one phase that remained open on each attempt of the breaker closing.