

1 Q. **Projects over \$50,000 but Less Than \$200,000**

2 Tab 2 Replace Interior Coating on Surge Tank 3, Bay d'Espoir

3 In Appendix A, at page A8, Hatch outlines that the internal inspection revealed that
4 the coating system on the interior of the tank roof, shell, bowl and riser is in good
5 condition with some minor localized breakdown. As a result, Hatch recommended
6 at Page A9 that a complete detailed assessment of the tank interior coating system
7 with a certified NACE inspection occur within the next two years. Hydro's proposal
8 for this project is that an inspection occur as part of the project. Following Hatch's
9 recommendation, why shouldn't the inspection be completed first to determine
10 whether the extent of work Hydro is anticipating is actually required. (See also
11 pages A15, A16).

12

13

14 A. Please refer to Hydro's responses to IC-NLH-016 and IC-NLH-019.