

1 Q. Reference: Refurbish Generation Unit – Snook’s Arm, Volume I, Section D,  
2 Appendix B, Page D-67  
3 *“The purpose of these tests was to determine the present condition of the runners*  
4 *to confirm that planned runner replacements are justified.”*

5 Confirm that the runners were not replaced following the 1993 report and provide  
6 the justification for not proceeding with the project at that time.

7  
8  
9 A. It is confirmed. The runners at Snook's Arm and Venam's Bight were not replaced.

10  
11 The conclusions of the study at the time determined that prior to purchasing  
12 replacement runners, the economic justification for the project should be reviewed  
13 in light of the information gained during this performance test and hydrologic  
14 assessment.