

1 Q. C-5; Volume I, Tab 2: Replace Interior Coating on Surge Tank 3. On page 4 Hydro  
2 states: *"In particular, the interior coating on the riser is in a deteriorated condition*  
3 *with corrosion evident. A complete coating failure on the interior of the surge tank*  
4 *has left the metal exposed and corroded."* However, on page A8 the Hatch report  
5 states: *"The internal inspection revealed that the coating system on the interior of*  
6 *the tank roof, shell, bowl and riser is in good condition with some minor localized*  
7 *breakdown."*

8 Has Hydro evaluated other options, such as refurbishing localized areas of coating  
9 breakdown?

10

11

12 A. Please refer to Hydro's response to IC-NLH-016.