

1 Q. Recommendation #2 on page A9 the Hatch report states: *"Complete a detailed*
2 *assessment of the tank interior coating system with a certified NACE inspector*
3 *within the next two years. Implement a program whereby a detailed inspection of*
4 *the tank interior coating system is performed every four to six years, coordinating*
5 *with planned unit outages. During each assessment, refurbish localized areas of*
6 *coating breakdown on the interior of the tank shell, bowl and riser and apply a*
7 *compatible coating system."*

8 Has Hydro completed a detailed assessment of the interior coating system with a
9 certified NACE inspector? If yes, please provide a copy of assessment report. If no,
10 why not?

11

12

13 A. Please refer to Hydro's response to IC-NLH-019.