

1    Q.    **Project C-58: Replace Insulators - TL203**

2            With reference to the 2015 replacement of insulators, provide all available statistics  
3            of service interruptions attributable to insulator failures since 2014.

4

5    A.    Since 2014, TL 203 experienced one service interruption due to an insulator pin  
6            failure. The line tripped on January 12<sup>th</sup>, 2014 on structure 163 causing insulator  
7            string separation on the left phase conductor. No customer outage was caused by  
8            the line trip.