

1 Q. Could this work have been spread out over more than one year for each of
2 Unit 1 and 2?

3

4

5 A. No, the nature of this type of failure is that it cannot be repaired. The
6 affected waterwall tubes have to be physically removed from the boiler and
7 replaced with new fabricated waterwall panels. Replacement of all the
8 affected tubes must be completed before the unit returns to service such that
9 reliability is not compromised. Only Unit 2 was affected by this failure.