

1 **Re Page B-30:**

2 Q. What changes have occurred to bedrock on the trail since its first use so as
3 to require this upgrade?

4

5

6 A. The ongoing use of the trail over the years has caused the erosion of
7 overburden along steep sections. This deterioration of overburden, in turn,
8 has resulted in exposed bedrock at various locations.