Page 1 of 1

1	Re:	Page	B-89	Replace	I ine	Camp	98 -	TI	-228
1	116.	Iaye	D-03.	1/chiace		Callib	<i>3</i> 0 –		-220

Q. How was this building in particular, as well as the other survival buildings, reported in Hydro's process review "to match financial records with equivalent records" (Transcript, Oct 16, 2003, p.65/10)?

5

7 A. This building, as well as other survival buildings, was placed in the asset
8 hierarchy within the transmission line where they were located. If there was
9 a financial record and an equipment record, they were combined into one.