

1 **Re: Page B-92, Upgrade Line TL-212, \$463,700**

2 Q. What changes, if any, have occurred since construction that has caused the
3 line to not meet the standard clearance of 22 feet?

4

5

6 A. The line has experienced higher loads than the original design ice load. The
7 higher loads stretch the conductor causing it to sag nearer the ground,
8 causing flashovers and posing a danger to the general public.