1	Q.	B-5, Upgrade Stack Breeching Unit 1, \$3,553,400
2		If the gap in information results from a decrease in the amount of inspection and
3		maintenance work over this period, please explain how this relates to normal
4		inspection and maintenance procedures in effect over that period of time.
5		
6		
7	A.	This proposal has been revised. Please refer to the report attached to Hydro's
8		letter dated October 26, 2010. Please note that references to information that is
9		responsive to each of the Information Requests can be found in the footnotes of
10		this report.