

1 Q. **Re: B-68, Condition Assessment & Life Extension Phase 2 - \$1,215,700 in 2012**

2 Please provide particulars in relation to “*The increasing number of unexpected*  
3 *equipment failures in recent years...*” set out at page 9 of the Hydro report  
4 *Condition Assessment and Life Extension.*

5

6

7 A. Please see the table below.

Description	Unit / Common System	Year
Turbine Nozzle Block – Partition Failure*	1	2009
Marine Terminal Fender	Common	2008
Forced Draft Fan – Dorsal Fin Failure	1	2007
Turbine Nozzle Block –Partition Failure	2	2007
Boiler Water Wall Panel – Tube Leak	2	2006
Stage 1 Diesel Turbo-Charger Failure	Common	2005
Boiler Superheater Replacement	2	2007
Boiler Superheater Replacement	1	2008

8 \*Annual boroscope inspections were performed on the nozzle block on Unit 1 with  
9 the intention to replace it during the 2012 major overhaul of the unit. The  
10 inspection in 2009 however indicated that it had unexpectedly failed and needed to  
11 be replaced immediately.