

1 Q. Re: Refurbishment of the Fuel Oil Storage Facility

2 At Appendix A, page 10, an external inspection was recommended to be completed
3 in 2008. Has the subsequent inspection been completed?
4

5

6 A. The primary concern with the tank is internal floor plate corrosion. To conduct this

7 inspection will require a complete tank cleaning exercise in advance of any formal

8 inspections. It is noted, however, that once each 12-hour shift, a shift operator

9 conducts a routine external inspection of the tank farm, focused primarily on the

10 presence of any oil in the vicinity of the pipelines, tanks, and associated valves. Any

11 anomaly is documented, and corrective action initiated. A formal third party

12 external inspection has not been completed.