

1 Q. **Unit 1 Stack Breeching:** How much of the \$321,000 maintenance cost incurred in
2 2006 (\$320,000 of which was for "Corrective Maintenance") was attributable to the
3 replacement of the floor in Unit 1 in 2006 (as referred to at page B-77 of the Alstom
4 report, Tab B of Hydro's July 2011 report)?

5

6

7 A. Out of the \$321,000 maintenance cost incurred in 2006, \$30,000 was attributable
8 to the replacement of the Unit 1 east side breeching floor.