

1 Q. Refurbishment of the Fuel Oil Storage Facility, Holyrood Thermal Generating
2 Station

3 If an external inspection of Tank #3 was undertaken during or after 2008, please
4 provide a summary of the report. If not, please provide the reasons why not.

5

6

7 A. A documented external inspection, by a consultant or testing agency, has not been
8 undertaken since 2008, as the primary the corrosion issues for Tank 3 are internal
9 to the tank. However, visual non-documented walk-by inspections have taken place
10 by Hydro operations staff. See also the response to CA-NLH-6.