

1 Q. **Refurbishment of the Fuel Oil Storage Facility, Holyrood Thermal Generating**  
2 **Station**

3 In Appendix A of the report, page 10 of 248, AITEC recommends that NLH “Open  
4 the tank in six (6) years, clean the tank and establish a short-term corrosion rate,  
5 and if necessary do a complete floor scan and a full API inspection, or at least  
6 establish when a full internal is to be done.” What action has NLH taken as a result  
7 of this recommendation?

8  
9  
10 A. Hydro has not opened the tank within six years to perform the work described in  
11 the recommendation made in the AITEC report which was prepared in November  
12 2003. Hydro agrees that the scope of work needs to be completed but deferred  
13 completing it to 2011 for reasons as discussed in the response to PUB-NLH-20.