

Undertaking 77

Page 69, line 7 to Page 70, line 13

Undertake to provide a consultative opinion from the OEM (if one exists in writing) on the transformer prior to the failure.

For Sunnyside T1, there was no consultative opinion from the OEM prior to the failure in January 2014.