

1 Q. Has Hydro determined the cause of the "unacceptable moisture levels" in the
2 transformer oil of T5? If so, please provide details regarding the cause of the
3 unacceptable moisture levels (as well as any reports, documents or analysis
4 outlining such cause).

5

6

7 A. Please refer to Hydro's response to CA-NLH-5.