

1     Q.     Please provide any reports, analysis and documentation available relating to the  
2            extent and cost of work required to rehabilitate T5 to have it placed back in service.

3

4

5     A.     There are no reports, analysis, or documentation relating to the extent and cost of  
6            work required to rehabilitate T5 to have it placed back in service because Hydro has  
7            yet to determine whether any such work is required. Work will be required only if  
8            transformer T5 contains excessive moisture. Refer to CA-NLH-5 for details on  
9            Hydro's plan to determine the moisture level in transformer T5.