

1 Q. Please restate Table 7 at page 11 of Hydro's Report on Insulator Replacement (TL-
2 201 to TL-203) to show the cost of replacing only those insulators on TL-201
3 showing corrosion at present.

4

5

6 A. Table 7 provides the five-year maintenance history for TL-201, in addition to
7 proposed expenditures for 2014. The preventive and corrective maintenance costs
8 shown in the table for 2014 are primarily related to the cost of
9 inspection/refurbishment of wood pole structures and components under the
10 Wood Pole Line Management (WPLM). There is a small expenditure (\$3,000)
11 proposed and included for the replacement of insulators. These insulators will now
12 be replaced under this TL-201/TL-203 insulator replacement proposal.