

1 Q. On page 17 of the Upgrade Transmission Line Corridor Report it is stated that 3 high
2 inertia synchronous condensers located at Soldiers Pond and operation of Holyrood
3 Thermal Generating Station Unit 3 in a synchronous condenser mode are adequate
4 for stability purposes and that all other MVAR requirements can be supplied
5 through either static sources or a low inertia rotating unit. Please confirm that this
6 continues to be Hydro's position.

7

8

9 A. Please see Hydro's response to CA-NLH-003.