

1    Q.    Further to PUB-NLH-29, Appendix B shows the results for cases 1 to 10 while  
2           footnote 12 on page 34 of the Upgrade Transmission Line Corridor Report states  
3           analysis was performed on only 9 cases. Please explain this discrepancy.

4

5

6    A.    The footnote is incorrect. Transient stability analysis was performed for ten of the  
7           eleven base cases.